
APPENDIX C

RECORDKEEPING

COPIES OF COMPLETED FORMS

EDUCATIONAL BROCHURES



Remember: Only Rain Goes Down The Drain



Revised 10/01/2008



U.S. General Se Administration

rices

U.S. General Services Administration Public Building Services

DFC Environmental
Programs Group
Building 41, Room 240
PO Box 25546
Denver, CO 80225-0546

Protecting Storm Water

at the

Denver Federal Center



For More Information:

303-236-8000

John Kleinschmidt

303-236-2858

Bill Fieselman 303-236-2516

enver Federal Center Stori. Nater Program

tion's greatest threat to clean ing. Polluted runoff* is the nafor swimming, fishing, and drinktreated into water bodies we use storm sewer system flows unstream. Anything that enters a tem or directly into a lake or other pollutants. Storm water can flow into a storm drain sysdebris, chemicals, dirt, and lots, lawns, sidewalks, picking up Rainwater flows over parking

other community uses Platte River supports fisheries, and and a storm water pond on the DFC as ricultural Ditch, Downing Reservoir water sources. Downstream , the Wildlife use McIntyre Gulch, the Agthen flows into the Platte River. converges with Lakewood Gulch and McIntyre Gulch flows across the Denver Federal Center (DFC) and

to rivers, lakes, or oceans. pollution from agricultural lands, urban streets, parking lots and suburban lawns, and transports it *Polluted runoff is precipitation that captures

> not degrade water quality. be taken to ensure that DFC runoff does and downstream water supplies. Care must Platte River compromise water, wildlife, fish taminants that enter the Gulch and the directly into McIntyre Gulch. Any DFC conand snow melt from drain inlets and flows The DFC's storm drain system collects rain

permit requirements. storm water quality and comply with the measures the DFC will take to protect storm water management plan outlines what charge storm water into McIntyre Gulch. A Storm Sewer System (MS4) permit to dis-The DFC has an EPA Municipal Separate

Platte River connection to McIntyre Gulch and the of the storm drain system and its direct on the campus to increase public awareness placed distinct markers near storm drains construction sediments. The DFC has also sure that storm drains are protected from construction site inspection program, to enmanagement plan, which includes an active The DFC has implemented a storm water

home, and at play. caused by things we do everyday at work, at Water pollution is often unintentional. It's

Water Pollution Facts:

- over an acre of water surface A pint of used motor oil can expand
- A gallon of gasoline can contaminate 750,000 gallons of water.
- contains heavy metals. - Antifreeze is poisonous to wildlife and
- ger fish and other wildlife. - Trash can plug storm drains and endan-

How You Can Help:

- into a nearby storm drain bent material, don't rinse spills Make repairs as soon as possible. Check vehicles for leaks & spills. -Clean up spilled fluids with absor-
- outdoors. Clean paint brushes in a sink, not
- waste collection program. through a household hazardous Properly dispose of excess paints



U.S. General Services Administration

Bill Fieselman 303-236-2858 John Kleinschmidt 303-236-8000 For More Information:

BROCHURE DEVELOPMENT AND DISTRIBUTION FORM(S)

BROCHURE DEVELOPMENT AND DISTRIBUTION FORM

Date of Brochure	Development/Update: 10/1/2	2008
Name of Person(s	s) Who Developed the Brochure: <u>Bob</u>	Yelvin, Bill Fieselman, John
Name of Person(s	s) Who Developed the Brochure: <u>Bob</u> s) Who Distributed the Brochure: <u>Bill</u> elow, list dates the brochure was distributed	ieselman, John Kleinschm
distributed (e.g., o	distributed to each agency, distributed throu opy of the brochure distributed with this co	ugh building managers, etc.). Ensure
DATE DELIVERED	METHOD OF DISTRIBUTION	NUMBER OF BROCHURES DISTRIBUTED
8/28/14	Farmers Market	N 10
5/1/15	Earth Day Expo	5
9/30-12/7/15	Electronic Distribution	13+
/	,	4.20
	,	
	*	
	N	
*		
	V .	
* -		. 4
		H 1
1		N

Timestamp	Username
9/30/2015 11:40:54	9/30/2015 11:40:54 stephanie.downs@gsa.gov
10/20/2015 11:50:12	10/20/2015 11:50:12 patrick.campbell@gsa.gov
11/10/2015 12:12:46	11/10/2015 12:12:46 nicci.pagano@gsa.gov
11/10/2015 12:24:31	11/10/2015 12:24:31 charlie.carruth@gsa.gov
11/10/2015 12:33:33	11/10/2015 12:33:33 charles.turman@gsa.gov
11/10/2015 13:56:20	11/10/2015 13:56:20 william.fieselman@gsa.gov
11/11/2015 8:39:23	11/11/2015 8:39:23 john.kleinschmidt@gsa.gov
11/12/2015 8:06:41	11/12/2015 8:06:41 jamie.perdomo@gsa.gov
11/12/2015 9:11:56	11/12/2015 9:11:56 patrick.campbell@gsa.gov
11/12/2015 10:36:03	11/12/2015 10:36:03 denice.pacheco@gsa.gov
11/16/2015 7:57:42	11/16/2015 7:57:42 denice.pacheco@gsa.gov
11/17/2015 8:29:29	11/17/2015 8:29:29 jamie.perdomo@gsa.gov
12/7/2015 14:22:38	12/7/2015 14:22:38 jennifer.martinez@gsa.gov

Flectronic Distribution List

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
6/26/2015	1031, previosly exesting Good / Fair condition
6/26/2015	1030, Previosly existing, Gast contiston
6/26/2015	1004, Placed Steneil
6/26/2015	1003, Reflace Stancil
6/26/2015	1023, Reciously existing, Foir consiston
6/2/6/2015	1000 poriously existing, bad/Fair contorion
6/26/2015	1025, Reflaced Etencil
6/26/2015	1027, Placed Stancil
6/26/2015	1028, Raplaces etancil
6/26/2015	1041, reviously existing, & tais consistion
6/26/2016	1026, previously existing, book tail condition
6/26/2015	10/B, Mach Stancil
6/26/2018	1016, Praviously Exterior, and condition
Grafrons	1015 provided axisting, boat Fair considion
6/26/2015	1013, Placed Steneil
6/26/2015	10th, Previously aristions, book contition
6/26/2015	Old, jourious (existing, Good Fair consistion
6/26/2015	1011, freviously existing, bood combition
6/20/2015	4001, Previously spiriting, book/taid coubition
6/14 2015	30/6/ feplace stead (
6/26/2015	3017, Replaced Stancil
6/26/2015	1009, tellaced stencil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
0/26/2015	1007, Replaced Stancil
6/26/2015	1008, Existing, Fait condition
6/26/2015	2018, Placed stance
	309, Places steneil
	3023, Places Stancil
	3024, Place Stancil
	3027, Placed stancil
	3028, Placed Stance
	3036, Reflaced Steadil
	3037, Duplaced Steacil
	2035, Reglaced Steneil
	300 by Hace Stance
	2007, Replace standel
	3009, Place Stence
	3013, Raplaced Stance
	3014, Place & Stencil
	3010, Placed Stener 1
	3038, Places strucil
	3039, leflace stance)
	5004 Roplace Stancil
	Boo3, Raflacod stanci
	5002, Places Stancil

Date(s) of initial storm drain/catchment basin survey:

DATE	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
STENCILED	
6/26/2015	500/ Placed Steneil
6/26/2015	3040, Existing, ook contition
1/1/2015	2039, Existing, bool/Fair couliston
7/1/2015	1032, Existing, Lood Condition
71/2015	1034; Places stencil
	1036, Placed Stancil
	1037, Black Stencil
	1638, Places stancil
	accoss from 1038, & laced & Tancil
	1056 jaxisting, bool/Fair conbidion
	1055, Existing, Good /Fair condition
	1039, Do good floce to Attach stoneil
	1057, Places Stancil
	1058, Existing, wood condition
	1059, Exiting Good Conlitted
	1053, Exictive, had condition
	4052, Replaced Staveil
	1060 j Placed Stanci (1 Doain Vamage)
	1061, Placed Stencil
	1062, No place To Attach Stencil
	adjucent 4055, Existing, book condition
	4091, Places Stoneil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
7/1/2015	1063, Replaced Stencil
7/1/2015	1044, Haced staneil
7/1/2015	1048, Replaced Steveil
1//	1047, Nogood place to Attach Etencil
	1043, No good flace To Attach Stancil
	1045, NO good place to Attach stancil
	1044, Places strucil
	actoriant 1046, Places stance!
	1040, hellack stancil
	10ell, Reflacel Strace!
	1042, Raplaced Steneil
	1051 No good Place To Attach Stavail
	1052, NO god Place To Attach Stancil
	1050, No good place to Attach Strace
	1053, Placed Steneil
	1054, Placed STancil
	4050, Existing / good condition
	4049, Existing/ good condition
	4046 Place Stone
	4047, Exiciling/ good condition
and the second s	4044 Existly I good condition
	4050, Existing / good consistion

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
Thois	4059 (existing/ good condition
111	4067, Existing 1 good Lodition
	4056, Placed Stencil
	4060, Place Stencil
	4051, NO 400 & Place To & Flack stancil
	Cioux, flaced stened
	4045, Lephol Stancil
	yors, Places steamil
	2009, Existing (Good Condition
	2010, Placed stancil
	2006, Existing / book consistion
	2007, Existing/ good contition
	2003, Existing/ good consistion
	2004, Existing good consistion
	Abjacet SSENDOOI good was in
	Zetb, Existing, god codition
	2085, Existing, Fair condition
	2088, Existing Fair Condition Place Stancil
	2083, Existing / good Cardition
	2084, Existing/good condition
	2087, Existing / good condition
anima a singular and a singular and a singular deposit of the singular and a sing	2089/Existing / good condition

Date(s) of initial storm drain/catchment basin survey:

DATE	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN	
STENCILED		
7/1/2015	2090, Exiting, good considion	
1/1/2015	2002 /Existing/ cook condition	
7/1/2015	2001, Existion I good condition	
7/9/2015	2055, 4 xisting/ good fair condition	
7/9/2015	2054, Existing, Fair consistion	
//	7053, Existing, good continion	
	2051, Existily, good consition	
	2052, Places (Stener (
	7059, Existing, Fair coulition	
	2060, Existing book/Fait consistion (shote	5
	2071, Replace Danci	
	7072, Raplaced Stance	
	2095, Place Stancil	
	2097, Replaced STERCI	
	2096, Replace & Stance	
	Suthat 2092 , planed Stener	
	209 Zy Existing good contilion	
	wof roar, Places stencil.	
	E of 2092 Existing, good condition	
	2091, Place Stever	
	2103, Existing Fair condition	
	2081, Replace & Stancel	

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
Talans	
7/9/2015	2058, Stencilin Place, good/Fair Condition
	2070, Placed Stancil
<u> </u>	2073, Stencilia Place, good / Faid consistion
	2069, Placed Stancil
and the second	Wof 2069, NO good place To Attach stencil
	2068, Placed Stance
	2066, No good place To ATTach stever!
	2067, Place & Stancil
	2065, Placed steneil
	2057, Placed Stancil
	2056, Placed Stancil
	7015, Stancil in place, good contetion
	2014, Stencilin place, good consistion
	2017, Stancil in place, good condition
<u></u>	2018, Replaced Stancil
	2019, Stancil in place, good todat consistion
	2016, Reflaced Stancil
)	rosi, Raplact stare!
	2020, Stancil in place, good condition
	2022, stercil in place, good condition
	2013, Stencilia place, good condition
	2024, Placed Stancil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
7/9/2015	2025, Place Stancil
	206 2026, Placed Stencil
	7078, Steacilia flace, good condition
	2027, Stancilla place, good/Fair condition
	7074, Placed STRACE
	7030, Placed Stencil
	2032, Stewell for place, good Consition
	2031, Stencil in place, good condition
	2033, Placed Stancil
	2034, Staveil in place, good consistion
	2035, Stancilia fluce, good Fair consistion
	20412, Stancel in place, good contition
	2043, Stancil in place, 4006 condition
	roully steacilin place, good condition
	rous, Place & Staveil
	roll, Replaced Stever!
	2047, Replaced Staveil
	2018, Placed Strucil
<u> </u>	2019, Stened in place, good consistion
	2050, Replaced stancil
	2101, Replaced Stencil
	Sot 2101, Placed stereil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
8/7/205	4066, Stancilia place, good consition
	Sof 4061, Replaced Stancil
	4063, Stancilia place, good condition
	4062, Stencil in place, good condition
\ <u>\</u>	4064, Placet stencil
	4065, Stancilia place, good condition
	4066, Place & Stancil
	4067, Stancilin place, good condition
	4068, Stancilin place, good consistion
	4070, Placed Stancil
	4069, Stancillaplace, good condition
	4031, Stencil in place, good condition
	4032, Steacilia place, good consition
	4035, Place & Stancil
	4034, stencilin place, Fair consistion
	4033, Stencil in place, youl Fair conlition
	& of 4025, NO good place To Attach strucil
	4025, Nogood place To attach stencil
	41008, Place & Steneil
	4002, Placed Stencil
	4003, Placed stencil
	4004, Place & STencil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
8/7/2015	4005, Places Staneil
	4006, stancilin place, good contition
	4007, steacil in place, good consistion
	Sof 11005, Fancilin place, Fair consision
<u> </u>	2nd s of 1005, Places stencil
7/7/7015	4067 stancilia place, good consission
7/7/2015	UOGS, Stancil in place, good condition
7/9/2015	2082, Steveil in place, good condition
	2080, Placed Stancil
	2077 Stancil in place, Fair condition
	2078, stencil in place, Fair consition
	2079, Stancil in place, Fair condition
	2076, Placed stencil
	2075, Replaced Stancil
	2074 Replaced Steveil
	2012, Placed stencil
	2013, Placed Steneil
	2011, Placed Stencil
<u></u>	2008, Placed Stancil
)	2005, Stancil in placed, good condition
	7063, NO good place to Attach stencil
(2064, Placet Stancil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
8/1/2015	4024, wo good Plase to Attach Fence!
8/7/2015	4022, No goodplace to Attack steveil
3/7/2015	4021, NO good place to Attach sterce! 4020, place & Stancil 4019, No good place to Attach Stancil
2/7/2015	4020/ Place & Stancil
	4019, 100 good Olece To Attach Stence
	4018, Place stencil
	4011, Stracilia place/ Fair condition
	4016, Replaced Stancil
	4019, Placed STERRIL
	4011 Hood Sorned
	4012, Replace Stance
	4013, Stracil in place - good / Fait Condition
	yord flace Steacil
	4009, Placed Strace
	4040, po good place to stack Deucil
<u> </u>	Freder for 4040, Placed STRACE
<u> </u>	400, No good Place to Attach Social
	Abjacant 4010, Raplace = Teneil
	4036, No god Place To attach stence (
	4038, STEU CIL in place, Fair condition
	4039, Stered in place Replaced Strancil

H of 13

STORM DRAIN STENCILING FORM

Date(s) of initial storm drain/catchment basin survey:

DATE	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
STENCILED	S of 4005,
8/7/2015	30 So Sot Place & Stancil
(((4th SOF 4005, Placed Steveil,
	3032, Francitio place - Reflaced Stance
	3031, Replaced Strucil
	3029, Stancil la Place - 6005/Faircoulition
\	3030 Steacil in flace - book/Fair condition
8/14/15	
	4029, Staney Raffered
	4028, Place & Stancel
	4026, Francil in place / bood Fair condition
	4027, Stancil in flact, book contidione
	2017, Places Stanail
	3013, Réplaced stereil
	Saf 3043, Placed Stancil
	3041, Replaced strangel
	3033, Replaced STaveil
	3034, Stancil in place, book contition
	5010, Placed Souncil
	5011, Placed stancil
	502, No good Place To Attach stancil
	500, Raflact Staneil
	5008, Replaces Starcil

Date(s) of initial storm drain/catchment basin survey:

DATE STENCILED	LOCATION/ID # OF STORM DRAIN/CATCHMENT BASIN
8/4/15	5013, Talaplona manhola
1	5007, Placed Staned 1
(inlet suffert of 13710, House Stance
	5066, Places 50 ansi)
	3003, Pluces Stavell
	3004, Steveil in place, good condition E of 3004, Re place & steveil
	E of 3004, Re place & stancel
	3002, Replaces Stancel
	3001, Place & Staveil
	2057, Do good flace To Attach Street
	2036, Places Stangel
	2038, Place Steneil
<u> </u>	2041/ Stancilia place, book/ Fair contition
	2040, someil in place, Good condition
7/01	2039, Stancilinglace, Faid wasition
7/99 2015	
<u> </u>	7098, Placed Stancil
	5.06 2098, Placed Stancil
	WOF 2098, NO good place To Attach stencil
agreen commente, de la septembre, e andré actual de la constant de la constant de la constant de la constant de	2099, Placed Stancil
The approximate programmer and an extension of the second of the control of the c	

STORM SEWER INLET INSPECTION FORMS

Storm Water Inlet Inspections

Mater Inlet #	Sediment (Y/N)		enver Federa		My 2015
1001	THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OWNER, THE OWNER OWNER OF THE OWNER, O	Sea. Depth	Sed. Type	Inlet Type	Comments
1001	NO			Gurb Grate	
	Not Found				
1003	NO			Curb Grate	
1004	NO		market COOPER	GRATE	
1005	No			Curb Grate	
1006	NO			GRATE	
1007	NO		•	Curb Grate	
1008	Yes	31	WATER	Curb Grate	
1009	NO			Curb Grate	
1010	NO			Curb Grate	
1011	Not on Map				
1012	NO		_	Curb Grate	
1013	NO			Curb Grate	
1014	NO	_		GRATE	
1015	NO	_		Curb Grate	
1016	NO			Curb Grate	
1017	NO			GRATE	
1018	No	_		Curb Grate	
1019	NO			GRATE	ę
1020	YES	2"	WATER	GRATE	
1021	YES	(11)	DIRT	GRATE	
1022	No			Curb Grate	
1023	NO			Curb Grate	
1024	NO		Machine Contract Cont	GRATE	
1025	NO			CurbGrate	
1026	NO		accession and a second	Curb Grate	B 56 W (SE corner of circle driv
1027	NO			Curb Grate	bor on GE CONNEL 21 CLICKE ALLO
1028	YES	3'	WATER	Curb Grate	
1029	YES	(")	LEAVES	Curb Grate	100 1/10
1030	NO		LEFIVES	Curb Grate	BS6 W (NE corner of circle driv
1031	YES	41	WATER	Curb Grate	
1032	YES	איכ	WATER	(16)	
1033	NO	0/	WI TEK	Curb Grate	
1034	NO			GRATE	
1035	Not Found			GATIE	
1036	NO			Curb Grate	
1037	NO				
1038	YES	3"	WATER	Curb Grate	
1039	YES	21		Curb Grate	
1040	YES	3'	WATER	GRATE	
1041	YES	119	WATER	Curb Grate	
1042	NO		WATER	Curb Grate	
1043	NO			Curb Grate	
1044	YES	2"	WATER	GRATE	
	Not Found	- CX	WIIER	GRATE	

Water Inlet #	Sediment (Y/N)		Sed. Type	Inlet Type	Comments
1046	Not Found			The second secon	
1047	YES	3"	WATER	GRATE	
1048	YES	(1)	DIRT	Curb Grate	
1049	YES	()	DIRT	Curb Grate	
1050	NO			Curb Grate	
1051	NO			GRATE	
1052	NO			GRATE	
1053	NO	_		GRATE	On the roof of B.45.
1054	NO			GRATE	On the roof of B.45.
1055	YES	21	WATER	Curb Grate	DATHER BOT DE B. 13.
1056	No			Curb Grate	
1057	NO			Curb Grate	
1058	YES	2"	WATER	(urb Grate	
1059	YES	1"	LEAVES	Curb Grate	
1060	YES	111	LEAVES	Curb Grate	
1061	No		LEHVES	GRATE	1 11: 11 1 0
1062	Not Found			GNITE	Located in the turfarea.
1063	YES	21	WATER	Curb Grate	
2001	NO	0	WHIEK	GRATE	
2002	NO			GRATE	
2003	YES	, 11	LEAVES	Curb Grate	
2004	YES	21	LEAVES	Curb Grate	
2005	YES	21	WATER	GRATE	
2006	NO		WHIER	Curb Grate	
2007	NO				
2008	YES	12	LEAVES	GRATE GRATE	
2009	NO		CLHVIS	Curb Grate	
2010	YES	117	LEAVES	Curb Grate	
2011	YES	111	LEAVES	GRATE	
2012	YES	2'	LEAVES	Curb Grate	
2013	YES	111	WATER	GRATE	di agranda di
2014	NO		WPIEK	Curb Grate	
2015	NO		St. College Co	Curb Grate	
2016	NO			Curb Grate	
2017	NO			GRATE	
2018	NO			GRATE	
2019	NO			GRATE	
2020	NO		-	Curb Grate	
2021	NO	-		Curb Grate	
2022	NO			Curb Grate	
2023	YES	111	LEAVES	Curb Grate	
2024	YES	a"	WATER	GRATE	
2025	YES	111	WATER	GRATE	
2026	No		WITTER	GRATE	
2027	YES	10	LEAVES	CurbGrate	

Water Inlet #	Sediment (Y/N)	Sed. Depth	Sed. Type	Inlet Type	Comments
2028	YES	111	LEAVES	Curb Grate	
2029	NO			GRATE	
2030	YES	211	2" LEAVES		
2031	No			GRATE Curb Grate	
2032	YES	31	LEAVES	Curb Grate	
2033	No		LLAVES	Curb Grate	
2034	YES	31	WATER	GRATE	
2035	NO		CONTER		
2036	NO			Curb Grate GRATE	
2037	NO			GRATE	
2038	YES	21	WATER		
2039	YES	11/	WATER	GRATE	
2040	YES	31	WATER	Curb	
2041	YES	4"	WATER	Curb	
2042	NO	٦	WHIEK	Curb	
2043	No			Curb Grate	
2044	NO			Curb Grate	
2045	YES	11	LEAVES	GRATE	
2046	NO		LLAVES	Curb Grate	
2047	YES	21	154456	Curb Grate	
2048	YES	21	LEAVES	Curb Grate	
2049	YES		LEAVES	Curb Grate	
2050	NO	2	DIRT	Curb Grate	
2051	NO		******	Curb Grate	
2052	NO			Curb Grate	
2053	NO			(urb Grate	
2054	NO			GRATE	
2055	NO			Curb Grate	
2056	NO		***************************************	Curb Grate	
2057	No		Principal and the second	GRATE	
2058	NO		Butterfolking .	Curb Grate	
2059	YES	-,,,,,	1 = 11 = 2	Curb Grate	
2060		311	LEAVES	Curb Grate	
2061	YES I	2	WATER	Curb Grate	
2062	Not Found Not Found				
2062	YES	71	0727		
2064	YES	21	DIRT	GRATE	
2065	YES	211	DIRT	GRATE	1/2 covered with felt.
2066	NO	2"	WATER	GRATE	
2067	NO			GRATE	
2068	NO			GRATE	
2069	NO			Curb Grate	
2070	NO			GRATE	
2071		711		GRATE	
2072	YES	211	DIRT	GRATE	
~~12	YES	<u> </u>	LEAVES	GRATE	

Water Inlet #	Sediment (Y/N)	Sed. Dep	oth	Sed. Type	Inlet Type	Comments
2073	No		dwinus;		Curb Grate	Commence
2074	No	-			Curb Grate	
2075	No				Curb Grate	
2076	YES	211		WATER	Curb Grate	
2077	NO			DO TEX	Curb Grate	
2078	NO			, posterior and a serior and a		
2079	NO			and a second	Curb Grate	
2080	YES	21"		WATER	Curb Grate	
2081	NO			WATER	GRATE	, , , , , , , , , , , , , , , , , , , ,
2082	YES	211		LEAVES	Curb Grate	
2083	YES			LEAVES	Curb Grate	
2084	YES		,	LEAVES	Curb Grate	
2085	NO	~		LEHVES	Curb Grate	
2086	YES	, (1	_	1505	Curb Grate	
2087	No		-	LEAVES	Curb Grate	
2087	YES	, ()		1 50,000	GRATE	
2089			-	LEAVES	GRATE	
2090	NO		\dashv	gen-them.	GRATE	
2091	No		\dashv	and the state of t	GRATE	
2092			\dashv	MATERIAL PROPERTY.		
2092	NO		-	***************************************	Curb	
2093	NO		-			NE corner of B.15
2094	YES	311	-	Water	Curb	
2095	NO NO		\dashv		Curb Grate	
2097			4	Aggrandore Chicago	GRATE	
2097	NO		-		Curb Grate	
2099	NO		\dashv	_action and a	GRATE	Several more at B.16 eastside,
2100	No		-		GRATE	
3001	No		4		GRATE	
3002	No		-		Cutb Grate	Not Part of the
3002	NO		4		Curb Grate	NOT Part of the
3003	YES	NA	4	DIRT	Curb Grate	Denver Federal Center
	YES	N/A	4	DIRT	Curb Grate	
3005	No		\dashv	manufacture.	CurbInlet	1 West of Routt
3006	NO		1		CurbInlet	Anymore. Stret.
3007	NO		4		Curb Grate	
3008	NO		4		CurbGrate	
3009	NO		4		Curb Grate	
3010	NO		4		Curb Grate	
3011	No		4		GRATE	
3012	NO		\perp		GRATE	
3013	NO		4		Curb Grate	
3014	No		\perp		Curb Grate	
3015	NO		_		GRATE	
3016	YES	211	_	WATER	Curb Grate	
3017	NO				Curb Grate	

Water Inlet #	Sediment (Y/N)	Sed. Depth	Sed. Type	Inlet Type	Comments
30 1 8	NO			CurbGrate	COTTINCIES
3019	NO			Curb Grate	
3020	YES	211	DIRT	GRATE	
3021	YES	31	DIRT	GRATE	
3022	YES	211	DIRT	GRATE	
3023	No	• ~	DINI		White the state of
3024	NO			Curb Grate	
3025	NO			Curb Grate	1000
3026	NO			GRATE	
3027	NO		A STATE OF THE STA	GRATE	
3028	NO			Curb Grate	
3029	NO	- = T		Curb Grate	
3030	YES	21	154	Curb Grate	AND
3031	NO	_ d	LEAVES	Curb Grate	
3032			manufacture surviy	Curb Grate	13
3033	NO		wingspace Tricking	Curb Grate	
3034	NO		U.Sec.	Curb Grate	
	NO			Curb Grate	
3035	YES	211	DIRT	Curb Inlet	
3036	NO		garantina de la companya del companya de la companya del companya de la companya	(urb Inlet	
3037	NO		Accompliance .	Curb Inlet	
3038	No		with the same of t	Curb Inlet	
3039	NO			Curb Grate	
3040	No			Curb Grate	
3041	NO		equestions.)	Curb Grate	
3042	No		Marine Contract	GRATE	
3043	NO			Curb Grate	
4001	NO			Curb Grate	
4002	YES	4111	WATER	GRATE	
4003	YES	5"	WATER	GRATE	
4004	YES	211	WATER	GRATE	
4005	YES	311	WATER	GRATE	
4006	No			Curb Grate	The state of the s
4007	NO	_	-	Curb Grate	
4008	No	_		Curb Grate	
4009	YES	24	LEAVES	Curb Grate	
4010	No			GRATE	
4011	No			GRATE	
4012	NO			Curb Grate	
4013	NO			Curb Grate	
4014	YES	311	WATER	GRATE	
4015	No			Curb Grate	
4016	NO		-	Curb Grate	
4017	NO		Approximations	Curb Grate	
4018	YES	2"	LEAVES	GRATE	
4019	YES	111	DIRT	GRATE	

Water Inlet #	Sediment (Y/N)	Sed. Depth	Sed. Type	Inlet Type	Comments
4020	YES	2"	DIRT	GRATE	
4021	YES	21	DIRT	GRATE	
4022			GRATE		
4023	YES	3"	LEAVES	GRATE	
4024	NO		ALTER CONTRACT	GRATE	
4025	NO			GRATE	
4026	YES	31	WATER	Curb Grate	
4027	YES	5"	WATER	Curb Grate	3
4028	No		*Orthogrammy	GRATE	
4029	No		· ·	(urb Grate	
4030	NO			GRATE	
4031	NO		20000000	Curb Grate	
4032	NO	-	-	Curb Grate	
4033	NO			Curb Grate	
4034	NO			22, 5 0, 4.1	
4035	YES	211	LEAVES	GRATE	
4036	NO			GRATE	
4037	NO	-	ADDRESS OF THE PARTY OF THE PAR	Curb Grate	
4038	NO			GRATE	
4039	NO		with the same of t	GRATE	
4040	NO			GRATE	
4041	NO			GRATE	
4042	No			GRATE	
4043	YES	ا (د	DIRT	GRATE	
4044	No		***************************************	(urb Grate	
4045	NO			Curb Grate	
4046	YES	1/1	LEAVES	GRATE	WrongonMep
4047	YES	21	DIRT	Curb Grate	Wrong on Map
4048	YES	41	WATER	GRATE	
4049	YES	1 11	LEAVES	Curb Grate	
4050	NO			(urb Grate	
4051	YES	211	DIRT	GRATE	
4052	YES	41"	DIRT	Curb Grate	
4053	No			Curb Grate	
4054	No		·	GRATE	
4055	No			GRATE	
4056	No			GRATE	
4057	NO			Curb Grate	
4058	YES	3"	DIRT	Curb Grate	
4059	No		Beautif Property and	Curb Grate	
4060	NO			GRATE	
4061	NO			Curb Grate	
4062	NO			Curb Grate	
4063	YES	211	LEAVES	Curb Grate	
4064	No			GRATE	

				ouriec.	
Water Inlet #	Sediment (Y/N)	Sed. Depth	Sed. Type	Inlet Type	Comments
4065	No			Curb Grate	A CONTRACTOR OF THE PROPERTY O
4066	No		дания	GRATE	
4067	YES	2"	LEAVES	(urb Grate	
4068	YES	21	LEAVES	Curb Grate	
4069	NO			Curb Grate	
-5000-4070	NO			Can D Oreje	
5001	No			Curb Inlet	
5002	NO		***************************************	Curb Inlet	
5003	No			Curb Inlet	
5004	NO			CurbInlet	
5005	NO .		2.000	GRATE	
5006	YES	21	DIRT	CurbInlet	Outside Gate 7
5007	YES	311	DIRT	GRATE	Daiside Care 1
5008	YES	111	DIRT	Curb Inlet	
5009	No			Curb Inlet	
5010	NO			GRATE	
5011	YES	21	DIRT	GRATE	
5012	YES	211	LEAVES	GRATE	



SUBMITTAL GSA.govMail-Storm Sewer Inlet Inspections SCHEDULE FOR THE INSPECTION OF STORMWATER FEATURES CONTRACT 6.5,4.19, 4. d Bruce Johnson - 8PSDPD < bruced.johnson@gsa.gov>

Storm Sewer Inlet Inspections

York, Cinde <Cinde.York@davey.com>

Tue, Jan 21, 2014 at 12:57 PM

To: "bruced.johnson@gsa.gov" <bruced.johnson@gsa.gov>

Cc: "william.fieselman@gsa.gov" <william.fieselman@gsa.gov>, "Sharkey, Kevin" <Kevin.Sharkey@davey.com>

Bruce,

Attached is the inspection form from our storm sewer inlet inspections. I apologize for not sending you a schedule of when we begin this process. I simply began the process and forgot that I was supposed to inform you prior. Inspections began on 1/06/14 and were completed on 1/17/14.

This should take care of the following submittals:

C.5.4.19.4.e

C.5.4.19.4.c

Best Regards,

Cinde York

Quality Control Inspector/ACM

The Davey Tree Expert Company

One Denver Federal Center Bldg 45, E-1

Lakewood, CO 80225

PO Box 260608

Denver, CO 80226

Cinde.York@davey.com

Cell: 719-499-3799



DFC Storm Sewer Inlet Inspections 2014.pdf 2758K

WaterInlet#	Sediment (Y/N)	Sed.Depth	Sed.Type	InletType	Comments
1001	No			Curto Grati	
1002	NOT FOUND		_	Cors Grace	
1003	No	-,		Curhamto	
1004	YES	1'2"	H20		
1005	No		-	GOATE	2
1006	YES	1/2"	SOUT PINE NEGES	Curb Grate	
1007	Va	211	MENERES		
1007	YES	~ /	Scot	Cub Ginto	
1008	YES	30+	H ² 0	Ci 200 Groats	
1010	No.	111	Rocks	Curto Grate	
1010	YES V Vec	1 11	LEAVES	Curbfinate	
1012	153) 17	LEAVES	C. YO GOATE	
1012	YES	م ا	LEAVES	Cuch GRATE	
	No	_		Curb Grate	
1014	No.	0.5	GOOT	GRATE	
1015	- YES	3	SOOT LEAVES	Curb Grate	***************************************
1016	Yes	2"	LEAVES	curp hunte	
1017	YES	1/4"	LEAVES	CHRATE	B. C.
1018	YES	2"	LEAVES	Curb Grate	J
1019	No		-	GINATE	a *
1020	YES	5"	HZO SOCT DICT LEAVES	(1DATE	
1021	YES	1/4"	LEAVES	GIRATE	
1022	YES	.3"	LEAVES	Curp Grate	
1023	YES	3"	LEAVES	Curb Grate	
1024	No		_	Grate	
1025	YES	2"	LEAVES	Curh Groto	
1026	YES	1ft.	LEAVES	Curb Girate	*
1027	Yes	141	H20	Curb Grats	
1028	YES	2"	LEAVES	Curb Grate	
1029	YES 1	5"	SOOT UEAVES	Curb Grato	
1030	YES	111	SOOT LEAVES	Curb Grata	
1031	YES	4"	H20		
1032	YFS	101	H20 500T	Cirlo GRATE	5
1033	Ves	4"		Curb Carato	
1034	YES	4"		GOATE	7/20
1035	Nat Four				
1036	Ves	3"	LEAUES	Ourh GRAFE	
1037	Vec	2"	000	Cuch CARAGE	
1038	VES	8.	H20	Curto Grace	
1039	YES	14	H ² O	CIDATE	<u></u>
1040	YES	5"	1	Cuch GRATE	
1041	YES	4"	H20 5000	Curb Gnate	3
1042	Vés	5"	^	Curb Firet	
1043	YES	11.	Rock Soot	GOATE	
1044	Yes	5"	H20	CIDATE	
1045	Not FOUND			THE STATE OF THE S	
	····				

Wa	aterinlet#	Sediment (Y/N)		Sed.Type	InletType	Comments
	1047	YES.	4"	H2U 500T H2O, 500T LFAVES H2O, 500T LFAVES	GRATE	
	1048	VES	1"	HZO, SCOT LEAVES	CUHD GRAFE	
	1049	YES	}''	HZO, SOOT	Cuido Grati	
	1050	YES	2"	H ² O	Curharato	
	1051	YES	7"	H2h	GRATE	·
	1052	YES	3"	H 20 SOOT	GRATE	
	1053	YES	1"	H20	CHRATE	
10	1054	YES	11	H ² O	CINATE	
i.	1055	YES	3"	HZO, SOOT YEAVES	Cush CARACTE	
	1056	Yes	3"	H20	Curblicate	
	1057	VES	Ü"	H ² O	Curb GDATE	
	1058	3.1	Ü"	HZO	Curbagate	
	1059	YES V==	5"			
	1060	YES Vec	- Un	LEAVES	CURPHONE	Harris Carolina Carolina
	1061	YES		LEAVES		METAL BACKLUG IS ON DRAIN IS BROKE
	1061	No			GRATE	
	1062	No	9.	H°O, Soot	CIRATE	10
	2001	YFS	6"	H20	_	
		1F.5	<u> </u>	Smt	Grati	
	2002	No	1	,	- 10 -	
	2003	YES	174.	LEAVES	Cum Gross	
	2004	Y53	1#	LEAVES	Curb/Grate	
	2005	YES	18+	# H.70	Grato	
	2006	YES	2"	LEAVES	Curly Grote	
	2007	YES	3"	LEAVES	Grate	
	2008	YES	411	SCOT, LEAVES	Grato	
	2009	Yes	4"	LEAVES	Curh/Grato	
	20010	YES	8"	LEAVES	Custo Grate	
	2011	YES	5"	H20, SCOT	GIDATE	
	2012	YES	5"	LEAVES	GUODGIOATE	
	2013	YES	9"	SOUT	GOATE	
	2014	YES	311	LEAVES	Curplante	
	2015	VES	2."	LEAVES	Curplifyoto	
	2016	ŸES	1/2"	LEAVES	Curplanate	
	2017	YES	["	SOOT	Grate	
	2018	YES	[1]	SOOT	Caroto	
	2019	VES	1/2"	SOOT	Grato	
	2020	Yas	2"	LEAVES	Curb Grota	
	2021	YES	2"	LEAVES	Curb Ginto	
	2022	YES	3"	LEAVES	Curb Grate	
	2023	YES	.3"	LEAVES	Curb Grato	
	2024	VES	1/2"	Scor	Grate	1
	2025	Ass.	7"	H ² O	Create	
	2026	VES	3"	Scot	Grate	0
	2027	YES	in .	LEAVES	Purb Grato	
			21.		1 -	
	2028	YES.	7.	LEAVES	Costs Grate	1

DOM

[Wees also be the	Cadin art (V/N)	Cad Dasth	cal mea	InletType	Comments	
WaterInlet#	Sediment (Y/N)	Sed.Depth		CONTRACTOR CONTRACTOR	Comments	
2030	VES	1	LEGVES	Grate		
2031	YES.	31	LEAVES	Curb Grate		
2032	Y55		LEAVES	Curb Grato		
	YES	5"	LEAVES	Curb Canto		
2034	158	14	H ₃ 0	Grate		
2035	No	5"	H20, Lectures	Curb Grato	- requiring	main st west
2036	YES		Dist	Grote	Drain is changed. (OF STAND	MONE Guard shack
2037	No	11	H 28, Myd,	GRATE		
2038	YES	LJ."	H20/Leas	1-INATE		
2039	VES .	1	Dirt	Curb		
2040	YES	\(\mathcal{G}''\)	H20, Craves	Curh		
2041	YES	1, 4,,	Leaves	Curb	Very Deep Appx. 15: (SE of	. W side of 1 st st
2042	Yiss	3"	H ² 0	Cumplinate	Very Deep Appx. 15: SE of	B1d9 20
2043	YES	1011	LEAUES	Cudhate		
2044	YES	TOO DEEP TO	H ² O	CARATE		
2045	YES	2"	LEAVES	Cumplinata		
2046	Yes	4"	CEAUES	Cuplarate		
2047	YES	["	LEAVES	curh/Grat		
2048	YES	1	LEAVES	Curlifornate		
2049	YES	2"	LEAVES	Curpliants	4	900
2050	YES	10.	LEAVES	Curlimate		
2051	Yes	2"	LEAVES	Culturate		
2052	VES	5"	LEAUES: Troish	Curliante	W(
2053	Yes	40	HZO, LEAVES, Mind	Carnte		
2054	YES	2"	H30 Mendles	Cumlimite		
2055	YES	111.	LEAVES,	Curhlante		
2056	YES	144	Diet	BAR GOATE		
2057	No		_	Cubfiniti		
2058	YES	2"	LEAVES	Cush Growin		
2059	YES	32"	LEAVES	0.01/1(am t)		1 TOND
2060	YES	5.Ft.	H20	Corp Grita	Dain is closed (Style o	chut at at)
2061	Nor Facus	1.740	11-0	DANGARE	Drain is chaged (ronerete	
2062	NOT FOUND				:	
2063	Viss FOMD	1/4"	LEAVES	Girato		
2064	VES	1''.	Dirt	Grate	Groto was covered with FEUT.	open area SIE corner 3rd + cantar.
2065	YES	14	SOOT, LEAVES	Grate	CHULD WITH CHUCKE WITH LEGI.	STANISCO M
2066	Vēs	14	Scot, Leaves	Grate		
2067	VES VES	Uit Uit	H20,500	Gran		
2068	V No		11 01000	C L C L		
2069		1020 1"	LEAUES,	Cub Grote		
2070	YES.	1/2		Grate		
2071	YES	型北	(EAVES)	Grate		
2071	YES		SOLI UEAVES	Carata		
	YES	3"	SCOT	Givete		
2073	YES		LEAVES	Curpficato		
2074	No	10	1-0	CUASCOUTE		
2075	YES	1 1,,	LEAVES	Curb GRATE	<u>L</u>	

. .

WaterInlet#	Sediment (Y/N)	Sed.Depth	Sed.Type	InletType	Comments
2076	YES	"	500T H20	CUMOGRAME	
2077	YES	2."	LEAVES	Curblante	
2078	YES	111	(FAMES	Curhlanto	
2079	YES	2"	LEAVES	Curb/Grate	
2080	Yes	3"	LEAVES	Grate	
2081	YES	2."	POX	Cuntierate	
2082	YES	3"	LEAVES,	Curb/firate	
2083	YES	3"	LEAVES	Curpliarate	
2084	VES	70"	LEAVES	Curh/Grate	
2085	YES	11	放H20	Curplinate	
2086	YES	4"	LEAVES: Dirt	Curl broto	
2087	YES	2''	H20	Carato	
2088	YES	5"	HZO, LEAVES	Grato	
2089	YES	1/2"	H20	Grate	
2090	No	¥		Grote	
2091	Yes	5"	H20, LEAUES		
2092	Yes	2"	LEAVES	Curb	
2093	NOT ON MAP				
2094	YES	し"	HZO, LEAVES MUID CEAVES	Curlo	5
2095	YES	3"	Mud	Cut Grate	
2096 .	YES	2"	Mud	CHRATE	Curh broken above grate
2097	YES	3"	MUN)	Cuto/tone	·
2098	No	~		ſ	
2099	No	-			
2100	YES	1 1/2"	Publics, Leaves	Grate	
2101	YES	1/2"	LEAUTS	Curpfirate	
3001	Yes	1"	Scot	CUHOGOATE	
3002	YES	111	Scor	CONDGOATE	
3003	YES	1"	LEAVES HZO	CUID GOATE	
3004	YES	2"	LEAVES	CUMPTERATE	
3005	YES	3"	l s	CurbINET	
3006	YES	ļi	LEAVES	Curb INLET	
3007	YES	3"	GLAVES	CUAD GOATE	
3008	YES	3"	SUST LEAUES	CUAD BOATE	
3009 3010	No	4"		Cuts GrATTE	
3010	VES	~	LEAVES	Curb GOATE	
3012	No VES	5"	1000	GIDATE	
3013	No		Soot	Curtofinate	
3014	YES	3"	LEAVES	Curb Grote	
3015	YEK	5"	H ² O	Grate	
3016	YES	5"	500T H20	Gilum bat	P
3017	YES	1/2	SOUT	Curp Grate	
3018	NO		2001	Curbanate	
3019	No	_		Curbarate	
3020	YES	3"	Soct	GNATE	
	1 1 - 3		17001	I WINTE	L

.

WaterInlet#	Sediment (Y/N)	Sed.Depth	Sed.Type	InletType	Comments
3021	YES	3"	500T	CHRATE	6 9
3022	YES	4"	SOOT	Grote	14)
3023	Yes) it -	LEAVES	Curp Grate	
3024	YRS	1"	(EAVES	Cento Groto	
3025	NO			GOATE	
3026	Yes	[11	H20	LIDATE	
3027	No			Cudolanate	
3028	No	·		Cush Grate	
3029	YES	2."	SOCT	Curl Grate	
3030	YES	2,"	LEAVES	Curofivate	
3031	YES	3"	LEAVES	Cumbinte	¥
3032	VES.	3"	1 FAVES	CurbGrati	
3033	No		- CEAULO	Cupfinte	
3034	YES	1:1 -	LEAJES	Cirplanto	
3035	VES.	2."		CURD INCET	5
3036	YES	2"	LEAVES HZO VEAVES	PURD TALLET	
3037	YES	4"	LEAVES	CURDINCET	
3038	No.	9	LAVES	Chich TWET	
3039	No.		2-27-2	Cubarata	
3040	No			Curplinato	
3041	No				
3042	YES	2."	HZO	Curb GINATE	
3043	No	6,5	SCOT	\$	
4001	VES	2."	SOOT	CUASGINATE	Concrete around drain is brok
4002		<u>&"</u>	H ² D		CONCLETE GLOUDE GLATIN IS DED
4003	YES Vac	164	H ² O	COATE	
4004	YES V=c	1 Ft.	1720, SCOT	CHRATE	
4005	VES.	911	H ² O	GNATE	
4006	YES		SOOT	GOATE	
4007	YES	3"	LEAVES LEAVES	Curb Grate	
4007	YES		-	Curto Grate	
4009	No.			Cuch Grote	
4009	No			Curb GOATE	
4010	No			GRATE	
4011	NO			Grate	
4012	No	110	 , 	Curb Grate	
4013	YES		H20	Cuto Gente	
4014	YES	14	H20 S001	CIDATE	
	No) ii	1 = 1	Curb Grato	
4016	YES.		LEAVES 500	Cup GOATE	
4017	YES	2"	1500F LEAVES	Curb Comto	
4018	YES	2"	LEAVES	Avate	
4019	YES	3"	LEAVES	GOATE	
4020	No	 	1120	GRATE	
4021	YES		H20	GRATE	
4022	VES	Magl"	H ² 0	CIDATE	
4023	NO		-	GRATE	

WaterInlet#	Sediment (Y/N)	Sed.Depth	Sed.Type	InletType	Comments
4024	No	especial action of the second	- anaroustrages & Toolak	GNATE	
4025	No	٠.٥	_	GRATE	
4026	YES	8"	H20	Purto GRATE	
4027	Yes	8"	HZO	CUMOFUME	
4028	YES	1"	H20	GOATE	
4029	YES	8"	H20	CLAD GRATE	
4030	YES	2"	LEAVES	CIDATE	
4031	YES	111	LEAVES	CUM GDATE	
4032	YES	14	1 FAIRS	CUMO GIDATE	
4033	YES	5"	H20	Cush Grate	
4034	YES	44	SOOT, HZD LEAVES		
4035	YES	3"	Scat	Grato	•
4036	YES	111	LEAVES	GNATE	
4037	YES] it	LEAVES H20	Cub Grato	
4038	YES	6 "	H20 560T	GRATE	
4039	Yes	5"	Mud	CARATE	
4040	YES	1"	Mud	HIDATE	
4041	YES	1	H20	CHOATE	*
4042	No	. 1		GRATE	
4043	VES	= T	SOUT	CHATE	·
4044	YES	3"	500T USAVES	Cuito GOATE	
4045	YES	3"	LEAVES	CurloGrato	
4046	No	, ,		GOATE	
4047	YES	3"	LEAVES	Curto Girato	
4048	YES	2"	Soor	GRATE	
4049	YES	i ii	Soot Hours	Cush Grato	
4050	YES	14	SOCT WAS	GARRE	
4051	YES	4"	SOOT. LEAVES	amais Groto	
4052	Yes	3"	LEAVES	Curb Grate	
4053	YES	2"	LEAVES	Curlo Grote	
4054	VES	2"	SOCT LEAVES	CIDATE	
4055	No			GRATE	
4056	YES] it	LEAVES	GDATE	
4057	YES	3"	LEAVES	Curb GOATE	
4058	Yes	1"	LEAVESSON	Curp Greate	
4059	Yes	1/2"	LEAVES	Curb First	
4060	NO	-	-	CIDATE	
4061	YES	2"	LEAVES	Curb Grote	
4062	YES	3"	LEAVES	Curb Grate	
4063	YES	2"	LEAVES	Curb Grate	
4064	YES	2"	H20	Covati	
4065	YES	2"	LEAVES	Curb Grate	
4066	YES		SOOT	Grote	
4067	VES	C		Curb Grate	
4068	Y,ES	6"		Curb Grate	
4069	YES	3"	LEAVES	Cuido GINATE	

· •

WaterInlet#	Sediment (Y/N)	Sed.Depth	Sed.Type	InletType	Comments
5000	Not FOUND	OU	MAP		
5001	No	~_		CANTINET	
5002	No	~	_	CUMOTAKET	•
5003	NO-	·		CLIPOTNIET	
5004	NO			PURTNET	
5005	No	_		CIPATE	
5006	YES	2"	Soor	Curb TNIFT	
5007	Viss	4"	SOUT	GOATE.	
5008	YES	1'6"	H20	Curb FULET	
5009	YES	it	LEAVES	CURPTULET	
5010	No	parties.		C-DATE	
5011	YES	2"	300T H20	GRATE	
5012	YES	3"	SOUT	GILATE	

HOTLINE NUMBER CHANGES

HOTLINE CONTACT RECORD FORMS

HOTLINE CONTACT RECORD FORM

Date: 7	Time Call Received:	
Name of C	aller:	Phone Number:
Name of P	erson Receiving the Call:	
		*
-		
GSA EPG	Person Following up on Call:	
	*	
Further Ac	tion Needed (Y/N)? If Yes, describ	e
Date(s) Fu	rther Action Taken:	

Hone to date - 2/5/16

SWMP REVIEW ROSTER(S)



SWMP REVIEW ROSTER

Name of Person(s) Distributing the SWMP: Bill Freselman

If comments are received, maintain a record of comments and response(s) to comments with this Plan.

COMMENTS? ² Y/N	the on 12/01/2011. IMP began following /25/2013. Annual ME was performed in port (due to EPA on	None. Sull reviewd, No comments Sulm " " " " " " " " " " " " " " " " " " "
PHONE	decame effect of the Swith Annual Re	313-236-2516
AGENCY	En 184 Permit) by 65 A & EPA and was fru 4 Permit) of th	65.4-contractor
NAME OF RECIPIENT	2-ROYZOOY (i.d. and revision (Ly of the Ms. Ms. es through th	Sill Freschuan
METHOD OF DELIVERY ¹	The of with	H "
DATE	NPOES Per Developmen the effect review (per conjunction	1/50/14 2/15/16

 $^{^1}$ Note whether the Plan was delivered via hard copy (HC) or via e-mail (E). 2 If comments are received, note whether a follow-up to comments is required.

RECORD OF CHANGES MADE TO THE STORM SEWER MAP

None to date - 1/30/14

11 11 - 2/10/15

11 11 11 - 2/5/16

ILLICIT CONNECTION CORRECTION FORM(S)



ILLICIT CONNECTION CORRECTION FORM

METHOD OF CORRECTION AND APPLICABLE DETAILS ¹	See project documentation too.	Bldg 45 investigations	13184 56 11	3 td Street Storm sever line	6th 11 11 11				
LOCATION OF CONNECTION						1			
DATE		5	я						

¹ Note whether the illicit connection was plugged, rerouted, if the activity was discontinued or moved. Also note where the connection was rerouted to or where the activity was moved to.

DRY-WEATHER SURVEY FORM(S)

ımary
y Sur
Surve
ther §
I Dry Wea
Jal Dr
Ann
DFC:
ıtfalls.
er Outfa
n Sew
h Storrr
Gulch
ntvre
Mc

2	McIntyre Guidh Storm Sewer Outrails, DFC.	- 1							
Outfall no.	Physical location	Year	Survey	Ave flow rate gals/min	Dissolved O2 mg/l	Conductivit Temp.	Temp. (deg.C)	E	comments
1401 IT3001C	Downing Becannoir Southwest corner inlet	2008	6/18/2008	0.88	6	_	15.12	7.94	
		2009	8/24/2009	0.88	10.9	1.57	19	6.98	
	As aulch ages under Kipling St. inside fence	2008	6/18/2008						unable to find this outfall
02OU 19016C	Nth bank	2009	8/24/2009	flow is a tric	8/24/2009 flow is a trickle, not enough to sample	ugh to samp	9		
		2008	8/15/2008	10 32	α	0.736	14 73	7 97	
020UT1005C	Halfway between Kipling St & 1st St crossing,	2008	6/18/2008	12	6	1.03		7.85	captured approx 90% of flow
	Nul Dallh	2009	8/24/2009	10	10			8.1	
		2007	7/31/2007	2.5	7.28	0.222	16.42	7.96	
020UT1003C	By Main St Bridge, W side North Bank, end of 3rd St	2008	6/18/2008 no flow	no flow					
		5009	8/24/2009 no flow	no flow	as and				
	:	2006	6/15/2006	0.55	8.31	0.415	41		8.12 v. slow drip, high algae content
020UT1001C	West of aqueduct, North bank. 42 glameter pipe	2008	6/18/2008	0.19	9:36	0.399	11.86	7.78	
		5000	8/24/2009	0.33	9.8	0.029	15.1	8.52	
		2006	6/15/2006	1.77	90.6	1.3	14.41	8.35	
020UT1011C	Bridge to howhere, w side hun bank in wing wall, 42" diameter pipe	2008	6/18/2008	2.4	9.3	1.24	14.26	7.96	
	•	2009	8/24/2009	1.5	9.2	1.31	16.5	8.44	
OSCOUTION	aradian of any interest and a problem	2008	6/18/2008 damp but no flow	damp but r	no flow				
000000	and or box carded alled to bush	2009	8/24/2009 no flow	no flow					
		2006	6/15/2006	1.64	8.15	1.2	14.46	8.09	
020UT1009C	End of 6th St projection to Gulch. 48" diameter pine	2008	6/18/2008	26	9.36	0.399	11.86		7.78 captured approx 90% of flow
		2009	8/24/2009	36	8.54	0.94	17.8		
09011T1047C	7th Ct Bridge Courth eide	2008	6/18/2008	2.5	7.6	1.35	18.6	7.8	
		2009	8/24/2009	10	9.18	1.27	18.5	8.43	
CEUUUTIOOO	Northwest corner of Rida 710	2008	6/18/2008 no flow	no flow					
		2009	8/24/2009 no flow	no flow					
0201IT40450	West side Blda 810 due N from generator blda	2008	6/18/2008	6/18/2008 no measurable flow	able flow				
2500110020	West side bidg o to, due in it titli getterator bidg								

McIntyre Gulch Storm Sewer Outfalls - Denver Federal Center: Annual Dry Weather Survey - August 2011

Outfall no.	Physical location	Year	Survey	Avg Flow Rate	Dissolved O2 Conductivity ms/cm	Conductivity mS/cm	Temperature (degrees C)	H	Salinity %	Turbidity	Comments
140UT3001C	Inlet to Downing Reservoir at southwest corner of reservoir	2011	8/18/2011	10+	8.19	1.34	17.3	7.96	0.06	-	
020UT9016C	North bank of McIntyre Gulch, inside of the fence just before it goes under Kipling St	2011	8/18/2011								Flow is a trickle, not enough to sample. See *1 below
020UT1005C	North bank of McIntyre Gulch, haifway between Kipling St & Main Avenue crossing	2011	8/18/2011	9	7.91	1.25	15	7.87	0.05	108	
020UT1003C	North bank of McIntyre Gulch, west of Main St bridge, south end of 3rd St projection	2011	8/18/2011				1				No flow. No outfall, Outfall has been destroyed during recent reconfiguration of McIntyre Gulch
02OUT1001C	North bank of McIntyre Gulch, west of Agricultural Ditch aqueduct, 42" diameter concrete pipe	2011	8/18/2011	0.25	7.15	0.316	15.4	7.94	0.01	9	
020UT1011C	Outfall is in the north wing wall of the 5th St bridge (Bridge to Nowhere), west side of bridge, north bank of McIntyre Gulch, 42" diameter pipe	2011	8/18/2011	S	7.71	1.44	16.1	8.17	0.06	0	
020UT9008C	Inside of north box culvert under 5th St bridge (Bridge to Nowhere), north wall	2011	8/18/2011			- /					No flow
020UT1009C	North bank of McIntyre Gulch, south end of 6th St projection, 48" diameter pipe	2011	8/18/2011	30	6.07	1.46	17.4	8.26	0.06	0	This is the discharge outfall for the Bldg 52 groundwater treatment system
020UT1017C	Southwest corner of intersection of 7th St bridge and McIntyre Gulch, south side of gulch. Drains marshy area along west side of 7th St, north of Bldg 710	2011	8/18/2011	3.3	8.39	0.91	20.6	8.08	0.04	ო	
09OUT0003C	South bank of McIntyre Gulch, north of the northwest corner of Bldg 710	2011	8/18/2011								No flow
020UT1015C	West side Bldg 810, due N from generator bldg	2011	8/18/2011								Outfall has been reconfigured during recent re-channelization of McIntyre Gulch in this area

^{*1 -} Took instrument readings from McIntyre Gulch flow where outfall would discharge too: dissolved oxygen 8.94 mg/L, conductivity 0.730 mS/cm, temperature 15.8 C, pH 8.12, salinity 0.03%, turbidity 4

5	
7	
lst	
혌	
7	
-	
6	
ا خ	
اچ	
-	
죔	
ā	
۶I	
3	
F	
=	ĺ
2	
듼	
₹	
McIntyre Gulch Storm Sewer Outfalls - Denver Federal Center: Annual Dry Weather Survey - August 201	
욛	ı
e	ı
O	ı
g	ı
ē	۱
ě	ı
Ŀ	ı
è	ı
Ē	ŀ
ŏ	۱
•	l
=	l
哲	ı
E	ļ
5	
Ve.	
è	
S	
E	
9	
S	١
당	
E	١
O	١
Je J	
E	1
S	١
Σ	١
	1
	١

Outfall no.	Physical location	Year	Survey	Avg Flow Rate gals/min	Dissolved O2	Conductivity mS/cm	Temperature (degrees C)	H	Salinity %	Turbidity	Comments
mid-stream	Mointyre Gulch where it leaves the DFC on the east side. Measurement taken from mid-stream.	2012	8/31/2012	AA	7.87	1.03	15.6	7.68	0.04	ဖ	
400T3001C	Inlet to Downing Reservoir at southwest corner of reservoir	2012	8/31/2012	1.5	8.53	1.94	17.8	7.98	0.09	69	
02011790160	North bank of McIntyre Gulch, inside of the fence just before it goes under Kipling St	2012	8/31/2012	trickle					E		Not enough flow to measure. This appears to be a seep rather than an outfall.
020UT1005C	North bank of McIntyre Gulch, halfway between Kipling St & Main Avenue crossing	2012	8/31/2012	6	7.33	2.03	17	7.92	0.09	89	
020UT1003C	North bank of McIntyre Guich, west of Main St bridge, south end of 3rd St projection	2012	8/31/2012	¥	¥ Z	N A	NA	Ą	Ā	Ą	Outfall destroyed. See note *1 below.
020UT1001C	North bank of McIntyre Gulch west of Agricultural Ditch aqueduct, 42" diameter concrete pipe	2012	8/31/2012	0.5	8.27	0.8	14.7	8.15	0.03	-	
020UT1011C	Outfall is in the north wing wall of the 5th St. bridge (Bridge to Nowhere), west side of bridge, north bank of Mcintyre Gulch, 42" diameter pipe	2012	8/31/2012	2	7.64	1.48	15.6	8.04	90.0	en	
020UT9008C	Inside of north box culvert under 5th St bridge (Bridge to Nowhere), north wall	2012	8/31/2012	AN	NA AN	¥.	NA	NA	A	A	No flow
020UT1009C	North bank of McIntyre Gulch, south end of 6th St projection, 48" diameter pipe	2012	8/31/2012	18	6.91	1.59	18.2	7.88	0.07	0	
020UT1017C	Southwest corner of intersection of 7th St bridge and McIntyre Guich, south side of guich. Drains marshy area along west side of 7th St, north of Bldd 710	2012	8/31/2012	NA	AN	NA	ν. V	ž	\$	ž	No flow
DE0001T0000	South bank of McIntyre Guich, north of the northwest corner of Bida 710	2012	8/31/2012	AN	NA	NA	NA	Ā	A A	Ą	No flow
0.0001	North side of McIntyre Gulich between Joppa and BLM storage yards, north of the northeast	2012	8/31/2012	ž	ž	₹ Z	ž	¥	ž	ă	No flow
020UT1014C	Outfall is north of Door N-28 of Bidg 810.	2012	8/31/2012		NA	NA AN	ĄV	Ž Ž	ž	Ą	Outfall discharges the stormwater retention basin located between Door N-28 and Metnyre Guich. The stormwater retention basin does not dischage unless water is deep enough in the basin to reach the drain, approximately 16-inches deep.
OSMATIONS	Outtail is north of Door N-25 Of Bidg 810, at the	2012	8/31/2012	\$	1 //1 n	p. 114			10 0		Outfail dischage is at the same level as the water in Morntyra Gulch, therafore it is not possible to determine if how is dischariging from the outfail. The outcand is connected to a manhole 29 ft to the southwest. The manhole is subsequently connected, via manhole approximately 20 feet north of the emergency generator structure on the north side of Blog 810 (see outfail 02OUT1015C comments).
Capation	Disectly rorth of Door N-15 of Bidg 810 and	2012	8/31/2012		ž	, e	Ą	ž	¥	A N	Marhole has a trickle in it. Flow enters the manhole from the south, makes a 90° turn to the east and east the randward screen sort east in an underground pipe, to another manhole. Flow then exits this manhole to the northward and discharges to cutfall IQ20IT1013C. Flow exiting the IQ20IT1015C manhole does not discharge directly to an outfall on Mointyre Gulch (see comments for outfall 020UT1013C).
3000ETU000	Directly north of Doors N-9 and N-10 of Bidg 810.	2012								14	Outfall dischage is at the same level as the water in McIntyre Guich, therefore it is not possible to determine if flow is discharging from the outfall. There is no manhole between outfall and Bldg 810.
Outfall Door N-5 N-7		2012		N A	NA	NA	NA	Ą	NA	¥ Z	No flow
020UT1016C		2012	8/31/2012	Y.	V.	NA	AA	Ą	¥.	ž	Manhole between outfall and Bldg 810 also dry (manhole is 14 ft north of the north edge of the pavement).
	Mointyre Guich where it enters the DFC on the	6,500	8/31/2012	ΔN		878	47.5	7 5.4	2	2	

^{*1-} During the summer of 2011, the banks of McIntyre Guich were reconfigured where the guich crosses Main Ave. This work was performed as part of the DFC-wide Utilitity infrastructure Project (UIP).
During this work, Outfall No. 0220/11035C was descroyed, it is believed that this outfall was part of the old DFC storm sewer system and was no longer operational. Therefore, it was not replaced.
Flow had not been noted at this outfall during the Annual Dry Weather Survey since July of 2007.

McIntyre Gulch Storm Sewer Outfalls - Denver Federal Center: Annual Dry Weather Survey - November 2013

					. 11.4						×		-28 and water is	one it is not somected to a via nocy comments).	a 90° turn to n northeast inole does ufall	ore it is not nhole		ne north	
Comments			This is a seep not an outfall. This location is not longer monitored.		Ouffall destroyed. See note *1 below.								Outfall discharges the stormwater retention basin located between Door N-28 and McIntyre Gulch. The stormwater retention basin does not dischage unless water is deep enough in the basin to reach the drain, approximately 18-inches deep.	Outfall dischage is at the same level as the water in McIntyre Gulch, therefore it is not possible to determine if flow is discharging from the outfall. The outfall is connected to a manhole 29 ft. to the southwest. The manhole is subsequently connected, via underground pipe, to a manhole approximately 20 feet north of the emergency generator structure on the north side of Bldg 810 (see outfall 020UT1015C comments).	Manhole has a trickle in it. Flow enters the manhole from the south, makes a 90° furn to the east and exits the manhole to the east. The flow travels 306ft east in an underground pipe, to another manhole. Flow then exits this manhole to the northeast and dischages to outfall 020UT1013C. Flow exiting the 020UT1015C manhole does not dischage directly to an outfall on Mointyre Gulch (see comments for outfall 020UT1013C).	Outfall dischage is at the same level as the water in McIntyre Guich, therefore it is not possible to determine if flow is discharging from the outfall. There is no manhole between outfall and Bidg 810.		Manhole between outfall and Bldg 810 also dry (manhole is 14 ft north of the north edge of the pavement).	
2			This is		Outfall		rii	No flow		No flow	No flow	No flow	Outfall McInty deep e	Outfall possib manho underg	Manho the ea underg and dis not dis	Outfall possib betwee	No flow	Manho	
Turbidity	0.0	0.0	, Lange	0.2	Ž Š	3.4	1.2	Ž Š	0.0	¥ X	N A	N A	¥ ¥	A A	ž		N	¥	2.6
Salinity %	0.1	0.1		0.1	¥.	0.1	0.1	¥	0.1	Ą	NA	A A	Å	Ą	ž	814 2	NA	Ā	0.1
Ŧ	7.73	7.73		7.64	NA	7.88	7.79	¥	77.7	¥	NA	NA	NA A	NA N	A N		NA	N A	7.81
Temperature (degrees C)	8.28	13.97		13.28	N A	9.23	12.26	NA	14.35	NA A	NA	NA	NA	ĄZ	ď Z		NA	NA	8.98
	1.65	2.15	8 9 19	1.77	Ą	1.24	1.56	Ą	1.53	Ą	NA	NA	Ą	NA NA	ž		NA	NA	1.50
Dissolved O2 Conductivity mg/l	5.88	5.63		4.97	N A	6.18	5.53	NA A	5.34	Ϋ́	NA	NA A	NA AN	¥ Z	₹ Z	AN A	NA	NA	6.84
Avg Flow Rate gals/min	NA	<1.0	trickle	10	Ą	~ 1.0		NA A	16	Ą	NA	A A	Ą	¥.	ď Z	Y.	NA	NA	NA
Survey	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013	11/3/2013
Year	2013	2013	2013	2013	2013	2013	2013	2013	2013	2013	2013	2013	2013	2013	2013		2013	2013	
Physical location	McIntyre Gulch where it leaves the DFC on the east side. Measurement taken from mid-stream.	Inlet to Downing Reservoir at southwest corner of reservoir	North bank of McIntyre Gulch, inside of the fence just before it goes under Kipling St	North bank of McIntyre Gulch, halfway between Kipling St & Main Avenue crossing	North bank of McIntyre Gulch, west of Main St bridge, south end of 3rd St projection	North bank of McIntyre Gulch, west of Agricultural Ditch aqueduct, 42" diameter concrete pipe	Outfall is in the north wing wall of the 5th St bridge (Bridge to Nowhere), west side of bridge, north bank of Mcintyre Guich, 42" diameter pipe	Inside of north box culvert under 5th St bridge (Bridge to Nowhere), north wall	North bank of McIntyre Gulch, south end of 6th St projection, 48" diameter pipe	Southwest corner of intersection of 7th St bridge and Michtyre Gulch, south side of gulch. Drains marshy area along west side of 7th St, north of Bilog 710	South bank of McIntyre Gulch, north of the northwest corner of Bldg 710	North side of McIntyre Gulch between Joppa and BLM storage yards, north of the northeast comer of Bldg 810.	Outfall is north of Door N-28 of Bldg 810.	Ouffall is north of Door N-25 Of Bidg 810, at the waters edge.	Directly north of Door N-15 of Bldg 810 and generator bldg.	Directly north of Doors N-9 and N-10 of Bidg. 810.	Outfall directly north from a point halfway 7 between Door N-5 and N-7 of Bldg 810.	Directly north of of a point halfway between Door N-3 and N-5 of Bldg 810.	McIntyre Gulch where it enters the DFC on the west side. Measurement taken from midstream.
Outfall no.	mid-stream	140UT3001C	02OUT9016C	020UT1005C	020UT1003C	020UT1001C	020UT1011C	020UT9008C	02OUT1009C	020UT1017C	09OUT0003C	120UT1001C	020UT1014C	020UT1013C	020UT1015C	020UT9002F	Outfall Door N-5 N-7	020UT1016C	mid-stream

^{*1 -} During the summer of 2011, the banks of McIntyre Guich were reconfigured where the guich crosses Main Ave. This work was performed as part of the DFC-wide Utilitity Infrastructure Project (UIP).

During this work, Outfall No. 02OUT1003C was destroyed. It is believed that this outfall was part of the old DFC storm sewer system and was no longer operational. Therefore, it was not replaced. Flow had not been noted at this outfall during the Annual Dry Weather Survey since Juliy of 2007.

McIntyre Gulch Storm Sewer Outfalls - Denver Federal Center: Annual Dry Weather Survey - September 2014

Last Precipitation - 9/22/14

Reference Photo		Ouffall-14OUT3001C		Outfall-02OUT1005C		Outfall-02OUT1001C	Outfall-02OUT1011C	Outfall-020UT9008C		Daily Outfall-020UT1009C				>	d to d	d d to d	y drot drot drot mot mot	A d to d to b d	A droit asst and droit and droit asst asst and droit asst asst and droit asst and droit and droit asst asst and droit asst asst and droit asst asst asst asst asst asst asst as
Comments			This is a seep not an outfall. This location is not longer monitored.		Ouffall destroyed. See note *1 below.				r treatment system.	Average Flow Rate of discharge on 9/26/14 - 7.86 gpm	Average Flow Rate of discharge on 9/20/14 - 7,88 gpm No flow	Avenage Flow Rate of discharge on 9/20/14 • 7.86 gpm. No flow No flow No flow	Average Flow Rate of discharge on 9/20/14 - 7.88 gpm. No flow No flow No flow	Average Flow Rate of discharge on 926/14 - 7.88 gpm No flow No flow Ouffall discharges the stormwater retention basin located between Door N-28 and McInry Caldet. The stormwater are dention basin because a water is deep enough in the basin to reach the drain, approximately 18-inches deep.	Average Flow Rate of discharge on 9/26/14 - 7/88 gpm No flow No flow Outfall discharges the stormwater retention basin located between Door N-28 and Melriyee Galdh. The stormwater retention basin does not discharge unless where is deeper mough in the basin to reach the drain, approximately 18-inches deep. Outfall discharge is at the same level as the water in McIntyre Guich, therefore it is not possible to determine if flow is discharging from the outfall. The connected to possible to determine if flow is discharging from the outfall. The connected out underground pies, to a manhole approximately 20 feet north of the emergency generator structure on the north side of Bildg 610 (see outfall 02-0UT1015C.	No flow No flow No flow No flow Outfall discharges the stormwater referrition basin located between Door N-28 and Mehryes Cauldh. The stormwater referrition basin located between Door N-28 and Mehryes Cauldh. The stormwater referrition basin does not delohage unless water is sheep enough in the basin to inschi the diaria, approximately 19-inches deep. Outfall dischage is at the same level as the water in Mehryes Guich, therefore it is not possible to determine if flow is dischaging from the outfall. The ordinal is connected to a manifole 20 if, to the southwast. The manhole is subsequently connected, via underground pies, to a manifole approximately 20 feet north of the emergency generator structure on the north side of folig 81 (see outfall 820/11 015C comments). Manhole has a tricide in it. Flow enters the manhole from the south, makes a 90° turn to the east and exist him manhole to the seat. The flow travels 306ft east in an not dischages to outfall 020UT1013C. Flow exting the 020UT1015C common dischage in cutfall 020UT1013C. Flow exting the 020UT1015C common flow of technique flow the rest structure on that outfall 020UT1013C. Flow exting the 020UT1015C.	No flow No	No flow No flow No flow No flow Outfall discharges the stormwater retention basin located between Door N-28 and Markey actient. The stormwater retention basin does not defrage unless water they call the storm of the stormwater retention basin does not defrage unless water they are stored to see the store of the defraging from the outfall to outfall dischage is at the same level as the water in McImtyre Guich, therefore it is pressible to determine if flow it settlarging from the outfall to outfall so connected was a manifole structure on the north side of Bidg 310 (see outfall Q2OUT1015C comments). The flow travals 306ft east in an underground pies, to a manifole supproximately 20 feet north of the emergency agreemator structure on the north side of Bidg 310 (see outfall Q2OUT1015C comments). The flow travals 306ft east in an underground pies, to another manifole. Flow there exist this manifole to the north nord storage is at the same level as the water in McImtyre Guich, therefore it good rischages is at the same level as the water in McImtyre Guich, therefore it possible to determine if flow is discharging from the outfall. There is no manifole between outfall and Bidg 310.	No flow No flow No flow No flow Outfall discharges the stormwater retention basin located between Door N-28 and Machinye Gulch. The stormwater retention basin does not dischage unless water is steep enough in the basin to reach the drain, approximately 'Beinches deep, countierloaps is at the same level as the water in Motinye Gulch, therefore it is roousible to determine if flow is discharging from the outfall. The outfall is connected an manhole 29 fit to the southwest. The manhole is subsequently connected, via amounterground pipe, to a manhole approximately 20 feet north of the energency generator structure on the north side of Bldg 810 (see outfall 020UT1016.C communds). Manhole has a trickle in it. Flow enters the manhole from the south, makes a 90° to the east and east and east the manhole to the northea and discharge of the land the same level as the water in McIntyre Gulch, therefore it is recount discharge directly to an outfall on McIntyre Gulch (see comments for outfall occurred). Outfall and Bldg 810. No flow Manhole between outfall and Bldg 810 also dry (manhole is 14 ft north of the northeades).
Turbidity	0.0	14.4	This	0.0	Outfe	0.0	0.0	NA No fi	F	0.0 Aven	× 3		× 10 2 2 2	2 1 2 2					
ORP mV Tur	109	99		11	50	06	102	NA		109									
TDS g/L OR	0.413	1.51		1.43		0.545	1.22	A A		1.31									
Salinity 7	NA P	AA		¥.		A A	N A	NA A		NA									
PH S	7.86	8.01		7.89		8.21	7.86	Y Y		7.84	7.84 NA	NA NA	NA NA NA	7.84 A A A A	NA N	787 A A A A A A A	78 7	NA N	NA N
								t					1-1						
(degrees C)	17.71	19.81		17.82	1	16.21	16.82	N N		17.73	17.71 NA	NA N	NA NA NA	Ž Ž Ž Z Z	N A A A A A	NA N			
Conductivity mS/cm	0.472	2.36		2.24		0.851	1.9	AN		2.05	2.05 NA	NA NA	NA NA	N A N A N A N A N A N A N A N A N A N A	N A A A A A A A A A A A A A A A A A A A	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	N N N N N N N N N N N N N N N N N N N	N N N N N N N N N N N N N N N N N N N	N N N N N N N N N N N N N N N N N N N
Dissolved 02 mg/l	6.53	7.19		4.91		4.8	4.25	d N	52.	3.84	3.84 NA	3.84 NA	3.84 NA NA	2 8	2 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	A A A A A A A A A A A A A A A A A A A	N A A A A A A A A A A A A A A A A A A A	S S S S S S S S S S S S S S S S S S S	NA N
gals/min	NA A	<0.5	-	8.5		trickle	<1.0		NA NA	NA 55	A 6 A	A & A A	A A A A	N A N A N A N A	A A A A A A	A A A A A A A A A A A A A A A A A A A	A A A A A A A A A A A A A A A A A A A	A A A A A A A A A A A A A A A A A A A	
date	9/26/2014	9/26/2014	9/26/2014	9/26/2014	9/26/2014	9/26/2014	9/26/2014		9/26/2014	9/26/2014	9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014	9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014 9/26/2014
Year	2014	2014	2014	2014	2014	2014	2014		2014										
Physical location	Mointyre Gulch where it leaves the DFC on the east side. Measurement taken from midstream.	Inlet to Downing Reservoir at southwest corner of reservoir	North bank of McIntyre Gulch, inside of the fence just before it goes under Kipling St	North bank of McIntyre Gulch, halfway between Kipling St & Main Avenue crossing	North bank of McIntyre Gulch, west of Main St bridge, south end of 3rd St projection	North bank of McIntyre Guich, west of Agricultural Ditch aqueduct, 42" diameter concrete pipe	Outfall is in the north wing wall of the 5th St bridge (Bridge to Nowhere), west side of bridge, north bank of Mcintyre Gulda, 42" diameter pipe		Inside of north box culvert under 5th St bridge (Bridge to Nowhere), north wall	Inside of north box culvert under 5th St bridge (Bridge to Nowhere), north wall North bank of McIntyre Gulch, south end of 6th St projection, 46° dameter pipe	Inside of north box culvert under 6th St bridge (Bridge to Nowhere), north wired of the North bank of Mchinye Guldh, south end of 6th St projection, 48° diameter pipe Southwest corner of intersection of 7th St hidge and Mchinye Guldh, south side of gulch, or far marrishy are a along west side of 7th St, north of Bildo 710.	Inside of routh box culvert under 5th St bridge legisge to Nowheel, north wall North back of Mchrye Gulch, south end of 6th St projection, 48' diameter pipe Southwest corner of intersection of 7th St Southwest corner of intersection of 7th St bridge and Mchrye Gulch, south side of gulch. Drains marshy area along west side of 7th St, north of Budg 7th and along west side of 7th St, Southwest of Mchrye Gulch, north of gulch.	Inside of north box culvert under 5th St bridge (Bridge to Nowhere), north wall North box Culoth wall North bank of Mchintyre Guldh, south end of 6th St projection, 48° diameter pipe of St projection, 48° diameter pipe of St bridge and Mehryre Gulch, south side of Julch Drains marshy area along west side of 7th St, bridge and Mehryre Gulch, north of 1the Thomas of Mehryre Gulch, north of 1the northwest comer of Blidg 710. South bank of Mehryre Gulch, horth of the northwest comer of Blidg 710. North side of Mehryre Gulch between Joppa and BLM storage yards, north of the northwest comer of Blidg 810.	Inside of fronth box culvert under 5th St bridge (Bridge to Nowhere), north wired of the St bridge to Nowhere), north with end of 6th North bank of Mchintye Guldh, south end of 6th St projection, 48' diameter pipe. Southwest corner of intersection of 7th St bridge and Mchintye Guldh, south side of gulch, north of Beldy 710. South bank of Mchintye Guldh, north of the northwest conner of Bldg 710. North side of Mchintye Guldh, north of the northwest conner of Bldg 810.	Inside of fronth box culvert under 6th St bridge (Bridge to Nowhere), north wall in which the worth and of 6th North bank of Mchintye Guldh, south end of 6th St projection, 48' diameter pipe. St projection, 48' diameter pipe and when the standard of 7th St bridge and Mchintye Guldh, south side of gulch, north of Belig 710. South bank of Mchintye Guldh, north of the northwest corner of Blidg 710. North side of Mchintye Gulch between Joppa and But storage yards, north of the northwest corner of Blidg 810. Outfall is north of Door N-28 of Blidg 810.	Inside of north ox culvert under 5th St bridge (Bridge to Nowhere), north wall in the wall of 6th North bank of Mchinyre Guldh, south end of 6th St projection, 48° diameter pipe. St projection, 48° diameter pipe. Southwest corner of intersection of 7th St bridge and Mchinyre Guldh, south side of gulch. The pipe of 9th orth of 8thg 710. South bank of Mchinyre Gulch, north of the northwest comer of 8thg 710. North side of Mchinyre Gulch between Joppa and BLM storage yards, north of the northeast corner of Bldg 810. Ourfall is north of Door N-25 Of 8thg 810, at the waters edge. Ourfall is north of Door N-25 Of 8thg 810, at the waters edge.	Inside of fronth box culvert under 8th St bridge (Bridge to Nowhere), north wall St projection, 48' diameter pipe St projection, 48' diameter pipe Southwest corner or Intersection of 7th St bridge and Mahityre Gulch, south side of glidh. South bank of Mahityre Gulch, north of the northwest corner of Blag 710. South bank of Mahityre Gulch, north of the northwest corner of Blag 710. South bank of Mahityre Gulch between Joppa and BLM storage yards, north of the northeast corner of Blag 810. Outfall is north of Door N-25 Of Blag 810, a waters edge. Directly north of Door N-15 of Blag 810 and generator blag. Directly north of Doors N-9 and N-10 of Blag south of Breetly north of Doors N-9 and N-10 of Blag son and Blag 810.		
Outfall no.	mid-stream	- 3	020UT9016C				020UT1011C	4					17					7.447	45 N.7

11- During the summer of 2011, the banks of Maintyre Guich were reconfigured where the guich crosses Main Ave. This work was performed as part of the DFC-wide Utility Infrastructure Project (UIP). During this work, Outfall No. 020UT1003C was destroyed. It is believed that this outfall was part of the old DFC storm sewer system and was no longer operational. Therefore, it was not replaced. Flow had not been noted at this outfall during the Annual Dry Weather Survey since Jully of 2007.

orm Sewer Outfalls - Denver Federal Center: Annual Dry Weather Survey - September 2015
y Weather Survey
Annual Dr
er Federal Center:
utfalls - Denv
orm Sewer O
McIntyre Gulch Storm

e c			Survey R date gal	Avg Flow Rate Diss	Dissolved O2 Con	Conductivity Tel	Temperature (degrees C)	Sal PH	Salinity TI % g	TDS g/L ORP	ORP mV Turbidity	2	Comments	Reference Photo	
pin pin				Is/min			degrees C)				1				
							_	_	_					McIntyre Gulch east boundary	
		2015 9/3	9/3/2015	NA	7.63	1.66	16.51	6.95	1.0	1.1 59	9 92.6		in the second se	Outfall-140UT3001C	
		2015 9/3	9/3/2015	<0.5						-	-	No	Not enough now to capture for measurements		
		2015 9/3	9/3/2015	NA A	NA	A N	NA A	Ą	A A	NA	NA NA		This is a seep not an outfall. This location is not longer monitored.	O-#6-11-02011T4005C	
		2015 9/2	9/3/2015	-12	7.4	2.21	17.2	6.67	0.1	1.4	89 92.7	7.		Odniali-Ozo-	
		2015 9/7	9/3/2015	Y Y	Ą	Ā	NA	Ą	¥ X	Z Y	NA		Ouffall destroyed. See note *1 below.		
		2015 9/2	9/3/2015 to	trickle								Not	Not enough flow to capture for measurements	Ouffall-02OUT1001C	
		9015	370045	2	88	1.83	17.14	6.85	0.1	12	69 84	84.3		Ouffall-020UT1011C	
		-					47			AN	AN		woll c	Outfall-020UT9008C	
	- 2	2015 9/	9/3/2015	0 9	A 56.	F 19.1	17.44	6.85				0	This is the discharge outfall for the Bldg 52 groundwater treatment system. Daily Average Flow Rate of discharge on 9/26/14 - 7.36 gpm	Outfall-020UT1009C	
	1		9/3/2015	4	6.74	1.54	17.86	6.99	0.1	1.0 6	66 09	9.66		Outfall-020UT1017C	
020011017C north or brug 710 South bank of Moltyre Gulch, north of the		-	9/3/2015	0	A N	NA	NA	A A	NA A	Z V	Z Y	NA	No flow	Outfall-020UT0003C	
	11		9/3/2015	0	AA	¥ Z	Ą	NA A	A A	Z Y	A N	NA	No flow	Outfall-12SOUT1001C	
						2	4 2	4 2	4 2	4 2	Z Z	NA Mer	Outfall discharges the stormwater retention basin located between Door N-28 and McIntyre Guich. The stormwater retention basin does not discharge unless water is deep enough in the basin to reach the drain, approximately 18-inches deep.	Outfall-02OUT1014C	
02/OUT1014C Outfall is north of Door N-28 of Bidg 810. Outfall is north of Door N-25 Of Bidg 810. at the	at the	2015	9/3/2015	0	≨	5	2	5					Outfail dischage is at the same level as the water in Molityre Gulch, therefore it is not possible to determine if they is deschaging from the outfail. The outfails is connected to a manhole 29 it, to the southwest. The manhole is subsequently connected, was unarrily early to the southwest. The manhole is subsequently connected, was unarrily and an ambide approximately 20 feet north of the emergency agenerator structure on the north side of Bldg 810 (see outfail 02OUT1015C).	Ouffall-02OUT1013C and Manhole-02OUT1013C	
020UT1013C waters edge. Directly north of Door N-15 of Bldg 810 and			9/3/2015	A N	ď.	Š	<u>\$</u>	X :	<u> </u>	5		Ma und to	Manhole has a tickle in it. Flow enters the manhole from the south, makes a 80° turn to the east and easts the flow travels 50° fle ast it is underground upon to another the manhole to the east. The flow that waves 50° fle ast it is an underground pipe, to another manhole. Flow then east fits manhole to the northeast and dischages to ordifall 020UT1013C. Flow easting the 020UT1015C manhole does not dischage directly to an outsil on McImyre Culch (see comments for outsill proportion 103°).	Manhole-020UT1015C	
	-		9/3/2015	Y :	¥ :	Y .	Y S	£ 4	2 4	-			Outfall dischage is at the same level as the water in McIntyre Gulch, therefore it is not possible to determine if flow is discharging from the outfall. There is no manhole between outfall and Bldg 810.	Ouffall-020UT9002F	
02OUT9002F 810. Outfall directly north from a point halfway		-	9/3/2015	ž d	Y 4	K N	2 4	4 2	4 Z				No flow	Outfall-Door N-5 N-7	
-9 N-7	5	2015	9/3/2015		Z Z	£ \$	¥ ¥	NA A	NA A				Manhole between outfall and Bldg 810 also dry (manhole is 14 ft north of the north edge of the pavement).	Outfall-02OUT1016C and Manhole-02OUT1016C	
Mointyre Guich where it enters the DFC on the Mointyre Guich where it enters the DFC on the Mointyre Guich was side. Measurement taken from mid-				2	77	1 63	17.50	7 92	10	1.0	6	122.0		McIntyre Gulch west boundary	

*1- During the summer of 2011, the banks of McIntyre Guich were reconfigured where the gulch crosses Main Ave. This work was performed as part of the DFC-wide Utility Infrastructure Project (UIP).
During this work, Outfall No. 020UT1003C was destroyed. It is helieved that this outfall was part of the old DFC storm sewer system and was no longer operational. Therefore, it was not replaced. Flow had not been noted at this outfall during the Annual Dry Weather Survey since Jully of 2007.

CONTRACT LANGUAGE DEVELOPED TO PROHIBIT NON-STORM WATER DISCHARGES

Region 8 Sustainability & Environmental Management System

1.0 Purpose & Scope

The purpose of this procedure is to protect the Nation's waterways and wetland areas, into which storm sewers ultimately drain. This is achieved by requiring the use of protective measures, to prevent contaminated storm water or other types of water, which may contain chemicals, silts or soils generated during projects from entering waterways and wetland areas.

2.0 Activities & Departments Affected

- 2.1 Every person entering a GSA facility owned and/or operated by GSA (e.g. DFC Campus) has the potential to impact the Storm Sewer System.
- 2.2 This procedure is to be followed by all personnel conducting landscaping, site demolition, building construction, maintenance, remediation, underground line repair/replacement and/or intrusive subsurface activities at a GSA facility owned and/or operated by GSA.

3.0 Exclusions

Magnesium chloride used in snow removal activities.

4.0 Forms Used & Permits Required: (include reporting requirements)

Federal and State Forms a	nd Permits:	
PERMIT / FORM / REPORT	SUBMITTED TO: FEDERAL OR STATE AGENCY	SUBMITTAL FREQUENCE
Municipal Separate Storm Sewer System (MS4) Permit ⁽¹⁾	U.S. Environmental Protection Agency (EPA) and/or appropriate state agency	5 years; facility specific
Stormwater Management Plan	EPA and/or appropriate state agency	As needed
MS4 Annual Report	EPA and/or appropriate state agency	annual
Notice of Intent as spelled out by MS4	EPA and/or appropriate state agency	As needed

(1) The GSA Denver Federal Center (DFC) Campus has a small Municipal Separate Storm Sewer System (MS4) Permit, issued by the U.S. Environmental Protection Agency (EPA) under the National Pollution Discharge Elimination System (NPDES), as a requirement of the Clean Water Act, Section 402(p)(2). This requires that no liquid, other than stormwater, may be discharged directly to a storm sewer. Therefore, any activity which may impact water quality entering the storm sewer system or where other types of water must be diverted from the storm sewer system is addressed in this procedure.

☐ In-house GSA Region 8 and Contractor Forms:

- Excavation Permit Request Form (GSA Region 8 Excavation 'Dig' Permit Environmental Procedure)
- Environmental Programs Group Storm Water Inspection form (Attachment C)



Region 8 Sustainability & Environmental Management System

5.0 Acronyms, Abbreviations, and Definitions

Acronyms	Meaning	
CDPHE	Colorado Department of Public Health and Environment	
CO	Contracting Officer	
COR	Contracting Officer Representative	
DFC	Denver Federal Center	
EO	Executive Order	
EPA	U.S. Environmental Protection Agency	
EPG	Environmental Programs Group of GSA, PBS, Region 8	
GSA	U.S. General Services Administration	
MS4	Municipal Separate Storm Sewer System	
NPDES	National Pollution Discharge Elimination System	
NOI	Notice of Intent	
RCRA	Resource Conservation & Recovery Act	
RFI	RCRA Facility Investigation	
SEMS	Sustainability & Environmental Management System	
SPCC	Spill Prevention Control & Countermeasures	

Definitions:

<u>Municipal Separate Storm Sewer Systems (MS4s)</u>: May be required to obtain authorization to discharge stormwater (EPA); EPA requires that the DFC have an MS4.

<u>National Pollutant Discharge Elimination System (NPDES) Stormwater Program:</u>
Regulates stormwater discharges from three potential sources: municipal separate storm sewer systems (MS4s), construction activities, and industrial activities (EPA).

Outfall: The mouth of a drain or sewer

<u>Predevelopment Hydrology</u>: The runoff volume, rate, temperature, and duration of flow that typically existed on the site before human-induced land disturbance occurred (EISA).

6.0 Procedure

State Specific Procedures & Requirements [refer to individual State Legal Reviews for details on Statues, Laws, and Rules]: Most states administer their own stormwater programs.

STATE	REQUIREMENTS / PROCEDURES
Colorado	In Colorado, the Stormwater Management Program is regulated by the EPA and the State. Water Quality is regulated by the Colorado Department of Public Health and Environment (CDPHE) Water Quality Control Division. The program is referred to as the Colorado Discharge Permit System (CDPS) for non-federal property instead of NPDES. State stormwater requirements are mirrored after the federal NPDES program, requiring that stormwater be treated to the maximum extent practicable (MEP). CDPS requires that all construction sites disturbing more than one-acre, and all designated Municipal Separate Storm Sewer Systems (MS4s) to obtain permit coverage. Each permitted MS4 will be



Region 8 Sustainability & Environmental Management System

STATE	REQUIREMENTS / PROCEDURES
	responsible for establishing a Stormwater Management Program (SWMP) unde either the Phase I, or under Phase II of the CDPS. Additional permitting requirements may be required at the county and municipal level.
	No numeric requirements for stormwater pollutant removal have been
	established at the state level, but many stringent regional and municipal
	regulations are in place. Many municipalities reference the suggested
	requirements in the Denver Urban Drainage and Flood Control Manual, which was originally developed for the Denver metro area.
Montana	In Montana, the Montana Department of Environmental Quality (MDEQ) is
	authorized to administer the National Pollutant Discharge Elimination System
	(NPDES) Program through the Montana Pollutant Discharge Elimination System
	(MPDES) Program. Permits are developed and issued under:
	Phase Lef the NRDES atera water and issued under.
	Phase I of the NPDES storm water program applies to construction activities
	affecting more than 5 acres.
	Phase II of the NPDES storm water program covered smaller construction
	activities disturbing between 1 and 5 acres. [Administrative Rules of
	Montana (ARM), Title 17, Chapter 30, Subchapters 11, 12, and 13].
North	The North Dakota Department of Health & Environmental Division of Water
Dakota	Quality (DHEWQ) is responsible for administering the state's National Pollution
	Discharge Elimination System (NPDES) Storm Water Program, North Dakota's
	stormwater program is closely modeled after the federal NPDES program. At the
	state level, all construction sites disturbing more than one acre, many industrial
	sites, and all designated Municipal Separate Storm Sewer Systems (MS4s) are
	required to obtain and meet the requirements of NPDES permit coverage. In
	addition to state, regional, and local regulations there are a number of
	established and proposed TMDLs impacting North Dakota's watersheds, which
	often impact stormwater treatment requirements. To ensure compliance with all
	applicable stormwater regulations, the municipality where the project is a
	applicable stormwater regulations, the municipality where the project is to take place needs to be contacted.
South	
	The South Dakota Department of Environment & Natural Resources (DENR) is
Dakota	responsible for administering the state's Stormwater Management Program.
	South Dakota's stormwater program is closely modeled after the federal Nationa
	Pollution Discharge Elimination System (NPDES) program, which requires
	stormwater be treated to the maximum extent practicable. This program
	establishes permitting requirements for construction sites disturbing more than
	one acre, industrial sites, and Municipal Separate Storm Sewer Systems (MS4s)
	All MS4s should currently be permitted, or in the permit process. Each permitted
	MS4 will be responsible for establishing a Stormwater Management Program
	(SWMP). Be advised that there may be additional permitting requirements at the
	county and municipal level.
Utah	The Storm Water Program is regulated by the Utah Department of Environmenta
	Quality (UTDEQ) through the Division of Water Quality. The Utah storm water
	program is closely modeled after the federal National Pollution Discharge
	Elimination System (NPDES) program. The Utah DEQ water program
	establishes permitting requirements for construction sites disturbing more than
	one sere industrial sites and Municipal Construction sites disturbing more than
	one acre, industrial sites, and Municipal Separate Storm Sewer Systems (MS4s).
	Each permitted MS4 will be responsible for establishing a Storm Water
	Management Program (SWMP). Be advised that there may be additional
	permitting requirements at the county and municipal level, especially where
	TMDLs are in place.
	Utah does have a Storm Water Advisory Committee. The Advisory Committee



Region 8 Sustainability & Environmental Management System

STATE	REQUIREMENTS / PROGEDURES
	serves as an agent to address a variety of stormwater issues statewide, including implementation of Phase I and II regulations.
Wyoming	The Wyoming Department of Environmental Quality (DEQ) regulates the state's Wyoming Pollutant Discharge Elimination System (WYPDES) Storm Water Program . Wyoming's stormwater program is closely modeled after the federal National Pollution Discharge Elimination System (NPDES) program, which requires stormwater be treated to the maximum extent practicable (MEP). Numeric treatment requirements specific to stormwater have not been established at the state level, but water quality parameters will be established on a site-by-site basis when the risk of contamination is present.
	Wyoming's stormwater program establishes permitting requirements for construction sites disturbing more than one acre, industrial sites, and Municipal Separate Storm Sewer Systems (MS4s). All MS4s should currently be permitted, or in the permit process. Each permitted MS4 will be responsible for establishing a Stormwater Management Program (SWMP).
	Large construction permit - surface disturbance of 5 acres or more Small construction permit - disturbance of at least 1 acre, but less than 5
	A Guide to Temporary Erosion-Control Measures for Contractors, Designers and Inspectors Erosion and Sedimentation Control Plans, and BMP Fact Sheets
	Wyoming water quality regulations require that when discharging stormwater to a live water body (such as lakes, streams, and rivers), levels of turbidity may not increase by more then 10-15 NTU's over background levels. When discharging to non-live waterways, the state's goal is to reduce sediment loads in order to avoid aesthetic and habitat degradation.

(StormwaterAuthority.org; http://204.202.251.206/)

Standardized Procedure:

6.0 Stormwater Regulations & Contracting

- Comply with all federal regulations, and where applicable state regulations and local ordinances. Where required obtain permits and comply with reporting requirements.
- Follow requirements set forth in any Municipal Separate Storm Sewer System (MS4) permit that may exist, issued by the State and/or EPA where required. The Denver Federal Center (DFC) has its own MS4 permit, follow this permit at the DFC.
- The Property Manager or Contracting Officer will incorporate language requiring adherence to all Stormwater environmental requirements into all GSA contracts where the potential exists to impact the Storm Sewer System.
- GSA Project Managers and Contracting Officer Representatives (CORs) are responsible for overseeing contractors' performance and compliance.
- The signature of the COR or Project Manager on the Receiving Report contained in



the contract file, implies that all contract requirements relating to this Stormwater Environmental Procedure have been met.

6.1 Stormwater Awareness & Training

- <u>Contractors</u> are responsible for knowing that only rainwater may go down a stormwater sewer drain. <u>Contractors</u> will train their staff in Stormwater compliance measures, required by law, their contracts and defined by this GSA, SEMS Environmental Procedure.
- CORs are responsible for overseeing that this has been completed and is effective.
- The <u>SEMS Project Team</u> is responsible for disseminating Stormwater Awareness information throughout GSA Region 8:

posters brochures training modules huddle topics

newsletters presentations

- The <u>Storm Water Manager</u> or <u>Building Manager</u> is responsible for placing curb markers beside each storm drain catch basin.
- The <u>SEMS Action Team Lead</u> for Stormwater is responsible for reviewing, updating, reporting and implementing, at least annually, all federal, state and local regulatory requirements.
- The <u>EPG</u> and <u>Stormwater Program Manager</u> will ensure that the DFC Storm Sewer System Map is current, showing the location of all outfalls.

6.3 Construction Site Stormwater Design, Runoff Control and Post Construction Stormwater Management

a. <u>Project Managers</u> or <u>Contractors</u> will assess proposed new projects for their potential to impact stormwater, whether by soil disturbance or discharge.

Employ design and construction strategies that reduce stormwater runoff and discharges of polluted site water runoff (Guiding Principles for Federal Leadership in High Performance and Sustainable Buildings [Federal Leadership in High Performance and Sustainable Buildings Memorandum of Understanding, January 2006; "High Performance and Sustainable Buildings Guidance", Interagency Sustainability Working Group (ISWG), Dec. 2008]; GSA Region 8 Sustainability Requirements for High Performance Green Buildings - New Construction, Major Renovations & Existing Buildings Environmental Procedure).

Federal agencies are instructed to "use site planning, design, construction, and maintenance strategies for the property to maintain or restore, to the maximum extent technically feasible, the predevelopment hydrology of the property with regard to the temperature, rate," for any project with a footprint that exceeds 5,000 square feet; approximately 71 feet by 71 feet (Section 438 of Energy Independence and Security Act of 2007 (EISA); EPA, Technical Guidance on Implementing the Stormwater



Region 8 Sustainability & Environmental Management System

Runoff Requirements for Federal Projects under Section 438 of the Energy Independence and Security Act, EPA 841-B-09-001, December 2009). Promote the use of decentralized stormwater management design strategies to maintain or restore site hydrology to pre-development conditions and promote water-efficient landscaping and irrigation strategies.

If stormwater impact potential exists, appropriate contracting documents need to address this concern, as ensured by the Project Manager or Contracting Officer:

- The Scope of Work, for construction projects
- The Performance Work Statement, for service contracts, such as the Grounds Maintenance and Snow Removal contract.

If needed, this information will be placed into any Change Request for Modification, if a contract needs modified.

- b. <u>Project Managers</u> will include an Erosion Control Plan where storm drains could be impacted. This plan is required for DFC projects and may be applicable for Leadership in Energy & Environmental Design (LEED) projects. An Erosion Control Plan is part of the DFC Excavation Permit commonly called the DFC Dig Permit, and is required for DFC projects: See GSA Region & Excavation 'Dig' Permit Environmental Procedure:
- c. The GSA Project Manager is responsible for the following aspects, relating to the DFC Dig Permit:
 - Submitting a completed Excavation Permit Request Form (see GSA Region 8
 Excavation 'Dig' Permit Environmental Procedure) to the EPG DFC Dig
 Permit coordinator, prior to the disturbance of any earth.
 - Conveying the information in the DFC Dig Permit to the contractor performing the excavation work and all other parties who may be involved with the excavation.
 - Delivering a copy of the DFC Dig Permit to the Contracting Officer, for the Contracting Project files.
- d. The <u>EPG DFC Dig Permit coordinator</u> will research and assess the potential for soil and groundwater contamination and then prepare the permit, detailing the depth to water and any necessary precautions. The permit is assigned a number, logged in the database, filed and a copy is provided to the GSA <u>Project Manager</u>.
- e. Once it is determined that a project will disturb soils of any amount, the <u>Contractor</u> is required to initiate precautionary measures, as detailed in the Erosion Control Plan, to prevent discharge of potentially contaminated storm water or other non-storm related waters directly into a storm drain. Precautionary measures include, but are not limited to, the installation of silt fencing, absorbent material such as fiber rolls, straw bales, gravel bags (see examples at the EPA "National Menu of Stormwater Best Management Practices" website; Attachment B).

Projects involving soil disturbance of one acre or more require that the Contractor

Region 8 Sustainability & Environmental Management System

prepare a stormwater management plan and submit the Notice of Intent (NOI) form to the EPA. Additionally, the <u>Contractor</u> will submi EPA NPDES Form 3510-9 to the EPA and a Storm Water Management Plan (SWMP) to the <u>Project Manager</u> or <u>EPG</u> at the GSA. The <u>Contractor</u> must comply with the NOI requirements, including the Stormwater Prevention Plan, for the duration of the project. The contractor is required to submit the NOI number to the SEMS Project Team for recording. The <u>EPG</u> or <u>COR</u> will conduct and record inspections of these projects on a regular basis.

Upon completion of the project, the <u>Contractor</u> will request a Notice of Termination (NOT) inspection. The <u>COR</u> or an <u>agreed upon 3rd party</u> will inspect for the NOT and check whether or not the SWMP and NOI requirements have been met. Once the inspection is complete and the NOT is approved, the <u>Contractor</u> will submit a Notice of Intent to the EPA and <u>COR</u>, if necessary.

- f. Discharged water shall be directed away from all curbs and other areas where storm drains may exist.
- g. Discharging non-storm water to lawn areas, open areas, or into a Baker tank truck, is considered acceptable practice. However, the <u>Contractor</u> must install protection around all of the storm drains which could be impacted.
- h. GSA <u>Project Managers</u> will maintain oversight and conduct weekly inspections on any project requiring storm drain protection measures, to check the integrity of the protective measures and to ensure at the completion of the project that any observable material is removed from the storm drain area. Inspections are documented on the EPG, Excavation Permit: Excavation Inspection Report form (see GSA Region 8 Excavation 'Dig' Permit Environmental Procedure).
- Upon completion of the project requiring the discharge of water, storm drain protection should be removed by the <u>Contractor</u> and it should be noted in the project file.
- j. <u>Contractors</u> are required to adhere to the project design criteria as established in the design documents for the control, retention and detention of post construction runoff during storms and the removal of suspended solids from runoff.

6.4 Accidental and Deliberate Discharge Detection and Elimination:

- a. Contract language will dictate the preventive measures required to be implemented by Contractors working at GSA facilities in order to avoid non-storm water discharges entering the storm sewer system. This will be ensured by the <u>Project Manager</u> or <u>Contracting Office</u>.
- b. The <u>Contractor</u> is responsible for ensuring that their personnel are appropriately trained and compliant with these requirements. GSA Project Managers and CORs are responsible for monitoring contractors' performance and compliance.



Region 8 Sustainability & Environmental Management System

- c. Prevention of discharges:
 - Deliberate dumping into the stormwater system is illegal under the Federal Clean Water Act and is punishable by law.
 - The <u>Building Manager</u>, or assigned <u>Contractor</u> or individual inspects every mechanical room of all buildings monthly. If any spills or discharges are discovered, the <u>Building Manager</u> is notified and then the <u>EPG</u> is notified of any problems or potential problems.
 - Security measures are maintained at federal facilities. This reduces the
 potential for accidental or deliberate spills.
- d. <u>Contractors</u> are governed by the Green Buildings and Grounds Maintenance elements of the SEMS, thereby reducing the use of hazardous chemicals which can impact the Storm Sewers.
- e. Detection measures for non-stormwater discharges are performed:
 - By being observant;
 - Upon receipt of information from anyone at a federal facility reporting an observation or something suspicion;
 - As a result of a reported spill;
 - Where an MS4 permit or a Consent Order is in place, such as at the DFC: quarterly surface water sampling is performed as part of the Long Term Monitoring Program, and
 - Stormwater outfalls are inspected annually, during dry weather, for the presence of non stormwater discharges
- f. Response to Accidental / illegal release:

In the event of a non-stormwater (i.e., solvents, fuels, lubricants, dirt/sediment from a construction project, etc.) release indoors or outdoors into a Storm Sewer system notify the <u>Building Manager</u> or <u>Supervisor</u>. This material is not permitted to enter a storm drain.

At the DFC if no supervisor can be found, then call 303-236-2911. The Environmental Procedure for Spill Response is followed for a non-stormwater release into a Storm Sewer system.

The level of response varies according to toxicity. GSA <u>CORs</u>, <u>Project Managers</u>, <u>Building and Property Managers</u> all carry the Emergency Spill Cards, with contact details. The Spill Prevention Control and Countermeasure (SPCC) Plan is followed.

7.0 Records Management

The EPG are responsible for retaining the completed:

- DFC Excavation Permit Documents
- Inspection forms

Region 8 Sustainability & Environmental Management System

- GSA Staff Training records
- Copies of completed NOI forms
- Storm Water Management Plan
- EPA NPDES Form 3510-9
- Notice of Termination

8.0 References

EPA, Technical Guidance on Implementing the Stormwater Runoff Requirements for Federal Projects under Section 438 of the Energy Independence and Security Act, EPA 841-B-09-001, December 2009

Executive Order 13423 (Federal Register, Vol. 72, No. 17): "Strengthening Federal Environmental, Energy, and Transportation Management", signed by President George W. Bush on 24 January 2007

Executive Order 13514 (Federal Register, Vol. 74, No. 194): "Federal Leadership in Environmental, Energy, and Economic Performance", signed by President Barack Obama on 5 October 2009

Federal Leadership in High Performance and Sustainable Buildings Memorandum of Understanding, January 2006

H.R. 6--110th Congress [Public Law 110-140]: Energy Independence and Security Act (EISA) of 2007, Dec. 19, 2007

Interagency Sustainability Working Group (ISWG), as a subcommittee of the Steering Committee established by EO 13423, "High Performance and Sustainable Buildings Guidance", Final (12/1/08)

9.0 Appendices

Attachment A: Flowchart

Attachment B: Table 1: Examples of Control Measures and Table 2: Maintenance for Control Measures

Attachment C: Construction Site Inspection Form

Document Control Information:	Approved & Dated:
Stormwater Management "Month-Date-Year".doc	RJM 07/06/2012

Document Rev	ision and Update:	
Revision Date	Nature of Revision	Revision made by:
11/29/2005	Working Draft	Elizabeth B. Roberts
03/13/2006	Original Release	Elizabeth B. Roberts



STORMWATER MANAGEMENT
Region 8 Sustainability & Environmental Management System

Revision Date	Nature of Revision	Revision made by:
09/14/2007	Updated - New Regulations	Sue Grant
7/21/2008	Updated	Sue Grant & Robert Melvin
10/10/2009	Add ISO 14001 Document Controls,	Robert Melvin
01/25/2010 to 10/18/2010	Add state regulations, add Flowchart, outline Region 8 requirements, and update to address new federal regulations (i.e. EISA Section 438).	Robert Melvin, William Fieselman
07/06/2012	Rewrite to incorporate MS4 permit requirements, reassess EISA Section 438, emphasize Roles and Responsibilities in section 6, update flowchart	John Kleinschmidt, William Fieselman, Nick Gutschow, Robert Melvin



Region 8 Sustainability & Environmental Management System

ATTACHMENT A: Stormwater Flowchart Awareness and Training: GSA Project Manager or Contractor Contractors: train their staff in storm water if there is Soil disturbance from Construction, Responsible Parties Landsceping Waterline Repair, etc Evaluate potential of stormwater discharge • Before solicitation is sent out, and environmental compliance Contracting Officer's Representative (COR) Contractor CORs; ensure proper Contractor training During work performance Property Manager **Environmental Programs** SEMS Project Team; will at least annually Group (EPG) All Protect storm drains from runoff or other discharge review all local, state, and federal storm water egutations and ensure GSA procedures are Project Manager or Contracting Officer: Ensure up to date and in compliance; distributing info contract language requiring adherence to storm water regulations; Scope of Work, Performance Work Statement, and other relevant documents should reflect Storm Water/Property Manager: Place curb markers at catch basins EPG or Storm Water/Property Manager Employ design and construction strategies to reduce stormwater runoff and discharges of polluted site Ensure storm sewer system map is current water runoff (High Performance and Sustainable Buildings Guidanca, 2008) Only Follow OTHER THAN DFC NO Accidental/Deliberate Discharge: to the Project NO Region 8 Fleid Offices the Soi YES Added Requirements s the Soll disturbance EISA Property Manager/Contractor: may apply (i e . Municipa! Codes for Inspect mechanical rooms of all Federal 5,000 sq & or >1 acre? enter buildings monthly for discharge, stormwater, if impacted) in case of discovery inform the Property Manager or EPG as NO YES YES Follow Best Follow Management NOI Anyone: Only reinwater may be Practices' released into a storm drain; if a discovery is made of other releases, inform the Property Manager or EPG. They will respond as needed and may need to follow the SEMS Spill Response procedure Notice of Intent (NOI). Upon completion of project Contractor: Request Notice of Termination (NOT) inspection Arryone who disturbs solis: Contractor Submit Notice of Intent (NOI). Prepare application for an Excavation 'Dig' Permit with Erosion **a** Construction General Permit EPA NPDES Form NO EPG Has the right to inspect YES . 3510-9 and COR or agreed upon 3rd party inspect for NOT; have SWMP and NOI requirements been Storm Water Management Plan (SWMP) the Sol To GSA and EPA YES 5.000 sq ft or YES . Contractor: Remove erosion Energy Independence & Security Act (EISA) control protection from around Contracting Officer's Representative (COR) storm drain upon completion of project Inspect storm water EISA and erosion controls For any project with a footprint that exceeds 5,000 square feet: "Use alta planning, design, construction, NO YES Upon approval of inspection Contractor: Submit Notice of Termination (NOT) to EPA and Document Inspection on and maintenance strategies for the property to maintain or restore, to Quality Surveillance Form ration (NOT) to EPA and the maximum extent technically GSA; If required Follow the "Excavation sible, the pre-development hydrology of the properly with Olg Permit YES NO regard to the temperature, rate volume, and duration of flow' (EISA, Sec. 438, 2007) **Environmental Procedure** If NOI is Not Required Scan and save to EPG: Approve Storm Water Management Plan (SWMP) to retain drainage on site Complete NOI if Required

ATTACHMENT B Table 1: Examples of Control Measures

Source Area or Activity	Potential Pollutants	Control Measures
Pavement removal activities	Asphalt, concrete, sediment, oil and grease	Storm Drain protection: silt fence, fiber rolls, straw bales
Grading activities including stockpiling and hauling	Asphalt, concrete, sediment, oil and grease	Storm Drain protection: fiber rolls and / or straw bales
Underground utility earthwork activities/ remediation	Sediment	Storm Drain protection: silt fence / fiber rolls / straw bales
Vehicle and equipment use, storage and maintenance	Oil, grease, fuels, coolants, detergents and sediment	Earthen berms, drip pans, absorbent materials, covering, straw bales
Solid Waste	Construction and domestic waste (floatables), and leachate	Water-tight and/or covered dumpsters

Table 2: Maintenance for Control Measures

Control Measure	Maintenance/Repair Measures
Storm Drain Protection	Replace torn/damaged filtering or absorbent materials, remove accumulated sediment, and adjust as necessary.
Fiber rolls / straw bales, silt fences	Replace damaged sections, remove accumulated sediment and debris, re-position as necessary.
Street Sweeping	Perform as needed.

Region 8 Sustainability & Environmental Management System

ATTACHMENT C: Construction Site Inspection Form

	OVERALL CONDITION (Good, Fair, Poor)	NEED REPAIR? (Yes, No)	COMMENTS
Carrier and the Co.		TRAL MEAS	URES
Sediment Containment Systems			
Hay Bale Barriers			
Silt Fence Barriers			
Rock Barriers	751.8		100000000000000000000000000000000000000
Inserts			
Vehicle Tracking Pad			
	NON-STRUCTURAL	L MEASURE.	S and/or Swales
Diversion Dikes and/or Swales			A second desired and the second secon
Slope Drains			
Temporary Vegetation		1 1 1 1	
Perennial Vegetation			
Mulch and/or BFM Protection			
Soil Binder Protection			
Hillside RECPs			***************************************
Drainage Channel TRMs			
Riprap and/or Gabions			

Will existing BMPs need to be modified or removed or additional BMPs installed? If Yes, list the action items to be completed on the following table.

Y/N

ACTIONS TO BE COMPLETED	DATE COMPLETED	
	1 1 1 1 1	

Region 8 Sustainability & Environmental Management System

Weather information since the last inspection was held.

EVENT	DATE BEGAN	DURATION (Hours)	AMOUNT (Inches)
			1 1 1 2
	- 1 11 11		
			1. 1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
		. 12/11	

	and the state of t	
re non compliance incidents evident? Y/N yes, describe:		
dditional Comments:		
		economical de la company de la
gnature:		

ONE-TIME NON-STORM WATER DISCHARGE ASSESSMENT

CHANGES TO EXISTING CONTRACT LANGUAGE REQUIRING PROPER CONSTRUCTION SITE WASTE CONTROL AND DISPOSAL

None to date - 1/30/14" " 11 - 2/10/15" " 11 - 2/5/16

SITE PLAN REVIEW PROCEDURES

STORMWATER MANAGEMENT Region 8 Sustainability & Environmental Management System

the contract file, implies that all contract requirements relating to this Stormwater Environmental Procedure have been met.

6.1 Stormwater Awareness & Training

- Contractors are responsible for knowing that only rainwater may go down a stormwater sewer drain. Contractors will train their staff in Stormwater compliance measures, required by law, their contracts and defined by this GSA, SEMS Environmental Procedure.
- CORs are responsible for overseeing that this has been completed and is effective.
- The SEMS Project Team is responsible for disseminating Stormwater Awareness information throughout GSA Region 8:

posters

training modules

newsletters presentations

brochures

huddle topics

- The Storm Water Manager or Building Manager is responsible for placing curb markers beside each storm drain catch basin.
- The SEMS Action Team Lead for Stormwater is responsible for reviewing, updating, reporting and implementing, at least annually, all federal, state and local regulatory requirements.
- The EPG and Stormwater Program Manager will ensure that the DFC Storm Sewer System Map is current, showing the location of all outfalls.

6.3 Construction Site Stormwater Design, Runoff Control and Post Construction Stormwater Management

a. Project Managers or Contractors will assess proposed new projects for their potential to impact stormwater, whether by soil disturbance or discharge.

Employ design and construction strategies that reduce stormwater runoff and discharges of polluted site water runoff (Guiding Principles for Federal Leadership in High Performance and Sustainable Buildings [Federal Leadership in High Performance and Sustainable Buildings Memorandum of Understanding, January 2006; "High Performance and Sustainable Buildings Guidance", Interagency Sustainability Working Group (ISWG), Dec. 2008]; GSA Region 8 Sustainability Requirements for High Performance Green Buildings - New Construction, Major Renovations & Existing Buildings Environmental Procedure).

Federal agencies are instructed to "use site planning, design, construction, and maintenance strategies for the property to maintain or restore, to the maximum extent technically feasible, the predevelopment hydrology of the property with regard to the temperature, rate," for any project with a footprint that exceeds 5,000 square feet; approximately 71 feet by 71 feet (Section 438 of Energy Independence and Security Act of 2007 (EISA); EPA, Technical Guidance on Implementing the Stormwater

Region 8 Sustainability & Environmental Management System

Runoff Requirements for Federal Projects under Section 438 of the Energy Independence and Security Act, EPA 841-B-09-001, December 2009). Promote the use of decentralized stormwater management design strategies to maintain or restore site hydrology to pre-development conditions and promote water-efficient landscaping and irrigation strategies.

If stormwater impact potential exists, appropriate contracting documents need to address this concern, as ensured by the Project Manager or Contracting Officer:

- The Scope of Work, for construction projects
- The Performance Work Statement, for service contracts, such as the Grounds Maintenance and Snow Removal contract.

If needed, this information will be placed into any Change Request for Modification, if a contract needs modified.

- b. <u>Project Managers</u> will include an Erosion Control Plan where storm drains could be impacted. This plan is required for DFC projects and may be applicable for Leadership in Energy & Environmental Design (LEED) projects. An Erosion Control Plan is part of the DFC Excavation Permit commonly called the DFC Dig Permit, and is required for DFC projects: See GSA Region & Excavation 'Dig' Permit Environmental Procedure:
- c. The GSA Project Manager is responsible for the following aspects, relating to the DFC Dig Permit:
 - Submitting a completed Excavation Permit Request Form (see GSA Region 8
 Excavation 'Dig' Permit Environmental Procedure) to the EPG DFC Dig
 Permit coordinator, prior to the disturbance of any earth.
 - Conveying the information in the DFC Dig Permit to the contractor performing the excavation work and all other parties who may be involved with the excavation.
 - Delivering a copy of the DFC Dig Permit to the Contracting Officer, for the Contracting Project files.
- d. The <u>EPG DFC Dig Permit coordinator</u> will research and assess the potential for soil and groundwater contamination and then prepare the permit, detailing the depth to water and any necessary precautions. The permit is assigned a number, logged in the database, filed and a copy is provided to the GSA <u>Project Manager</u>.
- e. Once it is determined that a project will disturb soils of any amount, the <u>Contractor</u> is required to initiate precautionary measures, as detailed in the Erosion Control Plan, to prevent discharge of potentially contaminated storm water or other non-storm related waters directly into a storm drain. Precautionary measures include, but are not limited to, the installation of silt fencing, absorbent material such as fiber rolls, straw bales, gravel bags (see examples at the EPA "National Menu of Stormwater Best Management Practices" website; Attachment B).

Projects involving soil disturbance of one acre or more require that the Contractor

CONTRACT LANGUAGE DEVELOPED THAT REQUIRES E&SC PLANS



STORMWATER MANAGEMENT

Region 8 Sustainability & Environmental Management System

Runoff Requirements for Federal Projects under Section 438 of the Energy Independence and Security Act, EPA 841-B-09-001, December 2009). Promote the use of decentralized stormwater management design strategies to maintain or restore site hydrology to pre-development conditions and promote water-efficient landscaping and irrigation strategies.

If stormwater impact potential exists, appropriate contracting documents need to address this concern, as ensured by the Project Manager or Contracting Officer:

- The Scope of Work, for construction projects
- · The Performance Work Statement, for service contracts, such as the Grounds Maintenance and Snow Removal contract.

If needed, this information will be placed into any Change Request for Modification, if a contract needs modified.

- b. Project Managers will include an Erosion Control Plan where storm drains could be impacted. This plan is required for DFC projects and may be applicable for Leadership in Energy & Environmental Design (LEED) projects. An Erosion Control Plan is part of the DFC Excavation Permit commonly called the DFC Dig Permit, and is required for DFC projects: See GSA Region 8 Excavation 'Dig' Permit Environmental Procedure:
- c. The GSA Project Manager is responsible for the following aspects, relating to the DFC Dig Permit:
 - Submitting a completed Excavation Permit Request Form (see GSA Region 8 Excavation 'Dig' Permit Environmental Procedure) to the EPG DFC Dig Permit coordinator, prior to the disturbance of any earth.
 - Conveying the information in the DFC Dig Permit to the contractor performing the excavation work and all other parties who may be involved with the excavation.
 - Delivering a copy of the DFC Dig Permit to the Contracting Officer, for the Contracting Project files.
- d. The EPG DFC Dig Permit coordinator will research and assess the potential for soil and groundwater contamination and then prepare the permit, detailing the depth to water and any necessary precautions. The permit is assigned a number, logged in the database, filed and a copy is provided to the GSA Project Manager.
- e. Once it is determined that a project will disturb soils of any amount, the Contractor is required to initiate precautionary measures, as detailed in the Erosion Control Plan, to prevent discharge of potentially contaminated storm water or other non-storm related waters directly into a storm drain. Precautionary measures include, but are not limited to, the installation of silt fencing, absorbent material such as fiber rolls, straw bales, gravel bags (see examples at the EPA "National Menu of Stormwater Best Management Practices" website; Attachment B).

Projects involving soil disturbance of one acre or more require that the Contractor

E&SC PLAN APPROVAL CRITERIA

See previous page.

CONSTRUCTION SITE INSPECTION PROCEDURES

STORMWATER MANAGEMENT



Region 8 Sustainability & Environmental Management System

prepare a stormwater management plan and submit the Notice of Intent (NOI) form to the EPA. Additionally, the Contractor will submi EPA NPDES Form 3510-9 to the EPA and a Storm Water Management Plan (SWMP) to the Project Manager or EPG at the GSA. The Contractor must comply with the NOI requirements, including the Stormwater Prevention Plan, for the duration of the project. The contractor is required to submit the NOI number to the SEMS Project Team for recording. The EPG or COR will conduct and record inspections of these projects on a regular basis.

Upon completion of the project, the Contractor will request a Notice of Termination (NOT) inspection. The COR or an agreed upon 3rd party will inspect for the NOT and check whether or not the SWMP and NOI requirements have been met. Once the inspection is complete and the NOT is approved, the Contractor will submit a Notice of Intent to the EPA and COR, if necessary.

- f. Discharged water shall be directed away from all curbs and other areas where storm drains may exist.
- g. Discharging non-storm water to lawn areas, open areas, or into a Baker tank truck, is considered acceptable practice. However, the Contractor must install protection around all of the storm drains which could be impacted.
- h. GSA Project Managers will maintain oversight and conduct weekly inspections on any project requiring storm drain protection measures, to check the integrity of the protective measures and to ensure at the completion of the project that any observable material is removed from the storm drain area. Inspections are documented on the EPG, Excavation Permit: Excavation Inspection Report form (see GSA Region 8 Excavation 'Dig' Permit Environmental Procedure).
- i. Upon completion of the project requiring the discharge of water, storm drain protection should be removed by the Contractor and it should be noted in the project
- j. Contractors are required to adhere to the project design criteria as established in the design documents for the control, retention and detention of post construction runoff during storms and the removal of suspended solids from runoff.

6.4 Accidental and Deliberate Discharge Detection and Elimination:

- a. Contract language will dictate the preventive measures required to be implemented by Contractors working at GSA facilities in order to avoid non-storm water discharges entering the storm sewer system. This will be ensured by the Project Manager or Contracting Office.
- b. The Contractor is responsible for ensuring that their personnel are appropriately trained and compliant with these requirements. GSA Project Managers and CORs are responsible for monitoring contractors' performance and compliance.

STORMWATER MANAGEMENT

Region 8 Sustainability & Environmental Management System

ATTACHMENT C: Construction Site Inspection Form

	OVERALL CONDITION (Good, Fair, Poor)	NEED REPAIR? (Yes, No)	COMMENTS
	STRUCTU	JRAL MEAS	URES
Sediment Containment Systems			
Hay Bale Barriers	- 2		
Silt Fence Barriers			
Rock Barriers			
Inserts			
Vehicle Tracking Pad			
	NON-STRUCTURA	L MEASURE	S and/or Swales
Diversion Dikes and/or Swales		4 5	
Slope Drains			
Temporary Vegetation			
Perennial Vegetation			
Mulch and/or BFM Protection			
Soil Binder Protection			
Hillside RECPs	Local Control		
Drainage Channel TRMs			
Riprap and/or Gabions	Te		

Will existing BMPs need to be modified or removed or additional BMPs installed? Y/N If Yes, list the action items to be completed on the following table.

ACTIONS TO BE COMPLETED	DATE COMPLETED

STORMWATER MANAGEMENT
Region 8 Sustainability & Environmental Management System

Weather information since the last inspection was held.

EVENT	DATE BEGAN	DURATION (Hours)	AMOUNT (Inches)
	Contract to		
			E 23 E E E

	1 7 1.1					
						-
re non compliance incidents evident? yes, describe:	Y/N					
dditional Comments:						
	the state of the S					
				No.		
	*					
gnature:				-		
dapted from Denver Federal Center,	Deaft 1 Sto	rm Water	Manageme	nt Plan Cl	anter 5 M	av 2005
dapted from Deliver Federal Center,	Dian I Siu	HIII WALCI	Manageme	in Fran Ci	iapiei 3, ivi	ay 2003

COMPLETED INSPECTION FORMS

CONTRACT LANGUAGE REQUIRING POST-CONSTRUCTION STORM WATER MANAGEMENT

STORMWATER MANAGEMENT Region 8 Sustainability & Environmental Management System

prepare a stormwater management plan and submit the Notice of Intent (NOI) form to the EPA. Additionally, the Contractor will submi EPA NPDES Form 3510-9 to the EPA and a Storm Water Management Plan (SWMP) to the Project Manager or EPG at the GSA. The Contractor must comply with the NOI requirements, including the Stormwater Prevention Plan, for the duration of the project. The contractor is required to submit the NOI number to the SEMS Project Team for recording. The EPG or COR will conduct and record inspections of these projects on a regular basis.

Upon completion of the project, the Contractor will request a Notice of Termination (NOT) inspection. The COR or an agreed upon 3rd party will inspect for the NOT and check whether or not the SWMP and NOI requirements have been met. Once the inspection is complete and the NOT is approved, the Contractor will submit a Notice of Intent to the EPA and COR, if necessary.

- f. Discharged water shall be directed away from all curbs and other areas where storm drains may exist.
- g. Discharging non-storm water to lawn areas, open areas, or into a Baker tank truck, is considered acceptable practice. However, the Contractor must install protection around all of the storm drains which could be impacted.
- h. GSA Project Managers will maintain oversight and conduct weekly inspections on any project requiring storm drain protection measures, to check the integrity of the protective measures and to ensure at the completion of the project that any observable material is removed from the storm drain area. Inspections are documented on the EPG, Excavation Permit: Excavation Inspection Report form (see GSA Region 8 Excavation 'Dig' Permit Environmental Procedure).
- i. Upon completion of the project requiring the discharge of water, storm drain protection should be removed by the Contractor and it should be noted in the project
- j. Contractors are required to adhere to the project design criteria as established in the design documents for the control, retention and detention of post construction runoff during storms and the removal of suspended solids from runoff.

Accidental and Deliberate Discharge Detection and Elimination: 6.4

- a. Contract language will dictate the preventive measures required to be implemented by Contractors working at GSA facilities in order to avoid non-storm water discharges entering the storm sewer system. This will be ensured by the Project Manager or Contracting Office.
- b. The Contractor is responsible for ensuring that their personnel are appropriately trained and compliant with these requirements. GSA Project Managers and CORs are responsible for monitoring contractors' performance and compliance.

INITIAL AND REFRESHER STORM WATER MANAGEMENT TRAINING ROSTERS

DFC MS4 Permit Training 6/24/2011

Printed Name Signature Telephone Bill Fieulman Bill Fieselman 303-236-2516 303-204-0604 Cana a f Jana Faris Amcko Or 303-236-2858 John Kleinschmidt Sam Bade Georgnitec 617-992-9067 303-236-2547 Stephunce) Stephanie Downs CULTIS BERG (ud Ba 303-236.288 303-236-2743 Robert J. Melvin Rober J Meli: 303-236-2808. LIBA WILD Lluc lel 303-236-4616 KRISTI LEINEN down !

Environmental and NEPA Training

Environmental and NEPA Training

Floodplains, Wetlands, Storm Water And Endangered Species

GSA R8 NEPA, DFC Environmental Group, and ERO Resources, Inc., a natural resources consulting firm, will present an overview of GSA's approach to floodplains, wetlands, storm water and endangered species management for our real estate projects. This class will provide an introduction to these natural resource management areas and provide definitions of terms, regulatory requirements, GSA's screening and compliance process, as well as a general understanding of why and how these natural resources are protected under Executive Orders and Federal Laws.

This class is open to everyone and is especially pertinent for Realty Specialists, Project Managers and Building Managers.

When: Thursday, March 8, 2012 8:30 a.m. – noon

Where: Colorado Room

The training session will also be available on Webex. Please see your supervisor for an invitation.

*Please contact Lisa Haskins at (303) 236-2414, if you have any questions.



U.S. General Services Administration .

Sign-In Form

Wetlands, Floodplains, StormWater Management and Endangered Species
Training
March 8, 2012

March 8, 2012 8:30 am – 12 pm

Name	<u>Organization</u>
Robert J. Melvin	RUA CRWT)
Bill Fieselman	GSA CPWT)
LIBA WILD	G=A
Robert Schlattman	GSA
Dan Milherson	GSA 8PSC
Ane John	DPC
4	& BOPP
Lance Thompson	GSA FMSP
Sharon Malloy	
Margaret Danton	GSA (PWT)
Mark Baca	GSA
Christy Fookler	GSA
Charlie Petergen	GSA-MPSC
Knistin Howes	GSA-CSC
1/ Swaln	GSA-(rag)-MPSC
Shristan Shingard	
Suspina Davis	GSA (MPSC)
JASON HESSLING	GSA (MPSE)
J 877014 11 - 2771110	

Michelle Hotaling Most levesque Alex Secor Sanah Neujaha ANY Walleyn Russ Furry Will McAllister Brent Carlile ROBERT J. KIPPER Verna McCain JERM C. Callrey Ryan Lindberg Andrew Myers Michael LoLenda avenlenier Jack Cosper Kullas Brenda Haar Richard Hagmann bert Gauz adrience Heech Tasmin Biondi Tanya Burks

Adam Bankin

8PSM - mt Plains EPSM - Mt Regis 8P2PR 8PSM - Mt Plains SPIPT - Portfolio Magnit. 885D PBS/EPG Client Solutions GSA-CSC OPSM- MPSC EPSC-CSC 815011) -8PSM-MPSC 8PC-69A GSA CSC 8 PSHWS 8 DSHWS 8PHPM-C

8P/ PT-C

8P5M

8 PSC

8PSD



Contracting Officer SEMS Environmental Procedure Training

Created by: Lisa Haskins (8P2PM) · Your response: ✓ Yes, I'm going

Time

9am - 10am (Mountain Time)

Date

Wed Jul 18, 2012

Where

Colorado Room

Description

SEMS Program Managers will present their flowcharts (environmental procedure process) to Contracting Officers at CAM Meeting

We are in the process of determining which Program Managers will present at the specific training sessions for COs, PMs, Building Managers and Contractors - I am inviting all at this time but will remove your name if you do not need to present for specific sessions.

My Notes

Guests

- ✓ Andrew Olsen (8P2PM-C)
- ✓ Charles Rienhardt (8PSDPD)
- ✓ Lisa Haskins (8P2PM)
- ✓ Marion Buntyn (8P2PM)
- ✓ Michael Gasser (8P-C)
- ✓ Patrick Haze (8PSD)
- ✓ Robert Melvin (8P2PM-C)
- ✓ Sharon Malloy-Standbridge (8P2PM)
- ✓ Tammy Eatough (8PSMW)
- ✓ William Fieselman (8PSD-C)
- ? John Kleinschmidt (8PSDW)
- O Christina Fockler (8PC)
- Ø Mark Baca (8PSDPD)
- @ Randi Heller (8PSMW)
- Ø Thomas Record (8P2PM)
- Anne Laporta (8P2PM) (Speaker) Jessica Higgins (8P2PM)

Laura Magee (8PSD)



Region 8 SEMS Contracting Officer Training July 18, 2012 9:00am – 10:15 am 10:30 Please sign-in to document your completion of this training

Name	Organization	Signature
Lee Davis	MPSC	The state of the s
Trane Richardson	8P2PQ_(AMO)	Top Sec
Beverly Carly	8PSD	Beberly & Carey
min whitenberg	8PSD	Mure Isheiterper
Lathy Firwin	8P50	Janky Kging
Bub Marche	8PSC	Quebn, latthe
Len witzen	8PSC.	Len Welan
Tannis Taylor	8PSC	Taujis Taylor
Jameson HWHON	8PSC	
Jamie Blue	&PSC_	() miffle
Kenya Freeman	8PSC.	Kingatherman
Jill long	Brspp	Just fort of
Pennie Estrada	8 Q	Pound Boliana
Dylan White	805 MPSC	Dogla While
Judith Line	8 PCM	Jaguet Luni
Gloria Galleges	8PCM	Sprin fallegas
Angel Cohen	8 PCM	Angel Cohen
Nicole Friesen	8PCM	Musin
Haron Adams	8PCM	Claron Cylanis
David Carso	8PSD	Dadala
Robert J. Melvin	Braph	Nober pralie
Milec Gasser	4 1	m
Charlie Kienhardt	and the second s	Chil
Miriam Babcock	8Papa	Minam Babcock
Amy Lineberry Stephen Newton	& PSMP	ling
Stephen Newton'	8PC P	
Shirley Howington	8PSM	Thirty flowington
MONIQUE LICHY	8t5M	my lange
Darlene Gonzales	8 psm	C. Bonzalel
TAMMY EATOUGH	8PSM	Samiy Collace
Robert Collins	8PCP	Karl E Collins



Name	Organization	Signature
ROBERT J. KIPPER William Hartley Bill Fieselman Mike Gasser	805 K 81501 81501	Rapid & Riggins
Charlie Rienhardt	8PSD	Chal C
		,
160.5		Sami Augusti

ATTENDANCE LIST updated June 2012 Contracting Associates Meeting Training Subjects: Miscellaneous Acquisition Updates and protests)ate July 18, 2012 (Initial by your name to indicate attendance or add your name if not listed) Ini. Ini. Name Ini. Name Name 1.0. Casper Field Office Laura Magee Aaron Adams North Dakota Field Office Lee Davis Amy Lineberry South Dakota Field Office Len Wilson Angelica Cohen Utah Field Office Lorraine Douglas Anne LaPorta Wyoming Field Office Barbara Marthe Montana Field Office Benjamin Rissky Mire-Medina-Whittenburg GXY NA BAC-Miriam Babcock Beverly Carey Monica Divelbess MI Monique Tucny Christopher Cole Cindy Andersen Christine Steger Nicole Friesen Cody Lee Dan Bush Orlando Mendez Courtney R. Westlie 20 Heidi Sawyer Dannie Crowder Pamela Burley Joseph Dorsey Darlene Gonzales DAL Kay Thompson David Carson Pennie Estrada Raymond Panaguiton Kenneth Moore David Chavez Michael Smith Rhonda Nelson Dawn Perea 流 Robert Collins Nicole Haines Dylan White Pamela Ballard Robert Kipper Ray Lewis Rod Keiscome Ed Marin Shana Budd Roger Kubik Gloria Gallegos Steve Farrington Steve Nichols Sarah Huddle Jamie Blue Shanon Sweeney Susan Brunner Jameson Hutton MARION BUNTYA Shantelle L. Brungardt Janett Worthy Shawna Horvath Jean Schilling pull Shirley Howington Jeffrey Rich Shonita Mueller Jennifer Canfield Jerry Silver Stephen Newton Steve Eckelberg Jessica Pasicznyk Susan Protho Jessica R. Pimentel THIMMY ENTOLEEST 139 Jill Long is Tannis Taylor Joan Amend Tracie Richardson 112 Judy Line Tracy Troncosa-Maes William Hartley Kathy Kirwin Kelly Rima Kenya Freeman Kristen Feickert



Building Manager SEMS Environmental Procedure Training

Created by: Lisa Haskins (8P2PM) · Your response: ✓ Yes, I'm going

^{Time} 2pm - 3pm (Mountain Time)

Date Thu Jul 26, 2012

Where Red Rocks

Description

The following procedures will be presented in this order at the Building Manager's training - if you are not listed, you do not need to attend:

Green Purchasing - Marion Buntyn Recycling and Universal Wastes - Marion Buntyn Facility Solid Waste - Marion Buntyn Construction Demo - Waste - Marion Buntyn Chemical Storage and Disposal - Mike Gasser Spill Response - Mike Gasser Sanitary Sewage Discharge - Mike Gasser Stormwater Management - Bill Fieselman Asbestos Management - Buddy Alkire Grounds Maintenance - Chemical Usage - Mark Baca Excavation Dig Permit - Mike Gasser Pre-Demolition Inspection - Mike Gasser Underground Storage Tanks - Mike Gasser Site Remediation - Mike Gasser 90 Day Storage - Spill Response - Mike Gasser Indoor Water Intrustion - Mike Gasser Cross Connection Incident and Prevention - Mark Baca

Guests

- ✓ Andrew Olsen (8P2PM-C)
- ✓ Anne Laporta (8P2PM)
- ✓ Charles Rienhardt (8PSDPD)
- ✓ John Kleinschmidt (8PSDW)
- ✓ Lisa Haskins (8P2PM)
- ✓ Marion Buntyn (8P2PM)
- ✓ Michael Gasser (8P-C)
- ✓ Randi Heller (8PSMW)
- ✓ Robert Melvin (8P2PM-C)
- ✓ Sharon Malloy-Standbridge (8P2PM)
- ✓ Thomas Record (8P2PM)
- ✓ William Fieselman (8PSD-C)
- Charles Carruth (8PSDPD) I'll be on vacation,
- Ø Christina Fockler (8PC) I am out of town that week
- Laura Magee (8PSD)
 Off-site training
- @ Mark Baca (8PSDPD)
- Tammy Eatough (8PŚMW) Harold Alkire (8P2PM) Jennifer Martinez (8PSD) Jessica Higgins (8P2PM) Patrick Haze (8PSD)

Grounds Maintenance Water Use - Mark Baca
Boiler Emissions - Tom Record
Chiller Emissions - Tom Record
Energy and Water Management - Andrew
Olsen/Charlie Rienhardt
Indoor Air Quality - Complaint/Garage - Tom Record
Drinking Water - Tom Record
Sara Title III - Tom Record
Design Review - Sharon Malloy

My Notes



Region 8 SEMS Property Managers Training July 26, 2012 2:00 pm – 3:00 pm

Please sign-in to document your completion of this training

Name	Organization	Signature
Charlie Renlard	- 6SH-PRS	Wales Prople
Michael belends	bsa Pas	M-A Ali
ANDREW OLSEN	GSA PBS	Children 1
Bill Fieselman	65A PBS	Bell Jankman
Jennifer Martinez	GSA TBS	The Millian Cust
Dinice Pachece	CYSH PBS	Windlest & Par
Camie Perdomo	OSA	Gamio Ladono
Dana Danning	650	Charles of A
RICHARD SAIZ	6-54	Hony lily
RICHARD SAIZ	Arcanum for GSN	
MARion BUNTYN	GSA	manylogenty
	,	
4 4 5		
1.11.2		
,		
		. The same

R8 SEMS DFC Contractor Training

Created by: Lisa Haskins (8P2PM)

Time

8am - 12pm (Mountain Time)

Date

Thu Aug 2, 2012

Where

Remington Arms - Call In: 888-595-8957, #9525900

Description

The following procedures will be presented in this order at the DFC Contractor training - if you are not listed, you do not need to attend. The presentation will be set up and ready for you so you do not need to bring anything. Please be on time so we can start promptly at 8am. It is expected we will be there until @10am.

Green Purchasing - Mark Baca
Recycling and Universal Wastes - Mark Baca
Facility Solid Waste - Mark Baca
Construction Demo - Waste - Mark Baca
Chemical Storage and Disposal - Mike Gasser
Hazardous Waste Management - Mike Gasser
Spill Response - Mike Gasser
Sanitary Sewage Discharge - Mike Gasser
Stormwater Management - Bill Fieselman
Asbestos Management - Buddy Alkire
Grounds Maintenance - Chemical Usage - Mark
Baca
Excavation Dig Permit - Mike Gasser
Pre-Demolition Inspection - Mike Gasser
Underground Storage Tanks - Mike Gasser
Fugitive Dust - Mike Gasser

Guests

- - ✓ Charles Rienhardt (8PSDPD)
 - ✓ Laura Magee (8PSD) Call In
 - ✓ Lisa Haskins (8P2PM)
 - ✓ Mark Baca (8PSDPD)
 - ✓ Michael Gasser (8P-C)
 - ✓ Patrick Haze (8PSD)
- ② epetrovskis@geosyntec.com
 - O Christina Fockler (8PC)
 - @ Harold Alkire (8P2PM)
 - Ø John Kleinschmidt (8PSDW)
 - Marion Buntyn (8P2PM)
 - @ Randi Heller (8PSMW)
 - Sharon Malloy-Standbridge (8P2PM)
 - @ Tammy Eatough (8PSMW)
 - Thomas Record (8P2PM)
- David Williams (8P2PM)
- Jana Faris (8PSD)
 - Andrew Olsen (8P2PM-C)
 - VAnne Laporta (8P2PM) Speaker Vessica Higgins (8P2PM) Speaker Robert Melvin (8P2PM-C)
 - William Fieselman (8PSD-C)

Site Remediation - Mike Gasser
90 Day Storage - Spill Response - Mike Gasser
DBMS - Mike Gasser
Indoor Water Intrustion - Mike Gasser
Cross Connection Incident and Prevention - Mark
Baca
Grounds Maintenance Water Use - Mark Baca
Boiler Emissions - Tom Record
Chiller Emissions - Tom Record
Energy and Water Management and Metering Andrew Olsen/Charlie Rienhardt
Indoor Air Quality - Complaint/Garage - Tom Record

My Notes



Region 8 SEMS DFC Contractor Training August 2, 2012 8:00 am -12:00 pm

Please sign-in to document your completion of this training

Name	Organization	Signature
RUSSIAL SCHEME	ALEXT	Lasel Call
Brink Bodney Aleks Potahine	PM-Services	ABANNES MINE
Greig Branis	PM Services	Bengalson
Alfreda Jones	AJ'S CLEANING	College D
Maggie Williams	AJSClenning	avs
Deson Willis Deunis Gray	Citmore Court	
Ponnie Allry	Termini	Donni alley
Henry Estrate	Terminis	Agen
RICHARD SAIR	Arcanum	Le O F
KONNETH JACKSON	KCORP	2 years
Dana Dennine STONE SCOTTING	Alien +	Jon Start
Daniel Tomkinson	Sparker Warner	Daniel Touteran
Vince Oan	RME	Mas
Lawa Coylez	Aspen Pointe	Carry Corter
Change Kur hardt	85A A13 MC. C	Double & Marie
Touch of AME		
Chaine Flourtu	ATI-Oleaning	Min Vafor
Tim Hancock	Topse (C	1042 A.U
		4



Stormwater Management and Compliance at the Denver Federal Center Training

<u>Name</u>	<u>Organization</u>	<u>Email</u>
Cody Wennet	Joppa	
Complete Complet	I-Ipa RME	
AARON SUNK	RME.	
Bruce Johnson	GSA	
LORAN BARTOW	65A	losanihardow@gsaigov
RIGE DAROURS	GSA	
Mike Caw	GSA PWT	
Salvador Quezada Corrios Agala	RME	
	RME	
Joshua Schultz Curtis Schultz	RME	
Michael Alosi	RMEA GSA	
1960 LOWE	Hudspeth &	Associates



Stormwater Management and Compliance at the Denver Federal Center Training

Name	Organization	<u>Email</u>
Troy ENGOR	954	Troy, ersone 95A.gov
Jamie Perduno	684)	jamie perdomo agsorgas nizolos ivetelatteresa su
Niz Netslaff	GSX	Missles installed by
James De Moye	Korp	James. demoyer gsA. 60V
James Dell'		



Stormwater Management and Compliance at the Denver Federal Center Training

<u>Name</u>	Organization	Email
tale Stevens	SOPPA	
Jose C.Canille	Joppan	
AARON NEWBELL	Joppa	
Obsau Encilia	Coppa	
PAUL MARLIN	STURGEON	
Stern Shaples WILL IAM FORSTETI	Joppa	
WILL IAM FORSTEPV	MAGOU	
Adam Rankin	GSA	aden, rankin @ 959.90
Terry Potta Justin BANILS	Aleut	
Justin BANK	plat	john. hvebnerægsa.gov
JOHN HUEBNER	GSA	
Margaret Daultan	GSA	Margaret daultonegsa.gov
Clay KAGARITE	Aleut	Clayton, KAGARISE C 95A. 90V
Robert Melvin	GSA/PWT	robert. melvin@gsa.gov
PICHARD SAIZ	ARCANUM FAR	richard. saiz en 954. Jau



Stormwater Management and Compliance at the Denver Federal Center Training

Name	Organization	<u>Email</u>
Tim Hancock	Zoppa	tim.hancode @ joppa maintenance com
Jaul Rivera	JOPPA	Paul. Rivera @ Jospa maintonner. @
Michael Wilson	Joppa	
Josh Kammerlohr	Joppa	josh. Kamaerlohr@joppa maintenance.com
Patrick Campbell	654	patrick. campbellagsn.gov
Vince Dem	RME	vircent dean Orneche.com
GARY Beyers	5 W E	
Chalie Carr	oth Ost	
Mark Baca	GSA	
Oh b	- GSA	Chales. TORMAN & 950.90
Dha	Oclant	
Frank Lovato	Hont	
RUBEN VASQUE		
Jennifer Martir	rez GSA	



Stormwater Management and Compliance at the Denver Federal Center Training

<u>Name</u>	Organization	<u>Email</u>
Asson Way	614	AARON. WAS 6 G. M.S. COV
Dana Denning Randall Sjulstad	65A	Dana. Denning @ 65A. 60V [andall. SinlsTad@ 95A.gov
Bret Connichael	RIDE	
Brandon Jacketta	RME	
MckHastings	RME	
LyAN Strub Jeriney Englid	GSA	Jeffrey Engell Q 9501.900
Dan Zigich	PWT	daniel. zigich @gsa.gov
Denice tacher	co ESIA	denice. Pacheco@ gsa gov
Land Thompson	GSA	Michael golanda @ 950, 900
11/1/	65A	Michael golenda @ 950,00

Storm water run off training



Training:Storm Water				
Date:_11/_14/2013				
Printed Name	Signature			
1. Milhael Ditommuso	pelled forces			
2. DANIEL ANDREWS	Dulmos			
3. Lavil Mive on	hotal to			
4 Dale Stevens	CRI. A			
5. Monica Todocov	Morina looking			
6. Josh Kammerlohr				
7 AARON NEWBILL	on fubill			
8. LSSAC BAKE 105	15			
9. 1030 (Conlle.	1 JURIDAN CANTIL			
10. Kennell J. Keling	Render N. Kultur			
11. Stan Encin's	CK 11-			
12. Echap Smith	Colored Vo			
13. Palet York	Mash -			
14.	The state of the s			
15	V			

Project Manager Signature:



Stormwater Management Training

1 message

All -

Stephanie Downs - 8PSD < stephanie.downs@gsa.gov> Wed, Nov 19, 2014 at 12:28 PM To: Margaret Daulton - 8PSDPD-C <margaret.daulton@gsa.gov>, Nicci Pagano - 8PSDPD <nicci.pagano@gsa.gov>, Bruce Johnson - 8PSDPD <bru>bruced.johnson@gsa.gov>, Michael Golenda <michael.golenda@gsa.gov>, Charles Carruth <charlie.carruth@gsa.gov>, Charles Turman - 8PSDPD <charles.turman@gsa.gov>, Patrick Campbell - 8PSDPD <patrick.campbell@gsa.gov>, John Huebner <john.huebner@gsa.gov>, Shawn McCoy - 8PSDPD <shawn.mccoy@gsa.gov>, Adam Rankin - 8PSDPD <adam.rankin@gsa.gov>, Ian Willard - 8PSDPD <ian.willard@gsa.gov>, Lance Thompson - 8PSDPD <lance.thompson@gsa.gov>, Jennifer Martinez <jennifer.martinez@gsa.gov>, "J. Denice Pacheco" <denice.pacheco@gsa.gov>, Richard Saiz - 8PSD-C <richard.saiz@gsa.gov>, Jamie Perdomo - 8PSDPD <jamie.perdomo@gsa.gov>, Harvey Wong <harvey.wong@gsa.gov>, Joe Fuentes - 8PSDP <ryan.strub@gsa.gov>, Dana Denning - 8PSDPD <dana.denning@gsa.gov>, Gary Sebastian - 8PSDP <gary.sebastian@gsa.gov>, Paige Jacques - 8PC <paige.jacques@gsa.gov>, Loran Bartow - 8PSDP <loran.bartow@gsa.gov>, Nicolas Retzlaff <nicolas.retzlaff@gsa.gov>, Michael Alley - 8PSDP <mike.alley@gsa.gov>, Troy Eason - 8PSDP <troy.eason@gsa.gov>, Jeffrey Engelstad <jeffrey.engelstad@gsa.gov>, Gary Peterson - 8PSDP <gary.peterson@gsa.gov>, Robert Melvin - 8P2PM-C <robert.melvin@gsa.gov>, John Kleinschmidt <john.kleinschmidt@gsa.gov>, Michael Gasser <michael.gasser@gsa.gov>, William Fieselman <william.fieselman@gsa.gov>, Michael Alosi <michael.alosi@gsa.gov>, Douglas Baughman - 8PSDP <doug.baughman@gsa.gov>, Robert Kirkpatrick <robert.kirkpatrick@gsa.gov>, Dan Zigich Zigich - 8PSDW-C <daniel.zigich@gsa.gov>, Kristi Leinen <kristi.leinen@gsa.gov>, Lisa Wild lisa.wild@gsa.gov>, Charles Rienhardt <charles.rienhardt@gsa.gov> Cc: Curtis Berg <curtis.berg@gsa.gov>, Jana Faris <jana.faris@gsa.gov>

You are required to view the Stormwater Management Training video by December 31, 2014.

Once you have finished watching all four parts of the Stormwater Management Training, please document that you have viewed the videos by completing the electronic sign-in sheet here.

The Stormwater Management Training video can be found at http://www.gsa.gov/portal/content/114575#videoContainer.

Navigating the Storm Water & Wetland Management Webpage

- Find "Stormwater Training" in the bottom 1/3 of the page
- Click to view the video

The purpose of this training is to comply with the requirements of the DFC Municipal Separate Storm Sewer System (MS4) Permit issued by the U.S Environmental Protection Agency. Thanks to Bill Fieselman for putting this training together!

Stephanie G. Downs U.S. General Services Administration Director,

2014 STORMWATER MANAGEMENT TRAINING ATTENDEE LIST

- . ,	I watched all four parts of the Storm Water Management Training Video	I I a a mara mara
Timestamp		Username
11/19/2014 14:06:37	Yes	mike.alley@gsa.gov
11/19/2014 14:18:16	Yes	adam.rankin@gsa.gov
11/19/2014 14:18:33	Yes	adam.rankin@gsa.gov
11/19/2014 15:37:58	Yes	shawn.mccoy@gsa.gov
11/19/2014 15:49:22	Yes	lance.thompson@gsa.gov
11/19/2014 16:02:05	Yes	harvey.wong@gsa.gov
11/19/2014 17:54:39	Yes	margaret.daulton@gsa.gov
11/20/2014 10:15:35	Yes	daniel.zigich@gsa.gov
11/20/2014 15:28:30	Yes	bruced.johnson@gsa.gov
11/21/2014 9:10:17	Yes	patrick.campbell@gsa.gov
11/21/2014 9:37:26	Yes	charlie.carruth@gsa.gov
11/21/2014 16:26:27	Yes	jamie.perdomo@gsa.gov
11/23/2014 18:55:20	Yes	john.kleinschmidt@gsa.gov
11/24/2014 7:51:58	Yes	dana.denning@gsa.gov
11/24/2014 12:56:56	Yes	charles.rienhardt@gsa.gov
12/1/2014 10:43:37	Yes	jeffrey.engelstad@gsa.gov
12/5/2014 14:11:18	Yes	michael.alosi@gsa.gov
12/10/2014 6:03:56	Yes	dana.denning@gsa.gov
12/10/2014 9:16:44	Yes	william.fieselman@gsa.gov
12/11/2014 5:42:31	Yes	adam.rankin@gsa.gov
12/17/2014 9:16:25	Yes	loran.bartow@gsa.gov
12/22/2014 9:47:23	Yes	paige.jacques@gsa.gov
12/29/2014 9:31:17	Yes	gary.sebastian@gsa.gov
12/30/2014 12:34:37	Yes	nicci.pagano@gsa.gov
12/30/2014 14:12:59	Yes	nicolas.retzlaff@gsa.gov
12/31/2014 16:37:44	Yes	john.huebner@gsa.gov
1/2/2015 14:16:05	Yes	carlos.valenzuela@gsa.gov
1/5/2015 9:42:34	Yes	clayton.kagarise@gsa.gov
1/8/2015 12:55:44	Yes	robert.kirkpatrick@gsa.gov



Green Infrastructure and Low Impact Development Training Workshop for Denver Federal Center

February 25, 2015 9:00 – 11:00am

Chris Olson, PE



Colorado State University

Sign-In Form

Name

Adam Rankin
Bruce Johnson
Ian Willard
Robert Melvin
Patrick Campbell
Jennifer Martinez
Dan Zigich
Charles Klauhardt
KRISTI LEINEN
De Frendes
Hang Wong

Christopher Alder James de Moye Bill Fieselman <u>Organization</u>

GSA 8PSD

GSA 8PSD GSA 8PSD

QSA / The Arcanum Group

GSA 8PSLPD GSA /PBS

6SP/PBS

GSA/PBS

GSA/PBS

Horroy Warg

GSA 8P2PM

KORP GSA/TAG Email

adam. runkin 09

bouced. Jamson egsa. gov

robent. melvin @gsa.gov

portricks campbell agsA.gov jennifer. martine 2 Qgsa.gov daniel. zigivh Qgsa.gov

Charles, Runhand + @ GSA. 60

KRISTI. LEINEN@CISA. GO

Joe Funto @ gs. gou

Alarvay, wong @ 951: gov

christopher, alder e gso. son James, demoye e gsa. gov William, fieselman e gsa. gov



Green Infrastructure and Low Impact Development Training Workshop for Denver Federal Center

February 25, 2015 9:00 – 11:00am

Chris Olson, PE



Colorado State University

Sign-In Form

Name Organization Email GSA/PBS PATRICK HAZE partick. haze@gsa.gov margaret. daulton e GSA/PBS The Arcanum Group Margaret Daulton Shawn Mccay Qgsa.g.v GSA IPBS/Team 4 Shawn Mc Coy JohnKleinschmict john. Kleinschmidta GISA (PBS/EPG 950.900 GSA (PBS CHARLES TURMAN Charles . TURMAN & 95A. 90 PMSC/ DOS-Michael S. Heinson Mhanson @ Puservices Company, net CARLOS Valenzuela Aleut CARLOS. Valenzuela @ GSA. GOW Steve buthrie PM Services Stathica Pan Gut42003W York Jame Perdono GSA jamie, perdomo Ogsa.gov Mike Gasser (75A Michael gasser@ 859, 500 JOHN HUEBNER john. huebner@gsa.gov Stephante Downs 684 Stophanie Druns @ 959. for Robert. killputneh & gsa. son ROBERT PIRKEMEN 65A



Green Infrastructure and Low Impact Development Training Workshop for Denver Federal Center

February 25, 2015 9:00 – 11:00am

Chris Olson, PE



Colorado State University

Sign-In Form

Organization

N. Poron C150 Hleut Terry Potter Kathy Firwin GSAIPBS PBS Mizhael Alori 6SA/BBS Loran BARTOW Alent Clayton KAGARISE PICHARD SAIZ ARCANUM GOA Denne tacheco 6SA Gregory Williams 05M TRAT EASION Dana Denning 6-SA Sharon Malloy GSA LISA WILD 15A

Email

Temy, Potters 65A.60V

Kathy, Kirwin @gsa, gov

Mizhael, alogi @gsa, gov

Ioran, bartow &gsa, gov

Clayton, Kajaviso & GSA, 60

denice Pacheco @ ssa gov gregory. Williams@gsq.sov

TROY [Asone gsa gov

Dena. Denning o gsa.gov Sharon malloy Ogsagov Isa. wild Q gsa.gov

LANDSCAPING AND LAWN CARE PROGRAM

PEST CONTROL PROGRAM

Bill I have the Pesticide
Application records for the
base year of the Contract
in my Fites,
There are to many pages to
copy + provide to you unless
you need them in your
files. Let me know if I
need to copy them
Bruce
This Requirement would meet
paragraph C. 5. 19. 4.1 of the
contract



Alex.

Training: Chemical Disposal and Stormwater Runoff - C.S. 4.19.4.e

Date: 11/2013 1/21/14 Supposed to be "g"

	9
Printed Name	Signature
1. Josh Kammerlohr	Josh Kammerlohn
2. Mike Wilson	With Ne
3.	(*** (***
4.	
5.	
6.	
7	
8.	
9.	
10.	
11.	
12.	3
13.	
14.	
15.	

Project Manager Signature:

2013 PHC Treatment Booklet

C.5.4.19.4.h

Safe Pesticide Use

Davey Pesticide Policies

Ask your district/account manager for a current copy of Davey's risk reduction policies.

Strict adherence to using clean and maintained PPE, purchasing and using lower risk pesticide products and using Davey Engineering Controls at each facility is required.

- 1. Pesticides used by Davey personnel must be approved for use under Plant Health Care (PHC) guidelines developed by the Davey Institute. All PHC materials are ordered only on basis of actual need. Appropriate Davey guidelines must be met in the selection of materials.
- A non-PHC pesticide may be purchased, in limited quantities, for specific job situations. However, authorization <u>must</u> be obtained from your operations manager <u>and</u> assigned technical advisor. Local purchases of approved pesticide formulations are authorized by contacting the Purchasing Department.
- 3. All pesticides and fertilizers must be stored according to label recommendations and material safety data sheets (See "Pesticide Storage and Disposal" section).
- 4. The contents of opened containers must be completely used before others of the same material are opened.
- 5. <u>All</u> pesticide containers are to be kept properly labeled with legible labels, including hand sprayers, backpack tanks, etc.
- 6. Unusable pesticides must be disposed of through an EPA or state licensed disposal facility. Violation of federal and state pesticide disposal laws are enforceable by fines and jail sentences. Contact the Davey Institute for assistance whenever you have a question about the use or disposal of pesticides.
- 7. Pesticides must always be transported in an appropriate manner. Never transport pesticide materials within a service vehicle cab.
- 8. Liquid or granular pesticides must be secured or contained with sideboards. It is not permitted to secure granular bags with loose 'bungee'-type cords.
- Side boxes or deck boxes used to hold containers are to be locked. Tank lids must be locked at all times except during fill-up.

Safe Pesticide Use

Basic Pesticide Safety

Proper storage, handling, mixing, measuring, and transporting of materials can reduce exposure, accidents and save waste. Always be alert and precise when dealing with concentrated materials. Many pesticide concentrates are considered hazardous materials. The purpose of safe pesticide handling is to reduce the risk of exposure to our employees, our clients, and our environment. You should be fully aware of the **concentrate label information** prior to handling. Material Safety Data Sheets (MSDS or SDS) provide additional precautions.

- 1. Always read the label with care. Before opening the container, pay strict attention to label warnings and cautions. Follow label directions for mixing and application.
- 2. Keep children, animals, and unauthorized people away from granulars, concentrated pesticides, and tank mixes. Store pesticides under lock and key (See "Pesticide Storage and Disposal" section). All storage boxes and tank hatches must be lockable on vehicles.
- 3. Store only in the original container and keep tightly closed.
- 4. There are three ways that toxic materials can enter your body: 1) Through your skin (dermal poisoning); 2) By swallowing (oral poisoning); 3) By breathing (poisoning by inhalation). NEVER smoke, eat, or drink while mixing or applying pesticides. Even when using personal protective equipment, wash hands thoroughly before smoking, eating, or drinking.
- 5. Avoid inhalation or direct contact. Always use clean personal protective equipment (PPE) prescribed whenever you handle the concentrated materials in the warehouse area. Always use Davey Engineering Controls to reduce inhalation exposure. This clothing and equipment is necessary to protect the most sensitive areas of your body from contamination. Use Davey-issued chemical-resistant (impervious) gloves, impervious apron, impervious boots, and goggles. Change gloves on a weekly basis or prior to glove impairment or unfitness.

Safety equipment must be available and worn along with protective clothing (long sleeves, trousers, head covering) to reduce exposure to chemicals during mixing and loading. Appropriate Engineering Controls must also be used throughout the mixing and loading operation.

- 6. After each workday, bathe and change to clean clothing. Wash clothing (separate from other clothing) after each day's use, using hot water and a strong detergent. Always use clean clothing when starting a new workday. An applicator must have extra clothing available (primarily in the service vehicle and/or secondarily at the facility) for emergency purposes.
- 7. Avoid spills. If spills occur, take *immediate action* to remove contaminated clothing and wash thoroughly. Follow Davey release response procedures and state recommendations.
- 8. Avoid applications under windy conditions that could create drift to nontarget areas (chemical trespass). Follow state or label recommendations.

Pesticide Storage and Disposal

Storage

- Storage of Davey-owned pesticides on residential properties is prohibited.
- Davey pesticide-using establishments are required to maintain appropriate cleanliness in order to function in a manner conducive to proper storage, handling, mixing, transportation, and disposal of pesticides.
- 3. All pesticide concentrates are to be stored within an identified **limited access** area. If possible, pesticides should be housed in a separate building and stored within a diked area. The storage area should have only one entrance door that is to remain **locked** unless pesticides are accessed.
- 4. Bulk containers of chemicals, such as Trimec and Formolene, are to have double containment (i.e., diked, double-wall container or container within a container).
- 5. Provide for removal of any fumes via an exhaust fan vented to the outside of the building.
- 6. The storage area should have adequate lighting sufficient to read labels and material safety data sheets (MSDS).
- 7. Opened pesticide containers should not be stored on wooden pallets. Cover wooden pallets with washable plastic.
- 8. Separate storage rooms for pesticides and herbicides are recommended. As an alternative, herbicides <u>must</u> be physically separated from other pesticides.
- Containers used to dispense herbicides during fill-up must be closed and labeled correctly. During application containers must be clearly labeled. Open buckets and pails are prohibited during mixing and fill-up.
- 10. All pesticides are to be stored separately from fertilizers. Combined fertilizer/pesticide products are considered and stored as pesticides. Follow state regulations for storage of granular products.
- 11. Spill control materials and equipment are to be present and readily available for use.

- Absorbent, e.g., sand, activated charcoal, cat litter, vermiculite, "oil-dry"; lime (good for neutralizing organophosphates and carbamates); or universal absorbent such as Hazorb pillows (20).
- Shovel and push broom to pick up absorbed spill.
- Heavy-duty plastic bags (leaf or garbage), plastic trash can or similar expendable leak-proof refuse container to contain and store absorbed spill until disposed of properly.

Triple-Rinse

Triple-rinse empty containers immediately after draining to avoid dried residue on the insides of containers. Dry chemical may be more difficult to remove with rinse water. Add the rinse to the tank and dispose or recycle containers according to state or local regulations. Do not accumulate containers. Avoid hazard to humans, animals, and the environment by following these procedures:

- 1. Empty the container into the tank and let it drain 30 seconds.
- 2. Fill it about one-fourth (1/4) full of water, cap and shake about 10 seconds to rinse inside surfaces.
- 3. Empty the container into the tank and drain 30 seconds.
- 4. Repeat the process twice more.
- 5. Before disposal, break or puncture container. Remove Davey labels.
- 6. Remove and rinse the cap. Do not recap the container. Dispose as normal.
- 7. Allow container to dry, then, and only then, can the empty container be put in the trash receptacle or recycled by an authorized recycler.

NOTE: Empty M-Pede and adjuvant containers are pesticide containers. As such, the law (FIFRA) states that they are to be disposed of in the same manner as all other pesticide containers or recycled by an authorized recycler. Empty containers should not be used for trash collection. Appropriate trash containers are made of metal and are closable with metal lids.

Disposal of Spilled Pesticides

If a spilled pesticide can be recycled -- use it! That is, add it to your tank mix and apply it according to label directions. In some cases spill cleanup can be sent to an MSW landfill with proper documentation. However some spilled debris is still considered hazardous material and must be disposed of as a hazardous waste. If spilled/absorbed pesticide is not recyclable, contact the Davey Institute for assistance.

<u>NEVER</u>, <u>EVER</u> allow unusable pesticide to enter toilets, sinks, sewers, creeks, ditches, or anything, which would lead to public water supply contamination.

C.5.4.19.4.h

Level 1 releases are classified as minor or incidental spills requiring an on-site employee to respond and take necessary collective actions to clean-up the spill. Level 1 releases are not considered an "emergency". Clean up should take less than 1 hour.

- 1. Keep people and animals away from spilled chemicals.
- 2. Confine the spill with absorbent pillows, sand, cat litter, or soil. Decontaminate the affected area as best as can be done without spreading the spill.
- 3. If concentrated pesticide is spilled on someone, have him or her remove contaminated clothing and wash immediately. Each staff member should have a complete change of clothing available at the office.
- -. Shovel contaminated absorbent into a heavy-duty plastic (leaf or garbage) bag. Label the bag as to its contents (ex: "approximately one pint Trimec 992 in cat litter"). Dry, dispersible granular, granular, or wettable powder product spill: IMMEDIATELY sweep the material up and put it in the waste container provided. If the material has not been contaminated, it is still usable.
- 5. Minor releases should be documented with a written spill report. Notify the immediate supervisor then project manager; report the spill to COR.

STREET AND PARKING LOT SWEEPING PRACTICES

STREET AND PARKING LOT DEICING PRACTICES

11-17

Schedule for STREET SWEEPING 16 5.4.19.4.6



Parking Lot and Street Sweeping

2 messages

Sharkey, Kevin < Kevin. Sharkey@davey.com>

Tue, Feb 18, 2014 at 8:04 AM

To: Bruce Johnson - 8PSDPD <bruced.johnson@gsa.gov>

Cc: Charlie Carruth - 8PSDPD <charlie.carruth@gsa.gov>, "York, Cinde" <Cinde.York@davey.com>

Bruce - I wanted to let you know that we conducted parking lot and street sweeping this past Saturday including the porous lots. We did have some major wind over the past couple of days that knocked over signs, created debris, twigs, limbs, trash, and tumbleweeds. Our crew is out policing the entire facility is morning. We are also wrapping up some potholes with cold patch as well. Please let me know if you have any questions or concerns. Thanks

Kevin Sharkey

Project Manager

Davey Tree Expert Co.

Denver Federal Center

Office: 303-274-6153

Fax: 330-676-6777

Cell: 719-499-3802

kevin.sharkey@davey.com

www.davey.com

Bruce Johnson - 8PSDPD <bru>

bruced.johnson@gsa.gov> To: "Sharkey, Kevin" < Kevin. Sharkey@davey.com>

Tue, Feb 18, 2014 at 10:40 AM

Sharkey I was out looking at the roads and lots and they look great. Thanks for getting the sweeping completed this weekend.

Bruce

[Quoted text hidden]

Bruce Johnson **Building Management Specialist** Denver Federal Center 303-236-4865

Dave, here to street sweering

Sometiment	RECORD OF TIME OF ARRIVAL AND DEPARTURE FROM BUILDINGS (DURING SECURITY HOURS)	EPARTURE Y HOURS)	BUILDING 45 W-1 Entrance		YEAR MONTH FEALLHALY	
DATE (a)	PRINT NAME (Last - First - Initial) (b)	SIGNATURE (c)	AGENCY OR FIRM (d)	ROOM NUMBER (e)	PURPOSE OF SEE TIME OF VISIT (9) (h)	OF DEPARTURE (I)
7-15-14	THEN ENCHAS	Mr. tholylws	Owner	45	Myselleright sissophy Than	d/sh/h
2-15-14	Mue Stevens	chit the	Osvey	45	7:00mm	S:colm
	DAVIEL HUGGETESS		Sport	45	11 11 11	•
	JOSE HARRILE	5	Down	45	11 11	
	JOSHUA KAMMENDAR		Janey 1	45	11 11	
0	KENNETH HETURNS	0.0	SAVEY	45	11 31	
M-81-8	Thu frued	Whill	Shred !	45	MECHANIC \$.005 1	:300
	Make Wish		SANEN	45	Mise furting	8
	ETHAN SMITH		Swed	45	11 9 11	
	1554 BAILLOS		Daley	45	1) 1/1	я
	Mentilf Towner		Cheley	45	11 11	
		i.	}	45		u
				45		Þ
				45		8
		e e		45		
				45		
* Federal Prot	* Federal Protective Service and Contract Administration personnel, when conducting an investigation, must place an "X" in this column.	when conducting an investigation.	must place an "X" in this co	lumn.		

GENERAL SERVICES ADMINISTRATION

SNOW REMOVAL Meeting



Training: Snow Removal & DE-Ieing PrACTICES
See C.5.4.19.4.6

Date: 10/30/20/13

Printed Name	Signature
1. Josh Kammerlohr	Dellamentohr
2. TANIEL AWDREWS	Duly
3. Paul Rivera	Whil King
4. Monica Todorov	manaytology
5. Dale Stevens	The No
6. ANDON NEWBILL	Ch Julit
7 Ethan Smith	CAT CAT
8. Remeth J Returns	Kenneth J. Kelyns
9. 1584 BARRIES	of FIR
10. Whe Wissey	Applied Will
11. Chan EACINIAS	LANCOHOLD CONVICE
12. 2050 C-Corrille	Gontopay Coull-
13. M. Unvel DiTommoso	morriel seeing
14.	
15.	

Project Manager Signature:



SNOW Meeting Report

C.5.4.19.5.b Location of meeting: DAJEY OF Meeting Leader (print clearly):	Date:	9-10-2014
Location of meeting: DAJEV OF	FICE - OFC Start Time:	9:15Am Finish Time: Duration: 10:45 Am
Meeting Leader (print clearly):	Meeting Je	eader signature:
KEVIN SHARKEY	6	ellin
	DED GOLDER I	A AMERICA AND A AN
Employee Name (print clearly)	Employee Number	N ATTENDANCE Employee Signature
11.00	Employee Number	Employee Signature
W. Faul Kivera		an officer
Vale Stevens		d West State of the state of th
3 Ethan Smith		Em / Mar
4 Jason Encinias	20045645	
5 Anxend anilla		and Contlle
		The ph
Renneth Returns	200115656	Renneth Returns
Josh Kammerlohr	20045655	m Chi
Monda logoron		Illning of Joglan
9 CINDEYORK	20037753	1 (Idolle)
10	1271 28 444	
11		
12		
13	1 1112	
14 1 1 1 1		
15		
16	the first seen a second seen	
17		
18		
19		
20	1.10	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Subject and remarks/comments:	
Sibou REMOVAL PROCESS &	
POLICY FOR 2014/2015	Terries .
SNOW SEASON.	
	The second
	100

HAZARDOUS MATERIALS STORAGE OR HAZARDOUS WASTE ACCUMULATION AREAS



FOR: MATERI SPILL C

1	à	
MATERIALS LABORATORY AND SPILL CLEANUP PROJECT AREA	APPROVED BY:	
MATERIALS LA SPILL CLEANUF	CHECKED BY: REJ	
GENERAL SERVICES ADMINISTRATION Denver Federal Center Lakewood, Colorado	DRAWN BY: ARA	
GENERAL ADMINIS Denver Fec Lakewood	JOB NUMBER: 187801038	
RIALS LABORATORY CLEANUP PROJECT		

4/15/09

FIGURE:

SPCC PLAN

An electronic copy of the SPCC Plan can be found on the "P drive" at the following path:

P:\DFC MASTER FOLDER\EPG\Stormwater\MS4 Permit 2011\SPCC\GSA Denver Federal Center SPCC Final 11_21_11



Spill Prevention, Control and Countermeasures (SPCC) Plan

Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

November 21, 2011

Prepared For:

Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

Attention: Mr. Michael Gasser

Pinyon Project #1/11-346-01.6302



Spill Prevention, Control and Countermeasures (SPCC) Plan

For

Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

Prepared For:

Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

Prepared By

PINYON Environmental Engineering Resources, Inc.

Project #1/11-346-01.6302

Author

Karlene R. Thomas, P.E.

Project Engineer

Kaile & Inef

Jame Toan

Lauren E. Evans, P.E President



9100 W. Jewell Ave, Suite #200 Lakewood, CO 80232-6357

(303) 980-5200 • (303) 980-0089 • <u>Colorado@pinyon-env.com</u> • www.pinyon-env.com

Spill Prevention, Control, and Countermeasure Plan--- Organization Sheet

This sheet describes the organization of the Plan. Chapters 1–3 describe General Services Administration (GSA) activities/operations at the Denver Federal Center (DFC) and how to implement the spill-response program at the facility. Chapters 4-5 describe the spill contingency and management program. Chapter 6 describes personnel responsibilities and required training. Specific spill response cards and tank information sheets for each aboveground storage tank (AST) are located in Appendices A and B, respectively. Specific details for each tank, as required by the SPCC regulations, are found on these cards and summary sheets.

Availability of the SPCC Plan: Keep copies of this SPCC Plan on file at the DFC Megacenter; DFC GSA Environmental Programs Group (EPG) office, Building No. 41; GSA Team 2 Building 53; GSA Team 3 Building 67; GSA Team 4 Building 25; and GSA Team 6 Building 41. It must be available for on-site review by representatives of the U.S. Environmental Protection Agency (EPA) or the Colorado Department of Labor and Employment Division of Oil and Public Safety (OPS) during normal working hours. Copies of the SPCC Plan must also be accessible to all persons responsible for administering the plan.

Purpose of the SPCC Plan: This SPCC Plan addresses storage and management of petroleum and other oil products stored in tanks that are owned and operated by the GSA at the DFC in Lakewood, Colorado; describes practices, procedures, structures, and equipment for the prevention of and response to spills at the facility; and fulfills the requirements for an SPCC Plan as mandated by Title 40 Code of Federal Regulations (CFR) §112. Other resources used to prepare this SPCC Plan include: Title 40 CFR §279.22, "Standards for the Management of Used Oil"; Title 40 CFR §300, "Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) National Oil and Hazardous Substances Pollution Contingency Plan"; and the OPS Storage Tank Regulations, 7 C.C.R. 1101-14. The table on page iv cross-references the program requirements of 40 CFR §112 with this plan.

SPILL PREVENTION, CONTROL, AND COUNTERMEASURES (SPCC) PLAN

Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

CERTIFICATION

In accordance with 40 CFR 112.3(d), I hereby certify that:

- 1. I am familiar with the requirements of the SPCC rule;
- 2. I, or my agent, have visited and examined the facility;
- 3. This Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

Note that this Professional Engineer certification does not relieve the owner or operator of an onshore facility of his duty to prepare and fully implement this Plan in accordance with all applicable requirements.

Registered Professional Engineer	00 REGIS 01 ENE R 7 31909 5
31909	E Formation of the second
Registration No.	
State	Date (1/21///

SPILL PREVENTION, CONTROL, AND COUNTERMEASURES (SPCC) PLAN Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

The attached SPCC Plan is applicable to the petroleum bulk storage facility located at:

Denver Federal Center, West 6th Avenue and Kipling Street, Denver, Colorado 80225-0546

Responsibility for implementation of this Plan is assigned to:

Denver Federal Center, Environmental Manager

Located at: Denver Federal Center, West 6th Avenue and Kipling Street, Denver, Colorado 80225-0546

It is the opinion of General Services Administration (GSA) that the controls described in the attached Plan are sufficient to prevent releases at the bulk oil facility from gaining access to waters of the United States. GSA's management provides full approval, at a level with authority, to commit the necessary resources to respond to any release, and to implement this SPCC Plan as herein described. In addition, a copy of this Plan is maintained at the facility and available during business hours for review by the EPA, State or Municipal regulatory authorities. If responsibility for implementation of this plan changes, fill out the Transfer of Management form in Appendix C.

<u>.</u>	Mh	()	RUW	<u></u>	
Denver F	ederal (Cente	er, Environn	nental Manage	r
			S	9	
	2	11	128) W		
Date					

01100

Cross Reference Matrix for Non-Production Facilities

lation	Description	Section
(b)(1) or (c)	SPCC Plan prepared prior to facility becoming operational (effective 11/10/2011)	N/A
3(d)	Professional Engineer (PE) certification with five elements	i
3112.5(a)	Amendment of SPCC Plan	1.2
112.5(b)	Review of Plan at least every 5 years with documentation (i.e. a log)	1.2, App E
112.7	General requirements for SPCC Plans for all facilities & all oil types	
112.7	Management approval of Plan	iii
§112.7	Discussion of facilities, procedures, methods or equipment not yet fully operational with details of installation and operational start-up	N/A
§112.7(a)(1)	General requirements; discussion of facility's conformance with rule requirements	1.0
112.7(a)(2)	Deviations from Plan requirements	1.3
§112.7(a)(3)	Facility description and diagram, type of oil and capacity of each container, transfer stations and piping, buried containers on diagram	2.0, Fig 2, App. A&B
§112.7(a)(3)(ii)	Discharge prevention measures	3.0
§112.7(a)(3)(iii)	Discharge drainage controls	3.2
§112.7(a)(3)(iv)	Countermeasures for discharge discovery, response and cleanup	4.0
§112.7(a)(3)(v)	Methods of disposal of recovered materials in accordance with legal requirements	4.4
§112.7(a)(3)(vi)	Contact list and phone numbers for facility response coordinator, National Response Center, cleanup contractors, all Federal, State, and local agencies who must be contacted in case of a discharge	4.5
§112.7(a)(4)	Spill reporting information	4.5
§112.7(a)(5)	Discharge procedures	3.2
§112.7(b)	Failure prediction (sources, quantities, rates, and directions)	App A
\$112.7(c)	Secondary containment for all areas from which a discharge of oil could occur (i.e. mobile refuelers, loading/unloading areas, transformers, oil filled operational equipment, etc.) other than bulk containers	App A & B
7(d)	Explanation of impracticability of secondary containment	1.4
3112.7(d)(1)	Oil spill contingency plan per part 109	2.5
§112.7(d)(2)	Commitment of manpower, equipment & materials to remove a discharge	iii
§112.7(e)	Written procedures for inspections and tests	5.0
§112.7(e)	Records of inspections and tests signed and kept 3 years	5.3
§112.7(f)(1)	Employee training	6.0
§112.7(f)(2)	Designated individual accountable for discharge prevention	6.0
§112.7(f)(3)	Discharge prevention briefings scheduled and conducted annually	6.0
§112.7(g)	Security: How oil handling, processing and storage areas are secured and access is controlled	2.3
§112.7(g)	Security: How master flow and drain valves of containers are secured	3.2
§112.7(g)	Security: How unauthorized access to starter controls on oil pumps is prevented	N/A
§112.7(g)	Security: How out-of-service and loading/unloading connections of oil pipelines are secured	N/A
§112.7(g)(5)	Security: Appropriateness of security lighting to both prevent acts of vandalism and assist in the discovery of oil discharges is addressed	2.3
§112.7(h)	Loading/unloading rack (excluding offshore facilities)	N/A
§112.7(h)(1)	Containment for contents of largest compartment	Table 1
§112.7(h)(2)	Warning light/sign, barrier system, wheel chocks, or break interlock system to prevent departure with connected lines	3.3
§112.7(h)(3)	Inspect drains and outlets of vehicles	3.3
§112.7(I)	Brittle fracture or catastrophic failure evaluation requirements	2.6
§112.7(j)	Conformance with State requirements	2.7
§112.3(k)(1)	Qualified Oil-Filled Operational Equipment: meets criteria	
§112.7(k)(2)(I)	Inspection procedures or monitoring program	5.0
7(k)(2)(ii)(A)	Oil spill contingency plan per part 109	2.5
7(k)(2)(ii)(B)	Written commitment of resources	iii

§112.8, §112.12	Requirements for Onshore Facilities (excluding production)	
§112.8(a), §112.12(a)	Meet general and specific requirements	1.0
§112.8(b)(1), §112.12(b)(1)	Facility drainage: Restrain drainage from diked areas; inspect accumulation	2.4
§112.8(b)(2), §112.12(b)(2)	Facility drainage: Manual valves to drain diked areas, inspect before discharging into watercourse	3.2
§112.8(b)(3), §112.12(b)(3)	Facility drainage: Undiked drainage with a potential for a discharge designed to flow to ponds, lagoons, or catchment basins	2.4
§112.8(b)(4), §112.12(b)(4)	Facility drainage: Final discharge of ditch drainage controlled	2.4
§112.8(b)(5), §112.12(b)(5)	Facility drainage: Where pump transfer is needed, two lift pumps installed with one installed permanently	N/A
§112.8(c), §112.12(c)	Bulk storage containers:	Table 1
§112.8(c)(1), §112.12(c)(1)	Containers compatible with material and conditions of storage	Table 1
§112.8(c)(2), §112.12(c)(2)	Secondary containment for capacity of largest container & sufficient freeboard for precipitation	Table 1
§112.8(c)(3), §112.12(c)(3)	Not allow drainage of rainwater from diked areas unless inspected, records kept of drainage events	3.2, 5.1, App I
§112.8(c)(4), §112.12(c)(4)	Completely buried metallic containers corrosion protected, leak testing conducted	N/A
§112.8(c)(5), §112.12(c)(5)	Partially buried containers corrosion protected	N/A
§112.8(c)(6), §112.12(c)(6)	Integrity testing, visual plus non-destructive shell testing, comparison records kept	5.0
§112.8(c)(7), §112.12(c)(7)	Internal heating coils monitored	N/A
§112.8(c)(8), §112.12(c)(8)	Containers engineered to prevent discharges	Table 1
§112.8(c)(8)(v), §112.12(c)(8)(v)	Liquid level sensing devices tested to ensure proper operation	5.0
§112.8(c)(9), §112.12(c)(9)	Observe effluent treatment facilities to detect system upsets	N/A
§112.8(c)(10), §112.12(c)(10)	Correct visible leaks and remove accumulations of oil	5.0
§112.8(c)(11), §112.12(c)(11)	Secondary containment for mobile/portable containers with capacity of largest container & sufficient freeboard for precipitation	Table 1
§112.8(d), §112.12(d)	Facility transfer operations, pumping and facility process	2.0
§112.8(d)(1), §112.12(d)(1)	Buried piping installed or replaced after 8/16/02 corrosion protected	N/A
§112.8(d)(2),	Terminal connections capped/blank flanged when not in service or in standby service for an extended time	N/A
8112 8(d)(3)	Pipe supports properly designed	2.0
8112 8(d)(4)	Inspect aboveground piping, integrity and leak test buried piping	5.0
8112 8(d)(5)	Warn vehicles of aboveground piping	N/A
	Completed and signed certification of substantial harm form	App D

Table of Contents

1.0	General Information	1				
1.1	Legal Requirements and Responsibility	2				
1.2	Revisions, Amendments, and Documentation	2				
1.3		3				
1.4	Determination of Practicability	3				
2.0	Facility Information	5				
2.1	Site Description	5				
2.2	8					
2.3						
2.4						
2.5						
2.6	는 사용 사용 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -					
2.7	Conformance with State and EPA Standards	8				
3.0	Spill Prevention Procedures	9				
3.1	Spill Prediction	9				
3.2						
3.3						
3	3.3.1 Oil Delivery Procedures	0				
3	3.3.2 Oil Dispensing Procedures	10				
	3.3.3 Grease Trap Cleanout Procedures					
4.0	Call Day of					
4.0 4.1	Spill Response and Reporting					
4.1	Emergency Releases					
4.2	Incidental Release					
4.4						
4.5						
4.3	Spill Reporting	1/				
5.0	Inspection Testing and Recordkeeping	21				
5.1	Inspections	21				
5.2						
5.3	Record Keeping	23				
6.0	Responsibilities and Required Training	25				
DFC	C Environmental Manager	25				
Prin	ncipal Emergency Contact	25				
	ll Response Team (SRT)					
	ilding Managers/Property Managers					
Pers	sonnel Training	26				
	HAZWOPER Training					
Spil	II-Response Training	27				

Table of Contents (Continued)

Appendices

Appendix A	Spill Response Cards
Appendix B	Tank Information Sheets
Appendix C	Transfer of Management Forms
Appendix D	Certification of Substantial Harm Determination Form
Appendix E	SPCC Plan Review Form
Appendix F	Monthly SPCC Plan Inspection Checklist/Log and AST Inspection Form
Appendix G	AST Oil Delivery/Ullage Forms
Appendix H	Spill History Log
Appendix I	Rainwater Inspection Log
Appendix J	Annual Gauge Calibration Form
Appendix K	Annual Inspection Records
Appendix L	Training Log Sheet

List of Tables

Table 1	Summary of ASTs
Table 2	Emergency Assistance Contacts
Table 3	Summary of Transformers

List of Figures

Figure 1	Site Location
Figure 2	Site Plan ASTs
	01 D1 E 0

Figure 3 Site Plan Transformers

1.0 General Information

This Spill Prevention, Control, and Countermeasures (SPCC) Plan (the "Plan") has been

designed to outline proper response to, and minimize the effects of, spills and releases of

hazardous materials that may adversely effect human health and the environment. This Plan

provides the information for spill prevention control and countermeasures for:

Denver Federal Center, West 6th Avenue and Kipling Street, Denver, Colorado

The facility location is identified on Figure 1.

The purpose of the Plan is to provide an outline for proper emergency response in the event of a

release, and to prevent discharges of oil from reaching navigable waters of the United States. Oil

is defined in 40 CFR 112 as "oil of any kind or form, including, but not limited to petroleum fuel

oil, sludge oil, oil refuse and oil mixed with wastewater other than dredged spoil." Spill and leak

prevention measures, and the training of employees, are the primary methods used to minimize

the chances of an accidental discharge. Subsequent methods include secondary containment to

prevent accidental releases from reaching waters of the United States. Copies of this Plan are

available at:

Denver Federal Center (DFC) MegaCenter

DFC GSA EPG office, Building 41

GSA Team 2 Building 53

GSA Team 3 Building 67

GSA Team 4 Building 25, Room 2322

GSA Team 6 Building 41

PINYON Environmental Engineering Resources, Inc

1.1 Legal Requirements and Responsibility

This Plan has been designed to meet the requirements of 40 CFR 112, "Oil Pollution Prevention," as outlined in Section 112.7 for SPCC planning. This facility is not a Substantial Harm Facility as defined in the Oil Pollution Act of 1990, and therefore a Facility Response Plan as outlined in Section 112.20 is not required (Appendix D).

1.2 Revisions, Amendments, and Documentation

This SPCC Plan will be reviewed and updated at a minimum of every five years (Appendix E). The Plan must be amended at any time should one of the following occur:

- There is a change in facility design, construction, operation or maintenance that materially affects the facility's potential for a discharge of oil into or upon the navigable waters of the United States;
- Significant changes to Federal or State regulations affecting the applicability and effectiveness of this SPCC plan or those affecting reportable spill quantities;
- If the SPCC plan fails or proves to be ineffective in preventing or responding to a spill;
- A more effective control or prevention technology is made available which will significantly reduce the chances of a spill event; or
- As required by the EPA or the State after review of the Plan.

Any technical SPCC Plan amendments must be certified by a registered Professional Engineer (P.E.) and implemented as soon as possible, but no later than six months after a facility change or the SPCC Plan review. Non-technical Plan amendments do not need to be certified by a P.E. The Division of Oil and Public Safety (OPS) now requires submittal of the cover page and P.E. certification page from the Plan for all registered facilities and the Plan must be dated within the last five years. In addition, the OPS requires that permit applications be submitted for ASTs prior to commencement of the installation/construction process or prior to certain renovations. Once the permit is acquired, initial tightness testing and an inspection by the OPS is required. Thereafter, annual registration is necessary.

In addition to review and certification, a record of the following activities must be maintained:

- Permits and registration records
- All monthly and annual inspections and corrective actions;
- Ullage and inventory control documentation
- All spill and release events;
- SPCC Plan training records;
- Changes in physical plant conditions that may be inconsistent with the current Plan; and
- Changes in maximum storage inventory or other physical plant changes.

1.3 Deviations from Plan Requirements

The SPCC plan does not deviate from the requirements for an onshore non-production facility under 40 CFR 112.1 to 112.8.

1.4 Determination of Practicability

Facility management has determined that use of the containment and diversionary structures or readily available equipment to prevent discharged oil from reaching navigable water is practicable and effective at this facility for all above ground storage tanks. Secondary containment and/or diversionary structures are not practicable for the oil-containing transformers located at this facility. Under the SPCC rules, transformers are exempt from sized secondary containment requirements, but are still subject to the remainder of the SPCC regulations. Additional discussion regarding active secondary containment for transformers is discussed in Section 2.7.

2.1 Site Description

Name of facility:

Denver Federal Center

Type of facility:

Administrative, document and sample storage, laboratory

and research activities

Location:

West 6th Avenue and Kipling Street, Denver, Colorado

Phone number:

MegaCenter: 303-236-2911

Person responsible for oil spill prevention:

DFC Environmental Manager

The DFC is a 633-acre complex located at the southwest corner of West 6th Avenue and Kipling Street in Jefferson County, Denver, Colorado. The DFC is located on a portion of the former Denver Ordnance Plant, a munitions complex operated in the 1940s by the Federal government. In the late 1940s and early 1950s the facility was renovated to office, laboratory and storage space for a variety of Federal agencies. The DFC is operated by the General Services Administration (GSA), an independent agency of the United States government which manages and supports the functioning of Federal agencies. The GSA owns or operates, for Federal tenant agencies, multiple aboveground storage tanks (ASTs), grease traps and electric oil-containing transformers located at the DFC.

2.2 Surrounding Land Uses

The DFC is located in a western suburb of the Denver Metropolitan Area within a highly urbanized corridor. Sixth Avenue borders the DFC directly to the north. North of Sixth Avenue, land use consists of commercial, light industrial and residential development. Kipling Street borders the DFC to the east. East of Kipling Street, land use consists of public/institutional land uses and open space with residential development further east. Alameda Avenue borders the DFC to the south, with

primarily residential developments south of Alameda Avenue. Commercial development borders the DFC to the west with Union Boulevard further to the west with additional residential development beyond.

2.3 Facility Security

Security measures are in place at the facility to prevent tampering or accidents, and are checked monthly during the formal monthly inspection (Appendix F). These measures include the following:

- Access to the DFC is controlled 24 hours a day, seven days a week;
- The DFC is surrounded by an eight-foot chain-link security fence, topped with barbed wire;
- The five entry gates are manned by armed security guards under the control of the Federal Protective Service (FPS);
- The facility is patrolled by the FPS;
- The DFC grounds are well lit by pole and building mounted lighting;
- Selected areas of the DFC are under camera surveillance 24 hours a day, seven days a week; and
- On-Site personnel man the Megacenter 24 hours a day on an on-call basis in the event of an incident.

2.4 Topography and Hydrology

Site Topography (Figure 1)

Surface drainage over the DFC property is generally from the west to the east. As a general rule, slopes are gentle, with a 2-3 percent grade.

Surface Water

Drainageways or waterways on the facility or within one-quarter mile of the facility, and the distance and direction from the facility (Figure 1), include:

- Downing Reservoir, located on the eastern side of the property, is a manmade storm water detention pond, as is the retention pond on the northern boundary of the DFC, and the retention pond west of the current fenceline.
- A manmade irrigation ditch, the "Agricultural Ditch," enters the property on the northern side and flows in a southeastern direction, crossing McIntyre Gulch and exiting the property's southeastern corner; and
- The only natural body of water on the DFC property is McIntyre Gulch, which enters the
 property from the west and flows in an easterly direction until it exits the DFC boundary
 on the east side.

2.5 Oil Spill Contingency Plan

A Contingency Plan is a set of instructions that outlines the steps that should be taken before, during, and after an emergency. A Contingency Plan looks at all the possibilities of what could go wrong and, "contingent" upon actual events, has the contacts, resource lists, and strategies to assist in the response to the spill. An oil spill contingency plan is only required in the following situations:

- Secondary containment is found to not be practical and is not provided for bulk storage tanks; or
- Secondary containment is not provided for qualified oil-filled operational equipment (including transformers) and there has been a discharge of greater than 1,000 gallons or two discharges each exceeding 42 gallons from qualified oil filled operational equipment within any 12 month period in the three years prior to the SPCC plan certification date.

At the DFC, secondary containment is provided for all bulk storage containers and there has not been a discharge greater than the above-stated thresholds from oil-filled operational equipment. Therefore, a contingency plan is not required.

2.6 Brittle Fracture Evaluation Requirements

Brittle fracture evaluation is required if a field-constructed aboveground container undergoes a repair, alteration, reconstruction, or a change in service that might affect the risk of a discharge or failure due to brittle fracture or other catastrophe. No field-constructed aboveground containers are located at this facility.

2.7 Conformance with State and EPA Standards

Bulk oil storage tanks, including those at Federal facilities, are regulated in Colorado by the Colorado Department of Labor and Employment Division of Oil and Public Safety (OPS) Storage Tank Regulations, 7 C.C.R. 1101-14, updated April 14, 2011. The OPS enforces state requirements for all ASTs with capacity of 660 to 39,999 gallons, including those pertaining to:

- Design, installation, operation and closure of ASTs;
- Cathodic protection for ASTs and associated piping;
- Release detection for ASTs and associated piping;
- Fire and safety standards for ASTs;
- Spill and overfill for ASTs;
- Registration and permitting of ASTs;
- Reporting, investigating, assessing and cleaning up releases from ASTs; and
- Reimbursement from the Petroleum Storage Tank Fund, if applicable.

Oil filled operational equipment, such as elevator hydraulics and transformers, are not included in the definition of "aboveground storage tank" found at C.R.S. § 8-20.5-101(2), and are excluded from these regulations as "equipment or machinery that contains regulated substances for operational purposes." The grease traps located at the DFC are below the 660 gallon threshold and are also excluded from these regulations.

The EPA regulates all bulk storage containers greater than or equal to 55 gallons. All bulk storage containers at the DFC which are owned or operated by the GSA, including ASTs and grease traps, fall under these requirements. Transformers and elevator hydraulics are exempt from the sized secondary containment requirements, but they must meet the other general requirements of the SPCC regulations.

Additional discussion of conformance with the applicable parts of 40 CFR § 112 is provided in the individual sections of this SPCC Plan.

3.0 Spill Prevention Procedures

3.1 Spill Prediction

Potential equipment failures that may lead to a release include:

• Seam, valve or fitting failures, foundation failure, tank rupture or tank or piping failures

due to corrosion;

Loading area failures, such as tank overfilling, hose or pipe failures, pump failure, valve

or fitting failure, or operator negligence;

Accidents; and

Acts of God, such as floods and earthquakes.

3.2 Diked Areas, Discharges from Secondary Containment

No diked areas with drain valves are located at this facility. The secondary containment for AST

469699, a 575 gallon gasoline AST located 75 feet to the east of Building 2 and used to refuel

equipment, is a steel containment basin. There are no stormwater outlets from the containment

basin. If the containment area fills up with stormwater, authorized personnel will remove the

stormwater via a manual submersible pump, after inspection for any oil. Typically, stormwater

evaporates.

3.3 Procedures

3.3.1 Oil Delivery Procedures

Fueling at the Site is performed by various vendors on an as-needed basis. Fuel truck drivers

have been trained to meet the minimum requirements and regulations established by the

PINYON Environmental Engineering Resources, Inc

Department of Transportation. The drivers are trained to handle spills by reporting them to management. Management will direct spill reporting and response as discussed in Section 4.0. The OPS requires submittal of ullage documents for any tanks that are registered with the OPS (greater than 660 gallons) on a yearly basis. OPS ullage forms are located in Appendix G.

Warning signs and/or wheel chocks will be provided in loading/unloading areas to remind drivers not to depart before complete disconnect of flexible or fixed transfer lines. The operator should follow the procedures described below:

- Prior to filling, operators must ensure that the volume available in the receiving tank is greater than the volume of product to be transferred into the tank (Appendix G).
- Bonding and grounding wires must be properly attached (when required) to the truck before product transfers.
- Connect receiving hose and check all valves to ensure delivery of product to the proper tank. Operators will not rely on settings of previous deliveries. Operators will check the relief vent on the receiving tank to ensure proper operation.
- The transfer will be constantly monitored to prevent overfilling and spilling. Even if the receiving tank has a built-in overfill protection system to safeguard against overfilling the tank and causing a spill, the operators will check the receiving tank by means of the tank gauge or by gauging the tank volume by "sticking" the tank, and will not solely rely on a paper inventory.
- The delivery hose and lines will be checked for leaks.
- When loading/unloading is complete, all appropriate valves will be shut off, hoses will be disconnected, and the operator will check for leaks.
- After delivery is complete, the tank will be gauged to verify receipt of product and ullage will be recorded.
- Personnel are aware of the storage location of spill response materials (spill kit).
- All spills must be reported to management immediately as outlined in Section 4.0.

3.3.2 Oil Dispensing Procedures

Motive power equipment is fueled at the Site from AST M597267 and AST 469699. The loader or forklifts are driven to the tank. The dispenser must then be turned on by a manual valve that

is kept padlocked in the off position. The driver then removes a flexible hose with a nozzle from a bracket, takes it to the truck or equipment and starts the dispenser with the nozzle, as at gasoline stations. The flex hose and nozzle are then replaced. Drivers have been trained to respond to spills as described in Section 4.0, and to report spills of any size to management. Management will direct spill reporting and response as discussed in Section 4.0.

The following measures are in place or will be followed at the fueling area to prevent releases:

- A warning sign will be posted to remind drivers not to depart before removal of the dispensing line;
- Use of manually controlled dispensing equipment;
- The operator or driver will remain on hand until fueling is complete; the dispensing nozzles will shut down if released by the operator;
- The delivery line will be checked for leaks;
- When fueling is complete, the dispensing nozzle will be removed, appropriate valves shut off, and the operator or driver will check the dispensing line for leaks;
- The total volume of fuel dispensed will be recorded and submitted to management (Appendix G);
- All spills will be reported to management immediately as outlined in Section 4.0;
- Personnel involved in fueling operations are aware of the emergency shut-off switch location; and
- Personnel are aware of the storage location of spill response materials (spill kit).

3.3.3 Grease Trap Cleanout Procedures

Two 500-gallon cooking grease traps are located in Building 53. Drivers have been trained to respond to spills as described in Section 4.0, and to report spills of any size to management. Management will direct spill reporting and response as discussed in Section 4.0.

The following measures are in place or will be followed at the pump out area to prevent releases:

A warning sign will be posted to remind drivers not to depart before removal of the line;

- The operator or driver will remain on hand until pumping is complete;
- The line will be checked for leaks;
- When pumping is complete, the line will be removed and appropriate valves shut off;
- The total volume of material removed will be recorded and submitted to management;
- All spills will be reported to management immediately as outlined in Section 5.0; and
- Personnel are aware of the storage location of spill response materials (spill kit).

4.0 Spill Response and Reporting

A timely response to a spill is critical to protecting human health and the environment. The type of response depends on whether the spill is an emergency or an incidental release. Response procedures for both release types are described in the paragraphs below. Under both scenarios, spill-response actions are conducted in two phases: immediate actions and follow-up actions. Immediate actions are procedural steps performed right away to place the spill event in a safe and stable condition. The follow-up actions are the remaining procedural steps that aid in combating the spill event, up to and including notification and area restoration.

The bulk storage facility is the responsibility of the Environmental Manager, who will direct and supervise the activities of response personnel in the event of a spill or leak. Unsafe or improper operating conditions, such as leaks, spill or obvious external damage to tanks or support structures will necessitate an immediate response activity.

4.1 Emergency Releases

Emergency releases are spills of unknown substances or spills that cannot be absorbed or otherwise controlled at the time of the release by personnel in the immediate release area (typically 55 gallons or more). These include spills that pose a significant safety or health hazard such as fire or explosion, or that reach a water source.

WARNING Do not respond to a release if you are not properly trained or equipped! Refer to the Material Safety Data Sheet (MSDS) for the spilled material.

Immediate Actions

- 1. Evacuate all personnel to a safe distance upwind from the spill and secure the area.
- 2. Immediately notify the On-Scene Coordinator (OSC) and the West Metro Fire Protection District (call 911).
- 3. Be prepared to provide the following information (Use the Release Report Form provided in Appendix H to document this information):
 - · Name, facility address, facility phone number
 - Date and time of discharge
 - Type of material discharged
 - Estimate of the total quantity discharged

PINYON Environmental Engineering Resources, Inc.

- Source of the discharge
- · Description of all affected media (e.g., water, land, air)
- · Cause of the discharge
- Damages or injuries caused by the discharge
- · Actions being used to stop, remove, and mitigate the effects of the discharge
- Whether an evacuation has occurred
- · Names of other individuals or organizations contacted
- 4. Relinquish control to the OSC or West Metro Fire Protection District upon their arrival.

Follow-Up Actions

- 5. If possible, without placing yourself at risk, try to contain the spill on site.
 - Put on the proper personal protective equipment (PPE) consistent with our level of training (e.g., face shield, apron, goggles, gloves, etc.)
 - Close valves and turn off power to pumps
 - Build a dike around the spill using absorbent material (for example, booms)
 - Protect storm water sewer drains and storm water conveyances through use of booms and drain mats, if available

NOTE: Only use absorbent material marked as compatible with the hazard class of the spilled material (check the material's MSDS for guidance).

Dispose of contaminated items, residue, and cleanup materials properly. All spill material is typically handled as waste, although in some instances recovered product can be reused. Call the GSA Industrial Hygienist for instructions on proper disposal of used absorbent.

Specific information for reponse to emergency spills can be found on each Spill Card, attached as Appendix A. Follow reporting guidelines in Section 4.5.

4.2 Incidental Release

Incidental releases are small spills of routinely used substances that do not pose a significant safety or health hazard, such as fire or explosion, or a risk to a water source, and that can be handled using spill kits located in the immediate area (typically less than 55 gallons).

Immediate Actions

WARNING Do not respond to a release if you are not properly trained or equipped! Refer to the MSDS for the spilled material.

- 1. Cease all work activities and notify personnel in the area of the spill.
- 2. Notify the OSC
- 3. Begin response actions:
 - a. Put on the proper PPE consistent with your level of training (for example, face shield, apron, goggles, gloves, etc.).
 - b. Turn off all sources of ignition (pumps, motors, etc.).
 - c. Without placing yourself at risk of injury, attempt to stop or slow the source of the spill to prevent any further release by following the procedures below:

- · Set containers upright or roll them over so the hole is facing upward
- Close valves and turn off power to pumps
- Place leaking drums in compatible DOT-approved overpack drums
- Transfer material from a leaking container to another container
- Patch holes in the leaking container
- Relocate container to where it poses less of a threat

Note Use a drip pan for all valves and similar dispensing equipment. Drips and leaks collected in a drip pan are not reportable spills.

- 4. Once the spill has been stopped, proceed with cleanup efforts:
 - a. Accumulate the spill using dry sweep, absorbent socks, absorbent pads, soil, etc.

WARNING Spilled substance may be flammable. Do not use metal shovels or rakes or any other equipment that may cause a spark.

- b. If spills escape secondary containment, use one of the following methods to clean up the spilled material:
 - Contaminant on or in water Use hydrophobic absorbents to skim off any material floating on the surface of water. If material has settled on the bottom of the water, consult with the OSC. Accumulate the waste in DOT-approved containers for proper disposal.
 - Contaminants on pervious surfaces (such as soil) –Absorb or scoop free-floating
 material into a suitable container, separating liquids from solids. Ensure that
 flammable or combustible material is not processed in a manner that could ignite it.
 Scoop or shovel contaminated items (soil, gravel, absorbent, etc.) into DOT-approved
 containers for disposal.
 - Contaminants on impervious surfaces (such as concrete) Absorb or scoop free-floating material into a container, separating liquids from solids. Ensure that flammable or combustible material is not processed in a manner that could ignite it. Absorb residual contaminants with absorbents and place them in DOT-approved containers for disposal. If the surface needs a final cleaning with hot water, steam, or abrasive blasting, consult with the GSA EPG.
- c. Label and mark the container to identify its contents.
- 5. Submit a completed Release Report Form to the GSA EPG by fax no later than 24 hours after the spill.
- 6. Dispose of contaminated items, residue, and cleanup materials properly. All spill material is typically handled as waste, although in some instances recovered product can be reused. Call the DFC Environmental Manager for instructions on proper disposal of used absorbent.

Specific information for reponse to emergency spills can be found on each Spill Card, attached as Appendix A. Follow reporting guidelines in Section 4.5.

4.3 Responding to PCB Spills

Note For PCB spills, only take those actions needed to minimize exposure and limit the extent of contamination. A contractor will complete the cleanup.

CAUTION To prevent PCB contamination of clothing or skin, wear protective clothing, boots, and gloves when constructing barriers and diversion structures. Do not use rubber protective clothing—a material similar to viton is more suitable.

WARNING The transformer may be live and there could a risk of electrocution. Do not proceed without proper training.

Some electrical equipment, such as transformers, capacitors, and switches, contain a significant quantity of dielectric fluid containing PCBs. Follow the following procedures if oil spills from such a unit and you are not sure whether it contains PCB oil:

- 1. Turn off electrical power to equipment involved.
- 2. Attempt to stop or slow the source of the spill to prevent any further release.
- 3. Notify the GSA EPG that a release involving dielectric fluid has occurred. The GSA EPG will notify the CDPHE.
- 4. Use every available option, including absorbing, diking, or diverting, to prevent the PCB spill from reaching storm water sewer drains, sanitary sewers, drainage ditches, or any other place where water may be present. Prevent water from flowing into the contaminated area from sources such as irrigation systems or storm water runoff. If the PCB spill reaches flowing water, storm sewers, or any inaccessible area, immediately contain and prevent any additional spill material from reaching those areas.
- 5. Place barricades around the contaminated area to prevent pedestrians and vehicles from entering until the spill material is cleaned up and removed. Post security guards until decontamination is completed.
- 6. Spread an oil-absorptive material on the contaminated area, leaving it in place as long as necessary to ensure that all available dielectric fluid has been absorbed.

Follow reporting guidelines in Section 4.5.

4.4 Restoration

The GSA is responsible for restoring the environment as closely as possible to its pre-spill condition. Restoration involves re-establishing destroyed flora and fauna or other remedial actions to assist in recovery from damage. Typical activities include planting ground cover,

replacing damaged trees, and watering or fertilizing plants. Restoration may also involve cleaning and painting damaged surfaces of vehicles, buildings, or other facilities.

If GSA resources do not clean up and restore the environment or do not meet applicable criteria, regional authorities may direct the work. If another Federal agency performs the cleanup, the GSA may be required to reimburse that agency.

4.5 Spill Reporting

Employees, contractors, and other personnel at the facility are responsible for the following:

• If the release poses a fire risk, the Fire and Police Departments must be contacted immediately:

Report spills of any size by notifying the Mega Center.

Mega Center

- In addition to the Mega Center, review the Spill Card for the specific AST to see if additional personnel should be contacted
- Give contacted personnel the following information:
 - The source of the spill or release;
 - The material being released; and
 - An assessment of the impact (size) of the release and potential hazards.
- Do not attempt to respond to severe situations without proper training, resources or backup personnel.

All public or press inquiries will be referred to the GSA Public Relations Office. In the event of eminent danger to the community, the OSC may make direct public notification prior to notifying the Public Relations Office.

Reporting a Harmful Quantity

A spill or overfill of a petroleum product must be reported if it is considered a harmful quantity of oil discharged to U.S. navigable waters, adjoining shorelines, or the contiguous zone. According to the EPA a harmful quantity of discharged oil is any discharge that violates state water quality standards, causes a film or sheen on the water's surface or leaves sludge or emulsion beneath the surface. Reporting requirements are no longer based on the amount of oil discharged, but instead on the presence of a sheen, sludge, or emulsion. For this reason, the Discharge of Oil regulation is commonly known as the "sheen" rule. Note that a floating sheen alone is not the only quantity that triggers the reporting requirements (e.g., sludge or emulsion deposited below the surface of the water may also be reportable). If such a release occurs the Environmental Manager will notify the National Response Center **immediately** upon knowledge of such release.

National Response Center 1-800-424-8802

Reporting a Spill from a Regulated Storage Tank

In addition, Colorado regulations require that a petroleum release of 25 gallons or more (or that cause a sheen on nearby surface waters) from regulated storage tanks must be reported to the Division of Oil and Public Safety within 24 hours.

Reporting a Spill to the State (CDPHE)

Any release that has or **may** impact waters of the state, which include surface water, ground water and dry gullies or storm sewers leading to surface water, no matter how small, must be reported **immediately** to the Colorado Department of Public Health and Environment (CDPHE). Written notification to the CDPHE must follow within five (5) days.

The CDPHE, Water Quality Control Division (the Division), issued additional guidance for reporting spills in "Guidance for Reporting Spills under the Colorado Water Quality Control Act and Colorado Discharge Permits," Policy Number WQE-10, dated March 1, 2008. The Division identified the following example of a spill (applicable to oil spill reporting) that is considered "non-reportable." The guidance states that spills that meet the following requirements are not required to be reported: "A spill to a generally impervious surface or structure (e.g., paved street/parking lot, storm sewer, warehouse floor, manhole, vault, concrete basement), or onto soils, that is fully contained in/on the impervious surface/structure or soils, or that is managed in

a manner so that it will not reach State waters at the time of the spill or in the future. Such spills that are cleaned up within 24 hours will be considered by the Division to have no potential to reach State waters. However, even if such spills are not cleaned up within 24 hours, the responsible person may be able to "fully contain" or otherwise manage a spill such that it will not reach State waters." Under SPCC regulations, even if a spill is not reportable, documentation of spills must be maintained for a period of three years (Appendix H).

The caller must be prepared to provide the following information:

- Name, address, and telephone number of the person reporting;
- Company name and location;
- Exact location of the spill;
- Date and time of the release;
- Quantity, source, and material spilled;
- Danger or threat posed by the discharge;
- Number and types of injuries (if any);
- Weather conditions at the incident location
- Location of nearest storm drain:

Nearest receptor location is on the Spill Card for each tank, located in Appendix A.

Proposed action for containment and clean up.

The Environmental Manager will complete the Spill History Log (Appendix H), and retain the record for a minimum of three years.

Reporting a Spill to the EPA

Whenever spills or overfills of a petroleum product that result in a release to navigable waters or adjoining shorelines that exceeds 1,000 gallons, or releases of more than 42 gallons in each of two discharges of oil in any 12-month period, the following information must be submitted in writing to the Region VIII EPA Administrator within 60 days from the time the spill occurs:

- Facility name and location;
- Facility owner or operator names;
- Facility maximum storage or handling capacity and normal daily oil throughput;
- Facility description, including maps, flow diagrams, and topographical maps;
- The cause(s) of the spill, including a failure analysis of system or subsystem where the failure occurred:
- The corrective actions and/or countermeasures taken (e.g., equipment repairs or replacement);
- Any other preventative measures taken; and
- Other information the Regional Administrator may require.

Region VIII EPA Administrator

US EPA Region 8 8OC-EISC 1595 Wynkoop Street Denver, CO 80202-1129

5.0 Inspection Testing and Recordkeeping

5.1 Inspections

Informal inspection of storage tanks, valves and piping will be made at the time of each delivery by an employee of GSA. Records do not need to be made of such informal observations. However, employees must report evidence of spills or damaged facilities and equipment. All visible leaks from seams, gaskets, rivets and bolts that are large enough to cause accumulation of product on the ground surface are to be reported to management and repaired immediately.

Informal inspections will also be made by operators during fuel dispensing. Records of informal inspections do not need to be made; however, evidence of spills or damaged equipment must be reported to management.

Formal inspections of each tank exterior, containment facility, transformer, aboveground piping, valves and hoses are conducted monthly by operating personnel to detect potential leakage from the tank, hose, pipe, connections and fittings (Appendix F). In addition, the general condition of items such as expansion joints, tank seams, locking valves, and metal surfaces are assessed. All secondary containment systems are inspected for the accumulation of petroleum product, and if present, the product is removed by a qualified contractor. Annual inspections for all steel ASTs greater than 660 gallons shall be conducted in accordance with STI SP001, Standard for the Inspection of Aboveground Storage Tanks, or API Standard 653, Tank Inspection, Repair, Alteration, and Reconstruction, whichever is applicable. Annual inspections shall be performed within 12 months after April 14, 2011, and during the same month in each year thereafter, as applicable, depending on the requirements of the chosen standard. External and internal inspections, and leak testing, shall be performed and documented according to the requirements of the standard being followed. Deficiencies noted during informal or formal inspections are acted upon in a manner consistent with environmental safety and good management practices. A State inspection form and a more detailed Site-specific inspection form are provided in Appendix F.

Rainwater will accumulate in outdoor secondary containment/diked areas. Personnel will use the following SOP to check secondary containment after *any* rain event.

After Rain Event SOP

For diked oil storage areas:

- 1. Check secondary containment for a visible sheen on the surface of the water, indicating residual spilled fuel product.
- 2. If there is a visible sheen, place absorbent pads on the water surface to remove spilled product.
- 3. Clean up spilled product.
- 4. Dispose of oily pads. Call the DFC Environmental Manager for instructions on proper disposal of used absorbent. Open the drain valve (turn left) and remove accumulated water.
- 5. Close the drain valve (turn right).
- 6. Complete the Rainwater Release Inspection Log (Appendix I)

If there are any questions about the quality of the water present, the OSC, at his/her option, will either:

- Arrange for the water to be pumped out and transported offsite for proper treatment and disposal
- Allow the water to evaporate and, if appropriate, take corrective action to clean up the residual contamination.

Only personnel who have received Spill-Response Training in accordance with Chapter 5 of this SPCC Plan can discharge water from containment areas.

5.2 Testing

If applicable, all alarms (including interstitial monitoring, high and low level and overfill) must be tested monthly and all electronic or mechanical gauges used for determining tank volume (ground–level tape gauges, clock face gauges, etc.), shall be calibrated annually, per manufacturer instructions. These calibrations shall be documented and maintained (Appendix J).

Annual inspections for all steel ASTs greater than 660 gallons shall be conducted in accordance with STI SP001, Standard for the Inspection of Aboveground Storage Tanks, or API Standard 653, Tank Inspection, Repair, Alteration, and Reconstruction, whichever is applicable. Leak

testing, if required, shall be performed and documented according to the requirements of the standard being followed.

5.3 Record Keeping

Registration records must be kept for the life of the tank. The following records must be maintained for at least five years:

- Installation or upgrade permits;
- Records of status changes;
- Repairs:
- Plan review records (Appendix E); and
- Spill event or free product removal records (Appendix H);

The following records must be maintained by the Environmental Manager for a period of three years:

- Annual inspection records (Appendix K);
- Monthly inspection records (Appendix F);

The following records must be maintained by the Environmental Manager for a period of one year:

- The most recent piping precision test results, if applicable;
- Product inventory records. These must be kept daily for motor fuel dispensing, for ASTs which rest on earthen materials and all ASTs connected to pressurized underground piping which does not meet applicable release detection requirements (Appendix G);
- Ullage documentation must be kept unless spill and overfill protection equipment that will automatically stop the delivery of liquid to the tank or sound an audible alarm that can be heard by the delivery operator exists. Ullage must still be determined by the delivery operator prior to delivery (Appendix G);
- Training records (Appendix L); and
- Annual electronic/manual tank gauge calibration records (Appendix J).

The OPS will request inspection and ullage documents on a yearly basis for registered tanks at this facility.

6.0 Responsibilities and Required Training

This section details personnel responsibilities to prevent and respond to spills.

DFC Environmental Manager

- Is accountable for oil discharge prevention and implementing the SPCC Plan
- Publishes procedures needed for implementing this SPCC Plan
- · Coordinates all required training and ensures that all required personnel receive training
- Monitors property managers as needed to ensure they continually inspect the petroleum storage areas under their control and follow effective pollution abatement procedures
- Ensures that site-specific spill contingency plans are posted in prominent locations at potentially significant spill sites
- Ensures that employees know where spill-response equipment is located
- Instructs employees to only clean up a spill if they have training, sufficient equipment, and specific written instructions
- · Maintains all records related to this document
- Evaluates system changes to determine if they affect the SPCC Plan
- Conducts inspections
- Reviews this plan when amendments are required or at least once every five years
- Establishes and implements spill prevention and control procedures
- Performs internal response reporting and ensures external reporting in the event of a spill
- Uses authority to immediately access GSA funding to initiate cleanup activities
- If the spill is reportable, completes the Release Report Form
- Makes required notifications and reports to state and Federal agencies within 24 hours: for example, the NRC, EPA, CDPHE, and LEPC
- · Maintains incident log
- Serves as liaison to Federal, state, and local regulatory agencies regarding waste management issues
- Ensures that integrity testing of ASTs is performed in accordance with applicable state and Federal standards
- Ensures containers are replaced or tested when integrity is questionable

Principal Emergency Contact

- · Notifies local law enforcement and medical authorities if needed
- Coordinates with the GSA EPG Environmental Specialist for necessary response equipment and supplies
- Requests assistance from other response agencies as needed
- Activates internal alarms and hazard communication systems to notify all facility personnel of an emergency
- Mobilizes the SRT and directs its actions
- Identifies the character, exact source, amount, and extent of the release, as well as other items needed for notification
- Performs external reporting in the event of a spill

- Assesses the possible hazards to human health and the environment due to the release, including both direct and indirect effects
- Assesses the substance released and implements prompt actions to contain and remove it
- Keeps local health officials informed of the situation
- Directs cleanup activities for small spills
- Evaluates spill reports and directs and coordinates control and cleanup efforts at the scene of a spill

Spill Response Team (SRT)

- The SRT (Table 2), which acts as an incident response team, performing functions as directed by the On-Scene Coordinator (OSC) to contain, control, and clean up a spill. SRT personnel will respond to a spill in a defensive manner and will seek the assistance of the FPS/OSC and the West Metro Fire Protection District for emergency releases.
- The DFC currently does not have a fire response team. In the event of a fire, personnel closest to the fire will contain it with available extinguishers until evacuation is complete. Personnel will then assist the OSC/FPS and/or the West Metro Fire Protection District. The GSA has an intergovernmental agreement with the West Metro Fire Protection District which operates the Jefferson County Hazardous Materials Team (JCHMT) out of Station 5. GSA Hazardous Material Team personnel (Table 2) are authorized to utilize JCHMT services.
- The West Metro Fire Protection District responds to all emergency releases and, if necessary, assists FPS personnel to contain the spill. If required, the West Metro Fire Protection District assumes control of the situation and performs containment procedures. Mitigation is performed by West Metro Fire Protection District personnel or by a private contractor.

Building Managers/Property Managers

- Periodically inspects the petroleum storage areas under their control
- Follows effective pollution abatement procedures
- Posts site-specific spill contingency plans at potentially significant spill sites under their control
- Ensures that integrity testing of ASTs (including diesel generator ASTs) is performed in accordance with applicable state and Federal standards
- Ensures containers are replaced or tested when integrity is questionable
- Ensures generators and other oil-storage equipment under their control are properly maintained

Personnel Training

HAZWOPER Training

All SRT attend initial and refresher Hazardous Waste Operations and Emergency Response (HAZWOPER) training courses. The 40-hour initial HAZWOPER training applies to five distinct groups of employers and their employees, including any employees who are exposed or potentially exposed to hazardous substances, including hazardous waste, and who are engaged in one of the following operations as specified by 29 CFR 1910.120(a)(1)(i-v) and 1926.65(a)(1)(i-v):

- Clean-up operations that are conducted at uncontrolled hazardous waste sites;
- Corrective actions involving clean-up operations at sites covered by the Resource Conservation and Recovery Act of 1976 (RCRA) as amended;
- Voluntary clean-up operations at sites recognized by Federal, State, Local, or other governmental body as uncontrolled hazardous waste sites;
- Operations involving hazardous wastes that are conducted at treatment, storage, and disposal facilities regulated by 40 CFR Parts 264 and 265 pursuant to RCRA, or by agencies under agreement with U.S. EPA to implement RCRA regulations; and
- Emergency response operations for releases of, or substantial threats of release of, hazardous substances regardless of the location of the hazard.

Spill-Response Training

GSA employees engaged in the handling of oil are trained in the safe handling of oil, and the operation of equipment, and are aware of the requirements and purpose of this SPCC Plan. Training sessions are conducted on a yearly basis. The Environmental Manager is responsible for properly instructing personnel in the operation and maintenance of equipment to prevent the discharge of oil and applicable pollution control laws, rules and regulations. All personnel and contractors who are required to receive this training must sign off on a training log sheet at the training session (Appendix L). All oil-handling personnel must be trained in:

- Understand the facility operating procedures and the ability to apply them;
- Know how to operate safety equipment used at the facility;
- The operation and maintenance of equipment to prevent discharges;
- Discharge procedure protocols;
- The applicable pollution control laws and regulations;
- The contents of the facility SPCC plan;
- Know where spill response materials are stored and their proper application;
- Spill reporting procedures;
- Understand the fueling system; and
- Know the location of the emergency shut off valves and how to operate.

In addition, employees involved in oil delivery operations must also demonstrate the following:

- Ability to identify petroleum product by color;
- Know the storage capacity of the on-Site tanks;
- · Ability to gauge tanks and convert inches of product to gallons; and
- Know the location and purpose of all valves, disconnect switches and alarms.

TABLES

Table 1 Summary of ASTs

way-	1 +	Contac	Contact Information																		5	opin miorinano	Idion		,	Gr.3 Data	, a	Notes	Inspe	nspection
DO TO	Agency Agency	Agency Contact Name	GSA Contact	GSA Responsible Phone Park Contect	sable General	Building ral Number act Location	Building Name Loca Location Desc	Location Capacity Description (qallons)	city (Material	AST Type	AST Material Piping	Leak Gauge/	Shutoff Sat 90%	econdary ontainment Security	los	netall Date AST Use	Owner	Emergency Shutoff Location	Permitted?	Spill Kit Spill Location History	Drainage ny Distance	Drainage Direction	Nearost Receptor	Rate of Potential Flow to Impact (gpm) Drainage	a nettime	lat	lon		Frequency	Type
	1	E S	Janua Perdono	03- 26- 936 Patrick Haze	976	C00624AA	810 near	52	1800 Diesel		Steel NA.	,	y 100%	Doubtewalled, Gate looke 100% (socked, tue		Emergency 2010 Generalor	nsas	In Building 810	19083-1	in brick endosure No	50 feel	North	Mcintyre Gulch	c1 to variable Y	2011-04-0571434	2512 39,7144	105.125047	2011-04-05/14/4/2-512 39,7144(5) -105,1250/47 Has fame alarm on generalor	erator	
			Jannie Perdomo		926	C006248A	to the south. 810 near door S1		10000 Diesel		Steel		Y 100%	Outlewilled, locked als 100% outside wa	Gale locked, Ill port locked, alorms on outside well	Emergency 2007 Generator	NSDA	In generator housing	18285-1	in brick endosure No	75 feet	Southerst	drainage olton	c1 to variable Y	2011-04-05714-42-512	2512 39.711703	105.123714	-105.123714 South of Building 810		+
						4450000	StD to the		1470 Diesek	Refly Tank	Steel		y 2259	tewatled, Gate locke gations, locked		Emergency 2007 Generator	USDA	in generator housing	18285-3	in brick endosure. No	. 75 feet	South	drainage cilich	<1 to	2011-04-05/14/42-512 39/711675	2512 39.7116		-105,123685 South of Building 810		-
	183	1680	Marc Baca	03- 25- 073 Marc Baca	5		Joppa 75 te		575 Garoine	37	1000	z	Steel open, M gallon	Steel box, open, 600 gallona porimiter security	eauly	Refuel	GSA	none	MR	92 Z	230 feet	Sputhess	Montyre Gulth	c110 variable Y	2011-04-05714-42-512 39.717922	2512 397179		Closed, need to permanently close per regulations (State & -105 11121 EPA)	tentry tate &	4
		202912-002	John	236- 8000 8000 Mark Boos	8	COGGZVA	7514	75 feet to the	375 Diesel	AST	Siee None	Y-visual port	z	Steel box - endosed, 400 Fil port, dispenser gallons (ocked	ispenser	Refuel	VS 50	on lank by padlodk	E E	lone	280 fest	South	Montyre Gulch	<110 variable Y	2011-04-05714:42-512	2512 39,717891		-105,111285 East of Building 2		-
					, ,	Announce	e be	adjacent to	O C	Refly Tark	None		>	Doublewalled, Camera, Il	drawle	Emergency 2010 Generalor	ş	n housing	18900-1	None None	unsure until constructio n comprete			<116 varable Y	2011-04-05714:42-512	2512 38,723944	-105112503	hillo level alarms, overiff bucket rupture alarm, electrorie monitoring, piping contained in generator housing, e-shuloif in gen housing	I bucket, ined in utail in	
		736 275 276				C006274A	nare count	northeest courtyard, near door E4	500 Greense	Gresselten	4	Z .	N	Locked Building		Grease frap	*55	Not	N.S.	None	70 feet	East northeast then Northwest along Sth	Storm crain	<1 to variable Y	2011-04-05714-42-512	2512 39722968	105 123261	Connected to sewer, any split scenario is during cleanaut or full back up of sewer	y spill	
								northeest countyard,			yeihes	, ž			-	1	***	Not	2	None	70 feet		storm eran	c1 lo	2011-04-06/14:17:202	7207 39.717057	-105.119009	Connected to sawer, only spill scenario is during chemoul or fluid back up of sewer.	ny spill out or	
		Petrick Higge	Paint 1926	303- 226-		200			8		Shellion seed and	44,000	COORT SEE		419	Emergency 2005 Generator	9 0	in generator housing	2		330 feet		mole deap	of to varable	2011-01-06/11/17/22/2		.105.1178	connull everifibuded, no day lank for generalor, dip dioc is kepi in lanc, generalor gets run weeky, lank filed only once in 4 3 years.	no day slock is gets run noce in 4	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		and Dreiner			COCCIONA			800 Desc	*		111000	N Double	2	-	Emergency 2002 Generator	778	in rousing	z	None No	25 feet		storm drain	c1 to variable Y	2011-04-06714-17:202		-105 1175	-105 117579 (ntertition monitor		
		303-236-6416	Jack Portinen	303. 236. Jenniler 2977 Martinez		CO0530AA	to the 53 near	to the south.	800 Diesel			>	M Doubt	_	-	Emergency 2006 Generator	W.	In housing	z	None No	25 feet	West	storm drain	<1 to vanable Y	2011-04-06714-17-202	7.202 39.717995	-105 119532			+
		7				C00527AA	10 OC	to the south,	100 Deset	AST	Steel Steel	z	z	Locked gate		1955 Phone systems	ms OSA	None	MR	None	400 feet	East hen south	storm drain	<1 to variable Y	2011-04-06114 17.202	7,202 39,716342	.105 117523			-
	S dist		Jeck Portinen		,,,,,,	COUSSOA	S S S S S S S S S S S S S S S S S S S	door door	250 Denei	Concrete value Steel	Slepi	>	>	Enclosure locked		Emergency 1998 Generalor	MMS/FPS	Manual valves	£	In endosure No	60 feet	South	Morm drain	<1 to	2011.04.06114.17.202	20.719799		Manuel shuloff velves; in bride endocure. NS pping leads from ASTs into Bisg 63 to 2 Egs -105 118016 each with 20 gel day tank.	n bridk ads from Egs	
	40 MMS/FPS Terry	Terry Danogr 303-235-5243	Jack Pontinen	235- Jernifer 2977 Marchez		COCSSDAA	10 P	r door	250 Desei	Concrete veuit	Steel Steel	3-	×	Enciosure locked		Emergency 1998 Cenerator	MMS/FPS	Manual	ž	In endosure No	364, 09	South	storm drain	<1 to verlable Y	2011-04-06714 17:202	7.202 39.727953	105 11645			-
1			Jack Pontinen			COCS30AA	neal 63 W11	r door	250 Diesel			,	>	Encosum locked		Emergency 1998 Generator	MMSFPS	Manual	ž.	in endosure No	90 (cer	South	storm drain	<1 to verlable Y	2011-04-06714:17:202	7.202 30.722476	901311601- 921			
		5				COMMON	mon mon mon	in the normeast corner, near 53 done F11	500 Diesel	Bely tank	No.	8	2	Locked room	8	Emergency Generalor			ž	None	90 (66	Norteest	storm drain	< 1 to veriable Y	2011-04-06714-17-202	7.202 39.715893	393 -105.111266	Inside a tooked room in Building -105.111269 53	Building	
		000000000000000000000000000000000000000		236-	- de	2000	900	to the east.	SOO Classed	Rely tank	Stael		2	Exterior do	locked,	Emergency 2001 Generator	FPA	in housing	18013-1	Adjacent to cenerator No	40 feet	H B	storm drain	41 to ventable Y		39.721016	105 111531			
	Ι.					400	d of the	to he east	On Cheese	apin toni	2		e de d			Energency 2009 Generator		. In housing	ž	Adjacent to generator No	150 feet	15	storm drain	v 1 to variable Y				Cylinder storage in endocure- specify norflammables only. PVC pipe sticking out of the ground-what is It?	only.	
				-		9000	2008	southeest,	50	Dely tenk		>	2			Emergency generator for clevator fire panel	900	- Nov	¥	None No				< 1 to variable	2011-06-27716-03:332	28.716303	-105.12565			
	don	John 303-236-8000			4	9000	2 3	to the east,	NO Diesel	Belly tank		>	- Pool		Exterior door locked	Emergency generator for lab fridge/lighting	usos	in housing	AR.	Adjacent shed No	100 feet	West?	drain to detention pond, then to storm drain	4 1 to variable Y	2011-04-06714-17.202	7.202 39.722787	787 -105 123851			

Table 2
Emergency Assistance Contacts

Spill Respon	nse Team M	embers	V
Title	Name	Work Phone	Alternate Phone
OSC/GSA	Alan Antonio	303-236-2366	720-284-9598
Alternate OSC/GSA EPG	John Kleinschmidt	303-236-2858	303-868-0795
SRT Member/ GSA EPG	Michael Gasser	303-236-2791	303-435-5848
SRT Member/ GSA Industrial Hygienist	Tom Record	303-236-2549	303-349-1140
Public Relations	Sally Mayberry	303-236-2583	Not Applicable
Spill Respon	nse Team M	embers	2
Title	Name	Work Phone	Alternate Phone
OSC/FPS	Alan Antonio	303-236-2366	720-284-9598
Alternate OSC/GSA EPG	John Kleinschmidt	303-236-2858	303-868-0795
Contracting Officer	Robert Collins	303-236-2699	303-906-5543
Property Manager	Kristi Leinen	303-236-4616	303-349-1637
Agencies			
Agency	Address		Phone
Federal Protective Services	DFC Building 41		303-236-2911
GSA Industrial Hygienist	DFC Building 41		303-236-2549
GSA EPG Fax	DFC Building 41		303-2365328
Public Relations Office	DFC Building 41		303-236-2583
Lakewood Police Department	445 South Allison Wa	y, Lakewood, CO	303-987-7111
Jefferson County Sheriff	200 Jefferson County	Parkway, Golden	303-277-0211

Table 2 (Continued) Emergency Assistance Contacts


West Metro Fire Protection District	447 South Allison Way, Lakewood	303-989-4307
St. Anthony Hospital	11600West 2 nd Place, Lakewood	720-321-0000
Metro Wastewater Management District	888 East 50 th Avenue, Denver	303-286-3000
Jefferson County Health Department	260 South Kipling Street, Lakewood	303-239-7162


Notes			No.				will be comoused near unidae construction	will be removed area under construction	area under construction			currently out of service, not any for permanent location	area under construction													The same through the same and same and same the same to the same through t																								completely encolosed by concrete and cinderblock walls -	completely encolosed by concrete and cinderblock walls -	drain in 5 wall													- above offices -	above offices	the second forms and the second forms are second forms and the second forms and the second forms and the second forms and the second forms are second forms	interior transformers with containment have opening in lip near wall - need to plus these	interior transformers with containment have opening in lip	near wall - need to plug these	interior transformers with containment have opening in lip near wall - need to plug these	
M Parameter	Agricultural Ditch	Agricultural Ditch	Agricultural Ditch	Agricultural Ditch	Agricultural Ditch	East Detention Pond	inframe	inknown	unknown	East Detention Pond	Melnture Gulch	manufacture of the	unknown	none	one	storm drain	storm drain	storm drain	storm drain	storm drain	Agricultural Ditch	The state of the state of	Agricultural Ditch	storm drain	Agricultural Ditton	form drain	storm drain	Con Con	9000	Tours deals	storm drain		storm drain		torm drain		storm drain .	Acres deals	storm drain	storm drain	storm drain	storm drain	torm drain	torm drain	storm drain	none	none	storm drain	storm drain	closm deals	ingin man	storm drain	storm drain	storm drain	lone	torm drain	ACTUAL CLAIM	West Detention Pond	storm drain	none	storm drain	storm drain	storm drain	cooling tower	поле	one	tone	9000		none	none	
o contraction		N to ditch, ditch flows SSE to McIntyre Gulch		4	ntainment	S to east detention pond	a to east determine point	north transformer sits in a degreesion	10 36	into east detention bond			drains to north.	escape beyond walls			nd Street	to NE to 2nd Street			NE to ditch, ditch flows SSE to McIntyre Gulch		NE to ditch, ditch flows SSE to McIntyre Guich	Est to storm drain	And Desired Barbon Arrive		to NF to 5425D storm drain	~ 40,		T	CM to My to curb and guiter to chi Street	0 4 3		nt, then to E to	parking lot then to 2nd Street		_	NNW out vent slots to drive to 5th Street curb and	to S to storm deals by dock	lot		ostreet			to Eto parking lot			ng lot storm drains		s treat the all less is solve for the street	T	to 5, through drain holes in wall to 6th Street		sel to parking lot		desired in Concrete waiss		out door to SE then to E to West detention pand				ock		poling tower		3" lip 20" x 40" room	3" lip 20' x 40' room	3" lip 20' x 40' room		3" lip 18" x 30" room	3" lip 18" x 30" room	
1	gravel	gravel	gravel	ped	pad	ped	por pro jones	graver pau mount	pad, gravel	pad. dirt	ped		unknown	pad: prave	pad, grave	pad, dirt	pad, gravel	pad, gravel	pad, gravel	pad, gravel	pad, dirt, gravel	1	pad, dirt	pag, gravel	pap, grave	part State	nad cravel	and Street	concrete	and in the second	concrate	200000	nari erave		concrete		concrete	Transport Contract	nad asphalt	pad, gravel	pad. grass	pad. asphalt	pad, gravel	pad, gravel	pad, gravel	ped	ped	pad, asphalt	pad, asphalt	Per	nod	ped	pad, grass	pad, grass	pad grave.	pad, grave.	and oned	gravel	pad, mulch	pad, dirt	pad	ped	pad, grass	pad, grass	concrete	concrete	concrete	concrete		concrete	concrete	
Znd containm	z	z	z	>-		2 2	2 2	2	z	Z	2		2	>	>	z	z	z	z	z	z		2 :	2 :	2 2	. 2	2	. >	,		2 2		>		>		>	2	. 2	z	z	z	z	z	z	>	>	z	z	>		*	z	2 >	,	2	2	z	2	>-	z	z	z	z	>	*	>	>		>	>	
product (type	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineraloi	mineraloil	mineraloil	mineraloil	mineraloil		nineraloil	mineraloil	mineral oil	mineraloil	mineral oil	grape seed oil	mineral oil	mineral oil	nineral oil	100	mineraloil	mineralon	mineral oil	mineraloil	mineraloi	nineral oil	mineral oil	mineral off	mineral oil		mineraloil		mineral oil		grape seed oil	all more lived	mineraloil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	nioecal oil	5 9 9 9 9	mineral oil	mineral oil	mineraloi	mineral or	mineraloil	io is and	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil	mineral oil		mineral oil	mineral oil	
capacity	2900	4070	31	3645	3645	155	1		374	285	155	200	86	684	684			180	568	197	273	000	230	T	T				197	407	402		188		188		180	0	163	31	169	I			460		493	229		290	200		166		T	I		220	251			185				233	233	233		233	233	
Description	Oil type G.E. 115 kV - 7970/13800 Volt 22,400 kVa, "X" circuit	Oll type 6.E. 115 kV-7970/13800 Volt 22,400 kVa, "Y" circuit	Oil type Cooper trans. 13.8kV-120/240 25 kVa, "Y" circuit	DOS - new transformer - not assigned if yet	DOS - new transformer - not assigned # yet	Oil type line material 13.8 kV-120/208 300 kVa	Oil type Aprila Halbidille Service 13:6 AV-2777-60 300 AVA	Cal type repetite the Local No. 277 / 480 250 NV.	Oil type Cooper 13.8 kV277/480 1000 kVa	Oil type Vantran 13.8 kV-120/208 225 kVa	Oil type Vantran 19.8 kV-120/208 112.5 kVa		Oil type G.E. 13.8 KV-120-208 112.5 kVa	Oil type Cooper 13.8 kV-277/480 2500 kVa	Oil type Cooper 13.8 kV-277/480 2500 kVa	Oil type Westinghouse 13.8 kV-120-208 750 kVa	Oil type McGraw Edison 13.8 kV-277/480 2500 kVa	Oil type cooper 13.8 kV-200 500 kVa solar	Oil type McGraw Edison 13.8 kV-277/480 2500 kVa	Oil type Westinghouse 13.8 kV-277-480 1500 kVs	Oil type Alpha Transformer Service 13.8 kV-277/480 1000 kVa		Oil type G.E. 13.8 kV-120/208 500 kVa	Oil type Westinghouse 13.8 kV-277/480 750 kVa	Cil type C.c. 13:6 KV-120/206 300 KVd	Cil type G. F. 12 R PV.130/208 235 PVa	Oil type Vantrag 13 8 kV-272/480 225 kVa	Oil type Martinehouse 13 a M.2300 1500 LV.	Oil type Westinghouse 13 8 PV-277/680 1500 bVs	Oil type regarding to the participation of the part	Off type Galteau 12 8 byt.277/480 3500 byts 'v" struck'		Oil type Westinghouse 13.8 kV-277/480 1500 kVa		Oil type Westinghouse 13.8 kV-277/480 1500 kVa		Oil type cooper 13.8 kV-200 500 kV3 solar	Cit and Martinsham 13 8 505 377/8 80 1500 50/2	Oil type Westinghouse 13 8 PV-277/020 750 PV-	Oil type Cooper 13.8 kV 120-240 25 kVa Y-circuit	Oil type Allis Chalmers 13.8 kV-120/208 300 kVa	Oil type Vantran 13.8 kV-277/480 500 kVa	Oil type RTE 13.8 kV-277/480 1000 kVa Transformer A	Oil type RTE 13.8 kV-277/480 1000 kVa Transformer B	Oil type Westinghouse 13.8 kV-277/480 1000 kVa	Oil type MGM 13.8 kV-277/480 2500 kVa	Oil type MGM 13.8 kV-277/480 2500 kVa	Oil type RTE 13.8 kV-277/480 500 kVa	Oil type RTE 13:8 kV-277/480 500 kVa	Oil tune G F 13 8 KV-277/480 500 kVs Messacenter	Date of the control o	Oil type Westinghouse 13.8 kV-277/480 500 kVa Mega-center	Oil type Balteau 13.8 kV-120/208 500 kVa	Oil type Cooper 13.2 kV-277/480 SOO kVa	Citype for 15.0 KV-277/400 500 KV4 X-Citylin	Oil type COD 14 & kV-130/208 75 kVa v.circuit	On type 3-th 13:0 kV-12:0/200 / 5 kVa Y-theur	Oil type Fayetteville 13.8 kV-277-480 500KVa Y-circuit	Oil type RTE 13.8 kV-277/480 500 kVa	Oil type Howard Ind. 13.2 kV-277/480 12.5 kVa	Oil type Cutler Hammer 13.8 kV-277/480 3000 kVa	Oil type Balteau 13.8 kV-277-480 500 kVa X-circuit	Oil type G.E. 13.8 kV-120/208 300 kVa	Oil type RTE 13.8 kV-277/480 750 kVa	Oil type RTE 13.8 kV-277/480 750 kVa "x" feeder	Oil type RTE 13.8 kV-277/480 500 kVa "V" feeder	Oil type RTE 13.8 kV-277/480 500 kVa "Y" feeder	Oil type RTE 13.8 kV-277/480 500 kVa "x: feeder		Oil type RTE 13.8 kV-277/480 500 y-circuit	Oil type RTE 13.8 kV-277/480 500 kVa x-circuit	
and formalism	Main Substation, North end of Fed Center	Main Substation, North end of Fed Center	Main Substation, North end of Fed Center	Main Substation, North end of Fed Center	Main Substation, North end of Fed Center	South side of building 16 South side of building 16	North side of building 7	North side of building 2	New pump house	North side of building 13	North side of building 1	-	North side of Gate #2, Center Street	Building 25 north of door E-8	Building 25 south of door E-12	South side of building 21	Building 20 by door E-8	Building 20 door E-9	Building 20 by door E-12	Building 20 by door E-12	East side of building 47	The state of the s	Building 48 by door E-4	Building 45 at 600f 5-7	Cort side of hullsing 41	Reilding 40 at door W.4 Neide	Building 40 at door W-4 N side	Building 41 inside door M.21	Ruilding 41 inside door W-21	Morthage ride of heilding 67	Northeast side of hullding 67	- Amount	Building 56 at door E-10		Building 56 at door E-10		Building 56 door E-11	Deall-disease Co. at dealer E. 17	Building S6 at door S.4	South of building 56 on west side of street	Southeast corner of building 55	South side of building 54	Building 53 at door E-10	Building 53 at door E-10	Building 53 at door E-19	Building 53 at door E-12	Building 53 at door E-12	South side of building 50	South side of building 50	Building 53 at door We16	OT-A DOOR OF SHEER	Building 53 at door W-16	South side of building 64	North side Building 85A	South side of building 85	South of building 84	to Strong of the strong of	South side of building 74A	West of building 70 MH ME-8 8th street	East side of building 94	East side Building 95	Building 710 southwest corner	Building 720 southwest corner	South side of building 710	Building 810 at door W3, substation no. 5	Building 810 at door W3, substation no. 5	Building 810 at door E6, substation no. 4	Building 810 at door E6, substation no. 4	To the state of th	Building 810 at door N4, substation no. 1	Building 810 at door N4, substation no. 1	
- I have		96 1	19719 1	1		201	1 0	1 (19	1 1255	45 1	1 28		-67M	1915 2	1916 2	0101 2	5-1-2 2	3870 2	1.1-1 2	-0101 2	202 2		LISAA 2		2 2010	-	44 2	1	0101	1	100	+	-0102	L	-0103 3		8868 3	2010	-	5778 3	3	88 3	461 3	460 3	3252 3	31-1 3	31-2 3	638 3	639 3	3	-		58 3	-	+	29.0	+	_	756 3		188 5	132 4	OTYF 4	576 4	9075 4	-	443	920		442 4	073 4	
Serie! Member	1 12521.	2 1252796	8 CP05050.		4	2 86507201	+	+	-	H	8677558	ł	H422284-67M	⊦	9 0126001	0 PAT3401-0101	4 C-45613-1-2	1050008870			 9 86G07202		C-169769173AA	-	-	+	+	T	+	+	3 PPD-0195	+	S PAT3371-0102	+	A PAT3371-0103	_	5 1050008868	C DATESTA OLON	+	+	╀	L	H	3 756001460	+	⊦	H		-	7219197	Ļ	80	H	7 0237009512	+	3 796001794	+	9 92104-01		Н		- 1		8 886006576			2 886005443	886006076	╀	8 886005442	9 886006073	
i cad x	3106743.327 [11-6-32-00]	3106717.391 [1-E-32-002	- 3106715.488 L1-E-32-06.	3106695.994 New 1	3100684.753	3109228.435 [1-E32-011	2100128 727	3109142.4	3108936,443 L1-E-32-079		3109333.803 [1-£32-017		3109325.016 [11-E-32-009	3107841.668 12-5-32-068	3107956.977 L2-E-32-06	3108178.349 L2-E-32-010	3108594,733 L2-E-32-01	2 3108591.545 L2-32-074	3108702.395 L2-E-32-01	3108700.143 L2-E-32-016	3107244.87 [2-6-32-019	010 500 5100 5100 5100	3106816.077 12-E32-018	310/130./8/12:5-32-029	2107270 170 17 5 17 5 17 5	3107074 571 12.E.32.040	3107924.012 2-F-32-03k	3107616 777 13-5-37-038	3107628 339 12, 532,037	3105623 850 13 5 32 03	1688930-21 0109824 83 H-0-5-32-022	70	3106479.749113-F-32-025		3106474.698 L3-E-32-024		3106512.757 L3-E-32-075	350,00,000,000		3106872.502		3107017.751 13-E-32-031		3107197,156 L3-E-32-033		3107353.947	3107337.818	3107587,648		2107091 331 13.F. 30.045		3107084.91		3105540.143	3105263.270		2102002016	3105848.112 L3-E-32-049		3105626.265 15-E-32-05	3105279.495 L5-E-32-066	3106751.679 L4-E-32-046	3106568.987 L4-E-32-04	7 3106804.903 L4-E-32-048	3105487.514 L4-E-32-06	3105507,962 14-E-37-06	3106049.14 L4-E-32-062	3106098.13 1.4-5-32-063		3105572.787 L4-E-32-058	3105581.893 L4-E-32-059	
000	1688889.94	1688903.678	1588888.03	1688908.324	1688905 363	1687722.032	1600035 507	1688831 595	1688778.262	1686843.147	1685888.022		1688423.301		1688249.55	1687719.75	1687176.20	1687198.43	1686996.35		1688419.222	4600376 363	1688376.263	100/633.390	100/07/100	158646A 498	1686463.767	1686726 565		1666369 317	1688370 318	2000	1688217.495		1688214.56		1688194.319	1,007007 63	1687783 52	1687798.403	1687559.479		1686987.818	1686985.62	1686827.721	1686760.431	1686782.948	1685974.957	1685959.331	1686595 408	700000000000000000000000000000000000000	1686583,725	1686390.009	1687283.253	1696050 734	1686715,657	1000110.001	1686754.515	1586121.073	1685911.771	1686092.839	1684533.319	1684558.419	1684318,98	1584494.92	1684516.498	1684679.38	1684670.112		1585237.288	1685212.191	
SMC	-105.120525	\perp			105.120733	105.111708	10011301	105,111997	100		-105.111361		105,111354	105.116627	-105.11622	105,115441	105,113969	-105.11398	105,113589	\perp	-105.118749	100 130071	105.120274	105 110553	105.11.932	105 116362	-105 116364	105 117454	105 117411	106113906	105 123708	2000	-105.121472	-	-105.12149	_	-105.121355	20001301	105 120658	-105,120082	105.119745	105,119572	-105.11893	-105.11894	-105,11847	105.118386	105.118443	-105.117567	-105.117536	-105 119322	_	-105,119345	-105.120212	-105.124826	406 406740	105 126461	100011001	-105,123739	-105.122481		-105.12577	-105.12056	105.121209	105.120374	105.125054		-105.123055	-105.122881		-105.12474	-105.124708	
TABLE	39.7242	516 39.724238	517 39,724195	518 39.724251	519 39.724243	520 39.720965	513 30 TAMOS	523 39 724017	524 39,723868				527 39,722889	528 39.722964	529 39.722428	530 39.720971	531 39.719474	532 39.719535	533 39.718979	534 39.71898	535 39.772902	OSCOLL OF SES	536 39.722789	530 30 731410	530 30.710750	5.41 39 7175.38	542 39 717526	5.43 30 718751	544 30 71827	E46 30 733701	A87557 96 343	210 2011	547 39 727357		548 39.722349		549 39.722293	CEO 30 731643	541 39 721163	552 39,721202	553 39,720545	554 39,72003	555 39.718973	556 39.718967	557 39.718532	558 39.718347	559 39.718409	560 39.716188	39.716145	79217807		563 39.717865	564 39.717336 -105.120212	565 39.719803	500 39.710933	568 39 71875	200 23.71073	569 39.718348	39.716605	571 39.716037		39.71224	39.712311	575 39.711651	39.712149	39,712208	578 39.722549	579 39.712623		580 39.714186	581 39.714117	


Table 3 Summary of Transformers

										2nd				
								capacity	product (type containm	containm	Manne	and treated	SW Recentor	
IDENT LAT	LONG	Y PROI	X PROI ID#	Serial Number Land Area Location	Land Area	Cocation	Description	(gallons)	01010	au a	MIDOM			
ı														interior transformers with containment have opening in lip
00012 00 000			TT0000000 050 CC 3 k 00k 3T0201C Con 3513034 003511 301 100511 00 1005	220000000	*	6 on political PM and of the Brighting	Oil rone RTF 13 8 kV-2777/480 500 kVa x-circuit	233	mineral oil	>	concrete	3" lip 12' x 35' room	auou	near wall - need to plug these
287 777233	FUCD217001- /4	1003100.392	3102012:403 [4-2-32-000]	GOUNNAMA		7.000								interior transformers with containment have opening in lip
200	Contraction of	1000	190 cc a v cra racacre	900000444		C on addition B.O and the Office Addition B.	Oil tone RTE 13 8 by 277/480 S00 by a velecity	233	mineral oil	^	concrete	3" lip 12' x 35' room	none	near wall - need to plug these
283 39.71404	-105.126563	1003177.903	283 39.714029 -103.126383 1883177.963 3103091.343 CH-C-3C-3C-3C-3C-3C-3C-3C-3C-3C-3C-3C-3C-3	***************************************		The state of the s								
OFFICE OF SOS		001 3011000	SECONDE S. M. P. S. A. CONSTRUCTOR	1050001430	,	o Harris and Comment of the Comment	Off toma Commune 13.8 MA200 1000 Ma colar	524	prane seed oil	Z	concrete	on dock brick wall with holes, drain to E then to N	McIntyre Guich	
284 39.71274	7 TO2.123142	1084700,098	384 39.717/24 -103.123142 1084/00.396 3100024.331 04-5-32-070		,	Dallung 610 agos L-9	and the control of th		0					
505 30 71410	1 105 12/1309	TO3 05 C2 8 A T	770-75-3-4 G99 895-301F TO3 8552891 905051 201- 101017 05 393	1059001429	4	Building 810 door N-23	Oil type Coopper 13.8 kV-200 1000 kVa solar	530	grape seed oil	z	concrete	on dock brick wall with holes, drain to E then to N McIntyre Gulch	McIntyre Guich	
207.144	7 105 123023	1685238 004	2001 39:714151 101121-1050 1000-1050 3104030 10114-1-30-078		4	Rullding 810 door N-5	Oil type cooper 13.8 kV-200 500 kVa solar	180	grape seed oil	z	concrete	brick wall 4 goes through to N to guich	McIntyre Guich	
200 2007	4 105.117623	C30 97 10031	25.11447 105.12.005 100505000 10050500 10050500 10050500 10050500 10050500 10050500 100505000 10050500 10050500 10050500 10050500 10050500 10050500 100505000 100505000 100505000 100505000 100505000 100505000 10050500000000	1	-	Fast of main substation at solar park array	Oil type copper 13.8 kV-277/480 500 kVa	596	mineral oil	z	pad, grass	to NE	north ditch	
588 39 72485	9 .105 117877	1689133 175	50 33. 24634 103.117632 1003.121.002 3.107501 11.632.072 0750020692	0750020692	-	East of main substation at solar park array	Oil type cooper 13.8 kV-277/480 500 kVa	596	mineral oil	z	pad, grass	to NE	north ditch	

FIGURES









Legend

Transformer

L4-E-32-048 Tranformer Identification

875 437.5 Feet Resources, Inc.

SITE PLAN TRANSFORMER LOCATIONS

Denver Federal Center West 6th Avenue and Kipling Street Denver, Colorado

Site Location: Denver, Colorado

Path: F:\Open Projects\Fed Center SPCC\Pinyon GIS\Fed Qenter_Transformers_Figure 3.mxd

Job No. 1/11-346-01.6302

Drawn By: MJS

Figure 3

Reviewed By: KRT Revision 0

APPENDIX D

THREATENED AND ENDANGERED SPECIES IN JEFFERSON COUNTY, CO

THREATENED AND ENDANGERED SPECIES IN JEFFERSON COUNTY, CO

COMMON NAME	SCIENTIFIC NAME	THREATENED (T) /ENDANGERED (E)
Bald Eagle	Haliaeetus leucocephalus	Т
Canada Lynx	Lynx canadensis	Т
Colorado Butterfly Plant	Gaura neomexicana ssp. coloradensis	T
Eskimo Curlew	Numenius borealis	E
Mexican Spotted Owl	Strix occidentalis	T
Pallid Sturgeon	Scaphirhynchus albus	Е
Pawnee Montane Skipper	Hesperia leonardus montana	Т
Preble's Meadow Jumping Mouse	Zapus hudsonius preblei	Т
Ute Ladies'-tresses	Spiranthes diluvialis	T